

ROUTINE (PERIODIC) BRIDGE INSPECTION REPORT

NUAAILUA STREAM BRIDGE
BRIDGE NO. 009003600501540
MAUI, HAWAII



For

State of Hawaii
Department of Transportation
Highways Division

Prepared by

Nagamine Okawa Engineers Inc.
1003 Bishop Street
Suite 2025
Honolulu, Hawaii 96813
Telephone: (808) 536-2626

FEBRUARY 2010

STATE OF HAWAII
DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

NBI BRIDGE INSPECTION REPORT

Date of Inspection	<u>2/18/10</u>	Bridge Name	<u>Nuaailua Stream Bridge</u>
Bridge Number	<u>009003600501540</u>	Route No.	<u>360</u>
Number of Spans	<u>1</u>	Highway	<u>Hana Highway</u>
Location: Island	<u>Maui</u>	Milepost	<u>15.39</u>
Feature Intersected	<u>Nuaailua Stream</u>	Substructure	<u>Reinforced Concrete</u>
Bridge Material:	Superstructure <u>Reinforced Concrete</u>		

Condition Rating		Remarks
36	TRAFFIC SAFETY FEATURES	Indicate if feature meets currently acceptable standards. 0 - No 1 - Yes N - Not Applicable
1.	Bridge Railings	0
2.	Transitions	0
3.	Approach Guardrail	0
4.	Approach Guardrail Ends	0
		RM-4 signs are damaged at the Kahului approach.

58	DECK	
1.	Wearing Surface	7
2.	Decks - Structural Condition	6
3.	Curbs	N
4.	Median	N
5.	Sidewalks	N
6.	Parapet	6
7.	Railing	6
8.	Paint	5
9.	Drains	N
10.	Lighting Standards	N
11.	Utilities	N
12.	Joint Leakage	N
13.	Expansion Joints or Devices	N
	Inspector's Condition Rating	6
		2. Downstream half of soffit has efflorescence and dark water stains.
		6. Minor collision damage to upstream parapet.
		8. Paint is faded and weathered on parapet and railing.

59	SUPERSTRUCTURE	
1.	Bearing Devices	N
2.	Stringers	N
3.	Girders, Beams, or Arches	5
4.	Floor Beams and Diaphragms	N
5.	Trusses -General	N
	-Portals	N
	-Bracing	N
6.	Paint	N
7.	Machinery (Moveable Spans)	N
8.	Rivets and/or Bolts	N
9.	Welds - Cracks	N
10.	Rust	N
11.	Timber Decay	N
12.	Concrete Cracking and/or Spalling	5
13.	Collision Damage	7
14.	Deflection Under Load	7
15.	Alignment of Members	6
16.	Vibrations Under Load	6
17.	Flat Slab	N
	Inspector's Condition Rating	6
		3. Hairline crack and delamination on bottom of girder G5 (from upstream) near Hana abutment. Girder G8 has several small spalls with exposed rebar and its upstream face is delaminated throughout. Gunite patches on girders G1 to G3.

Date of Inspection 2/18/10
 Bridge Number 009003600501540

Bridge name Nuaailua Stream Bridge

		Condition Rating	Remarks
60	SUBSTRUCTURE		
1.	Abutment		
	-Wings	6	1a. Wingwalls are covered with vegetation and moss.
	-Backwall/Breastwall	6/6	1b. Honeycombing between girders G6 and G7 (from upstream) and delamination between girders G7 and G8 on backwall of Kahului abutment. Dark water stains on the downstream half of Kahului abutment.
	-Footing	6	
	-Piles	N	
	-Erosion	7	
	-Settlement	7	
2.	Piers or Bents		1c. Abutments bear directly on bedrock. Unsound cement wash patch on upstream / Hana abutment.
	-Caps	N	
	-Column/Wall	N	
	-Footing	N	
	-Piles	N	
	-Scour	N	
	-Settlement	N	
3.	Pile bents	N	
4.	Concrete Cracking and/or Spalling	6	
5.	Steel Corrosion	N	
6.	Timber Decay, etc.	N	
7.	Debris on Seats	7	
8.	Paint	N	
9.	Collision Damage	8	
	Inspector's Condition Rating	6	

61	CHANNEL & CHANNEL PROTECTION		
1.	Channel Scour	6	
2.	Embankment Erosion	6	
3.	Drift	6	
4.	Vegetation	5	4. Heavy vegetation growth in upstream channel.
5.	Channel Change	7	
6.	Fender System	N	
7.	Spur Dikes & Jetties	N	
8.	Rip Rap	N	
9.	Adequacy of Opening	6	
	Inspector's Condition Rating	6	

62	CULVERT & RETAINING WALLS		
1.	Barrel		
	-Concrete	N	
	-Steel	N	
	-Timber	N	
2.	Headwall	N	
3.	Cutoff Wall	N	
4.	Adequacy	N	
5.	Debris	N	
	Inspector's Condition Rating	N	

Date of Inspection 2/18/10 Bridge Name Nuaailua Stream Bridge
Bridge Number 009003600501540

93	CRITICAL FEATURE INSPECTION DATE	Provide date if applicable. If not applicable, indicate with N.
1.	Fracture Critical Details	<u>N</u>
2.	Underwater Inspection	<u>N</u>
3.	Other Special Inspection	<u>N</u>

[If applicable, submit Underwater Inspection Report]




OTHER FEATURES		Y - Yes	N - No	Remarks
1.	Bridge Posted?	<u>Y</u>		Posted Limit = <u>10 Ton weight limit</u>
2.	Signage for Posting Legible/Visible?	<u>N</u>		Load posting sign is located near mile post 0.0 Route 360,
3.	Riding Surface (Roughness) Rating	<u>3</u>		and is used as a notice for all Hana bridges. 3 - Smooth, 2 - Average, 1 - Poor

REPAIRS AND IMPROVEMENTS

- List all work done to this bridge since the last inspection including cost.
a) Repaved A.C. overlay
- Indicate proposed and/or recommended improvements including estimated cost.
a) Install guardrail transitions, approach guardrails, and end treatments to meet current acceptable standards (Cost Est. = \$50,000).
b) Upgrade railing and parapet to meet current acceptable standards (Cost Est. = \$120,000).
c) Repair cracks, delaminations, and spalls in girders (Cost Est. = \$50,000).
d) Clear vegetation from bridge and upstream of channel (Maintenance Item).
e) Repair Kahului approach RM-4 signs (Maintenance Item).
- List any existing temporary conditions.

REMARKS AND RECOMMENDATIONS

- Does this bridge require inspection by Bridge Design Section? Yes - No -
[This should only be addressed by in-house inspectors who are not structural engineers.]
- Remarks: Describe defects. Use sketches, diagrams and/or photographs where possible.

Inspected by:	Name (printed):	Erik-Jon Cabbab / Cody Aihara	Certified Bridge Inspectors
	Signature:		
	Phone Number:	808.536.2626	
Supervised by:	Name (printed):	Dwight M. Okawa, S.E.	Title: V.P./Team Leader
	Signature:		
	Phone Number:	808.536.2626	

STATE OF HAWAII DEPARTMENT OF TRANSPORTATION
PONTIS BRIDGE INSPECTION REPORT

r10/8/07

Date of Inspection <u>2/18/10</u>	Bridge Name <u>Nuaailua Stream Bridge</u>
Bridge Number <u>009003600501540</u>	Route No. <u>360</u>
Number of Spans <u>1</u>	Highway <u>Hana Highway</u>
Location: Island <u>Maui</u>	Feature Intersected <u>Nuaailua Stream</u>

ELEM NO.	ELEMENT DESCRIPTION	ENV. (Note 1)	TOTAL QUANT.	UNIT	ST 1	ST 2	ST 3	ST 4	ST 5
013	DECK OR SLAB (Note 2)	2	735	SF.	735				
110	GIRDERS	2	248	LFT.	89	124	31		
215	ABUTMENTS	2	76	LFT.		76			
*	COLUMNS			EA.					
*	PIER WALL			LFT.					
*	PIER CAPS			LFT.					
301	JOINTS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)	2	42	LFT.		42			
331	BRIDGE RAILING	2	70	LFT.		70			
*	APPROACH SLABS			EA.					
*	BEARINGS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)			EA.					
*	CULVERT			LFT.					
*	SMART FLAG: STEEL FATIGUE			EA.					
*	SMART FLAG: PACK RUST			EA.					
*	SMART FLAG: DECK CRACKING (ON TOP OF DECK ONLY)			EA.					
359	SMART FLAG: SOFFIT OF CONC. DECK OR SLAB (THIS SMART FLAG IS MANDATORY IF DECK OR SLAB HAS AN A.C. OVERLAY).	2	1	EA.		1			
*	SMART FLAG: SETTLEMENT			EA.					
*	SMART FLAG: SCOUR			EA.					
*	SMART FLAG: TRAFFIC IMPACT (TRAFFIC IMPACT TO SUPERSTRUCTURE ONLY)			EA.					
*	SMART FLAG: SECTION LOSS			EA.					
OTHERS:									

COMMENTS:

Note 1: For each element, the inspector shall code the type of environment from the following key:

Env 1: Benign & Low Env: Little or no env. conditions affecting deterioration. Past bridge inspections show that env. has caused little or no deterioration.

Env 2: Moderate: Moderate level of environmental influence or deterioration. Past bridge inspections show that environment has caused some deterioration.

Env 3: Severe: Severe level of environmental influence or deterioration. Past bridge inspections show that environment has caused significant.

Note 2: For DECKS ONLY. All quantity in one ST only. Deck/slab is rated from top of deck/slab only. Use soffit smart flag (elem 359) to rate soffit.

Use these revised Condition States for rating Concrete Decks/Slabs	
CS1	No patched areas, no potholes, no spalls and delams, etc.
CS2	Distressed areas are less than 2% of the total deck area.
CS3	Distressed areas are more than 2% but 10% or less of the total deck area.
CS4	Distressed areas are more than 10% but 25% or less of the total deck area.
CS5	Distressed areas are 25% or more of the total deck area.

Inspector's Name (printed):

Erik-Jon Cabbab / Cody Aihara

Title: Certified Bridge Inspectors

Inspector's Name (signature):

Erik-Jon Cabbab *Cody Aihara*

Inspector's phone number:

808.536.2626

Supervisor's Name (printed):

Dwight M. Okawa, S.E.

Title: V.P. / Team Leader

Supervisor's Name (signature):

Dwight M. Okawa

Geographic and Route Data

(1) State Hawaii
(2) District 20
(3) County Maui
(4) Place 99999
(6) Feature Under NUAAILUA STRM
(7) Facility on HANA HWY
(9) Location 1.18MI W/KEANAE HMSTD RD
(16) Latitude 20° 51' 30.00"
(17) Longitude 156° 09' 48.00"
(98) Border Bridge
(99) Border Bridge Str No
(103) Temporary Str

On and Under Record Data

Route On
(5) Inventory Route 121003602
(10) Min Vert Clr 99.99 M
(11) Kilometerpoint 0024.751
(19) Detour Length 199 km
(20) Toll 3
(26) Func Class 07
(28) Lanes on/under 0200
(29) ADT 1720
(30) Year of ADT 2007
(47) Total Horz Clearance 06.4 M
(100) Defense Hwy 0
(101) Parallel Str N
(102) Direction of Traffic 2
(104) Hwy System 0
(109) Truck Traffic 00%
(110) Natl Truck Network No

General Data

(21) Maintenance Responsibility 01
(22) Owner 01
(31) Design Load 0
(33) Bridge Median 0
(34) Skew 00 deg
(35) Str Flared No
(37) Hist Significance 3
(38) Navigation Control 0
(42) Type of Service 15
(43) Structure Type Main 104
(44) Structure Type Approach 000
(45) No of Span Main 001
(46) No of Approach Spans 0000
(27) Year Built 1911
(106) Year Reconstructed 1940
(107) Deck Str Type 1
(108) Wear Surf/Protv Sys 600
(111) Nav Pier/Abut Protection

Dimensional Data

(32) Approach Rdwy Width 9.4 M
(39) Navigation Vert Clr 000.0 M
(40) Navigation Horz clr 0000.0 M
(48) Max Span Length 0009.1 M
(49) Str Length 00010.7 M
(50) Curb/Sidewalk Width Left 00.0 M
Right 00.0 M
(51) Brg Rdwy Width,curb-curb 006.4 M
(52) Deck Width out-out 008.4 M
(53) Min Vert Clr over 99.99 M
(54) Min Vert Clr under N 00.00 M
(55) Min Lat Underclr R N 00.0 M
(56) Min Lat Underclr L 99.9 M
(112) NBIS Bridge Length Y
(116) Navigation Min Vert Clr M

Proposed Improvements

(75) Type of Work 311
(76) Improvement Length 000171 M
(94) Bridge Improv Cost 1142
(95) Rdwy Improv Cost 0
(96) Total Proj Cost 1800
(97) Year of Cost Est 1999
(114) Future ADT 2400
(115) Year of Future ADT 2027

Condition Rating

(58) Deck 6-5
(59) Superstructure 6
(60) Substructure 6
(61) Channel & Channel Protect 6
(62) Culverts N

Appraisal Rating

(67) Structure Evaluation 4
(68) Deck Geometry 2
(69) Underclrn Vert & Horz N
(71) Waterway Adequacy 5
(72) Approach Rdwy Alignment 3
(36) Traffic Safety Features 0000

Scour Data

(113) Scour Critical Bridges 8
(202) Foundation Type
(220) Foundation Embedment 0.0 M
(221) Scour Countermeasures

Load Rate and Post

(41) Str Open/Post/Close Posted
(64) Operating Rating 39.0 ton
(66) Inventory Rating 16.3 ton
(70) Bridge Posting 4
(211) Posted Limit

(209) Str Name:

Princ Rte: 360 Milepost: 0.000

Proposed Maintenance

(212) Repair Priority
(213) Proposed Maint Type
(215) Maintn Date Completed / /
(216) Actual Maint Cost 0


Inspection Data

(90) Inspection Date (MoYr) 02/10
~~0108~~
(91) Inspection Frequency 24 Mo
(92) Critical Feature Insp (93) Date
Frac Crit Insp : N /
Underwater Insp: N /
Other Spec Insp: N /
(207) Inspection Quarter 4
(208) Inspection Number
(210) Date of Inspection -12/15/1996
02/18/2010


Over 200 Items

(200) Princ Route Location
(201) Wear Surface Thickness 0.0 mm
(203) District Maint Org
(204) Original Proj #
(205) Station Princ Rte 0.000
(206) Bridge Rail Type
(217) Culvert Bbl Height 0.0 M
(218) Culvert Bbl Length 0.0 M
(219) Culvert Fill Height 0.0 M
(222) Date of Load Rating / /
(223) Tracs No
(224) Bridge Crew Region
(225) Total Deck Area (M^2) 0.0
(226) Superstr Unit Cost 0.00
(227) Substr Unit Cost 0.00
(228) Next Insp Due Date (QuartYr) 498
(229) Agency
(230) Principal Route Number 360
(231) Principal Route Letter
(232) Principal Route Milepost 0.000
(300) Comments:

Sufficiency Rating = 037.0
Functionly Obsolete



NUAAILUA BRIDGE
 BRIDGE NO. 009003600501540




SECTION LOOKING TOWARDS HANA

NUAAILUA BRIDGE
 BRIDGE NO. 009003600501540

← TO KAHULUI

TO HANA →



UPSTREAM ELEVATION

NUAAILUA BRIDGE
BRIDGE NO. 009003600501540

NUAAILUA STREAM BRIDGE**PHOTO LOG**

Bridge No. 009003600501540

PHOTO NO.	DESCRIPTION
1	KAHULUI APPROACH LOOKING TOWARD HANA
2	HANA APPROACH LOOKING TOWARD KAHULUI
3	UPSTREAM / KAHULUI CRM WALL WITH COLLISION DAMAGE
4	DOWNSTREAM / KAHULUI GUARDRAIL AND CRM WALL
5	UPSTREAM / HANA CRM WALL
6	DOWNSTREAM / HANA GUARDRAIL AND CRM WALL
7	UPSTREAM PARAPET ELEVATION. NOTE: PARAPET HT = 42"
8	BACKSIDE UPSTREAM PARAPET ELEVATION
9	CLOSE UP OF SCRAPES ON UPSTREAM PARAPET NEAR HANA SIDE
10	DOWNSTREAM RAILING ELEVATION. NOTE: RAILING HT = 40"
11	BACKSIDE DOWNSTREAM RAILING ELEVATION. NOTE: DAMAGED RM-4 SIGN AT THE KAHULUI END OF RAILING
12	OVERALL A.C. PAVEMENT LOOKING TOWARD HANA
13	UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI
14	DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND WATER STAINS. NOTE: DECK DRAINS HAVE BEEN PAVED OVER
15	DELAMINATION AND HAIRLINE CRACK (8' LONG) IN BOTTOM OF GIRDER G5 NEAR HANA ABUTMENT
16	OVERALL VIEW OF GIRDER G8 LOOKING DOWNSTREAM WITH SEVERAL SMALL SPALLS WITH EXPOSED REBAR AND DELAMINATION THROUGHOUT THE UPSTREAM FACE
17	CLOSE UP OF LARGE SPALL WITH EXPOSED REBAR IN BOTTOM OF GIRDER G8 NEAR KAHULUI ABUTMENT
18	KAHULUI ABUTMENT WITH DARK WATER STAINS
19	HANA ABUTMENT
20	HONEYCOMBING BETWEEN GIRDERS G6 AND G7 AND DELAMINATION BETWEEN GIRDERS G7 AND G8 ON BACKWALL OF KAHULUI ABUTMENT
21	UPSTREAM VIEW FROM TOP OF BRIDGE
22	UPSTREAM VIEW FROM UNDER BRIDGE

NUAAILUA STREAM BRIDGE

PHOTO LOG

Bridge No. 009003600501540

PHOTO NO.	DESCRIPTION
23	DOWNSTREAM VIEW FROM TOP OF BRIDGE
24	DOWNSTREAM VIEW FROM UNDER BRIDGE



PHOTO 1 KAHULUI APPROACH LOOKING TOWARD HANA



PHOTO 2 HANA APPROACH LOOKING TOWARD KAHULUI



PHOTO 3 UPSTREAM / KAHULUI CRM WALL WITH COLLISION DAMAGE



PHOTO 4 DOWNSTREAM / KAHULUI GUARDRAIL AND CRM WALL



PHOTO 5 UPSTREAM / HANA CRM WALL



PHOTO 6 DOWNSTREAM / HANA GUARDRAIL END TREATMENT AND CRM WALL. NOTE: GUARDRAIL END TREATMENT HT = 26"



PHOTO 7 UPSTREAM PARAPET ELEVATION. NOTE: PARAPET HT = 42"



PHOTO 8 BACKSIDE UPSTREAM PARAPET ELEVATION



PHOTO 9 CLOSE UP OF SCRAPES ON UPSTREAM PARAPET NEAR HANA SIDE



PHOTO 10 DOWNSTREAM RAILING ELEVATION. NOTE: RAILING HT = 40"



**PHOTO 11 BACKSIDE DOWNSTREAM RAILING ELEVATION. NOTE: DAMAGED RM-4 SIGN
AT THE KAHULUI END OF RAILING**



PHOTO 12 OVERALL A.C. PAVEMENT LOOKING TOWARD HANA



PHOTO 13 UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI



PHOTO 14 DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND WATER STAINS. NOTE: DECK DRAINS HAVE BEEN PAVED OVER



PHOTO 15 DELAMINATION AND HAIRLINE CRACK (8' LONG) IN BOTTOM OF GIRDER G5 NEAR HANA ABUTMENT



PHOTO 16 OVERALL VIEW OF GIRDER G8 LOOKING DOWNSTREAM WITH SEVERAL SMALL SPALLS WITH EXPOSED REBAR AND DELAMINATION THROUGHOUT THE UPSTREAM FACE



**PHOTO 17 CLOSE UP OF LARGE SPALL WITH EXPOSED REBAR IN BOTTOM OF GIRDER
G8 NEAR KAHULUI ABUTMENT**



PHOTO 18 KAHULUI ABUTMENT WITH DARK WATER STAINS



PHOTO 19 HANA ABUTMENT



**PHOTO 20 HONEYCOMBING BETWEEN GIRDERS G6 AND G7 AND DELAMINATION
BETWEEN GIRDERS G7 AND G8 ON BACKWALL OF KAHULUI ABUTMENT**



PHOTO 21 UPSTREAM VIEW FROM TOP OF BRIDGE



PHOTO 22 UPSTREAM VIEW FROM UNDER BRIDGE




PHOTO 23 DOWNSTREAM VIEW FROM TOP OF BRIDGE




PHOTO 24 DOWNSTREAM VIEW FROM UNDER BRIDGE

ROUTINE (PERIODIC) BRIDGE INSPECTION REPORT

PIINAAU STREAM BRIDGE
BRIDGE NO. 009003600501662
MAUI, HAWAII



For

State of Hawaii
Department of Transportation
Highways Division

Prepared by

Nagamine Okawa Engineers Inc.
1003 Bishop Street
Suite 2025
Honolulu, Hawaii 96813
Telephone: (808) 536-2626

FEBRUARY 2010

STATE OF HAWAII
DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

NBI BRIDGE INSPECTION REPORT

Date of Inspection	<u>2/18/10</u>	Bridge Name	<u>Piinaau Stream Bridge</u>
Bridge Number	<u>009003600501662</u>	Route No.	<u>360</u>
Number of Spans	<u>1</u>	Highway	<u>Hana Highway</u>
Location: Island	<u>Maui</u>	Milepost	<u>16.60</u>
Feature Intersected	<u>Piinaau Stream</u>	Substructure	<u>Reinforced Concrete</u>
Bridge Material:	Superstructure <u>Reinforced Concrete</u>		

	Condition Rating	Remarks
36	TRAFFIC SAFETY FEATURES	Indicate if feature meets currently acceptable standards. 0 - No 1 - Yes N - Not Applicable

1. Bridge Railings	<div style="border: 1px solid black; text-align: center; width: 40px;">0</div>	1. Bridge railings do not meet acceptable height standards.
2. Transitions	<div style="border: 1px solid black; text-align: center; width: 40px;">0</div>	
3. Approach Guardrail	<div style="border: 1px solid black; text-align: center; width: 40px;">0</div>	
4. Approach Guardrail Ends	<div style="border: 1px solid black; text-align: center; width: 40px;">0</div>	

58	DECK	
-----------	-------------	--

1. Wearing Surface	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
2. Decks - Structural Condition	<div style="border: 1px solid black; text-align: center; width: 40px;">6</div>	2. Water stains on soffit and minor edge spalls along upstream side of bridge.
3. Curbs	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
4. Median	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
5. Sidewalks	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
6. Parapet	<div style="border: 1px solid black; text-align: center; width: 40px;">6</div>	
7. Railing	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
8. Paint	<div style="border: 1px solid black; text-align: center; width: 40px;">4</div>	8. This rating is for paint on the bridge railings.
9. Drains	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
10. Lighting Standards	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
11. Utilities	<div style="border: 1px solid black; text-align: center; width: 40px;">6</div>	
12. Joint Leakage	<div style="border: 1px solid black; text-align: center; width: 40px;">6</div>	12. Efflorescence and water stains on soffit and girders.
13. Expansion Joints or Devices	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
Inspector's Condition Rating	<div style="border: 1px solid black; text-align: center; width: 40px;">6</div>	

59	SUPERSTRUCTURE	
-----------	-----------------------	--

1. Bearing Devices	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
2. Stringers	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
3. Girders, Beams, or Arches	<div style="border: 1px solid black; text-align: center; width: 40px;">5</div>	3. Delaminations and cracks in girders.
4. Floor Beams and Diaphragms	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
5. Trusses -General	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
-Portals	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
-Bracing	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
6. Paint	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
7. Machinery (Moveable Spans)	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
8. Rivets and/or Bolts	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
9. Welds - Cracks	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
10. Rust	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
11. Timber Decay	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
12. Concrete Cracking and/or Spalling	<div style="border: 1px solid black; text-align: center; width: 40px;">5</div>	12. See Item 59.3
13. Collision Damage	<div style="border: 1px solid black; text-align: center; width: 40px;">7</div>	
14. Deflection Under Load	<div style="border: 1px solid black; text-align: center; width: 40px;">7</div>	
15. Alignment of Members	<div style="border: 1px solid black; text-align: center; width: 40px;">7</div>	
16. Vibrations Under Load	<div style="border: 1px solid black; text-align: center; width: 40px;">7</div>	
17. Flat Slab	<div style="border: 1px solid black; text-align: center; width: 40px;">N</div>	
Inspector's Condition Rating	<div style="border: 1px solid black; text-align: center; width: 40px;">5</div>	

Date of Inspection 2/18/10 Bridge name Piinaau Stream Bridge
 Bridge Number 009003600501662

Condition Rating Remarks

60 SUBSTRUCTURE

1.	Abutment	-Wings	7	Abutment is bearing directly on bedrock.
		-Backwall/Breastwall	7	
		-Footing	-	
		-Piles	N	
		-Erosion	7	
		-Settlement	7	
2.	Piers or Bents	-Caps	N	
		-Column/Wall	N	
		-Footing	N	
		-Piles	N	
		-Scour	N	
		-Settlement	N	
3.	Pile bents		N	
4.	Concrete Cracking and/or Spalling		7	
5.	Steel Corrosion		N	
6.	Timber Decay, etc.		N	
7.	Debris on Seats		N	
8.	Paint		N	
9.	Collision Damage		8	
	Inspector's Condition Rating		7	

61 CHANNEL & CHANNEL PROTECTION

1.	Channel Scour	7
2.	Embankment Erosion	7
3.	Drift	7
4.	Vegetation	7
5.	Channel Change	7
6.	Fender System	N
7.	Spur Dikes & Jetties	N
8.	Rip Rap	N
9.	Adequacy of Opening	7
	Inspector's Condition Rating	7

62 CULVERT & RETAINING WALLS

1.	Barrel	-Concrete	N
		-Steel	N
		-Timber	N
2.	Headwall		N
3.	Cutoff Wall		N
4.	Adequacy		N
5.	Debris		N
	Inspector's Condition Rating		N

Date of Inspection 2/18/10 Bridge Name Piinaau Stream Bridge
Bridge Number 009003600501662

93	CRITICAL FEATURE INSPECTION DATE	Provide date if applicable. If not applicable, indicate with N.
1.	Fracture Critical Details	<u>N</u>
2.	Underwater Inspection	<u>N</u>
3.	Other Special Inspection	<u>N</u>

[If applicable, submit Underwater Inspection Report]

OTHER FEATURES	Y - Yes	N - No	Remarks
1. Bridge Posted?	<u>Y</u>		Posted Limit = <u>10 Tons</u> (See Comment Below)
2. Signage for Posting Legible/Visible?	<u>N</u>		
3. Riding Surface (Roughness) Rating	<u>2</u>		3 - Smooth, 2 - Average, 1 - Poor



1. 10-ton posted load limit on Hana Bridges at both ends of Hana Hwy. No posting at the bridge.

REPAIRS AND IMPROVEMENTS

- List all work done to this bridge since the last inspection including cost.
None.
- Indicate proposed and/or recommended improvements including estimated cost.
 - Close off openings in CRM walls (Est. Cost = \$22,000).
 - Repair cracks, spalls, and delaminations in girders (Est. Cost = \$30,000).
 - Upgrade bridge railings and approach guardrails (Est. Cost = \$48,000).
 - Seal joint between original and widened portion of bridge (Maintenance Item).
- List any existing temporary conditions.
None.

REMARKS AND RECOMMENDATIONS

- Does this bridge require inspection by Bridge Design Section? Yes _____ No X
[This should only be addressed by in-house inspectors who are not structural engineers.]
- Remarks: Describe defects. Use sketches, diagrams and/or photographs where possible.

Inspected by:	Name (printed):	<u>Garrett Nago & Robin Okawa</u>	Certified
	Signature:	<u></u>	Bridge Inspector
	Phone Number:	<u>808.536.2626</u>	
Supervised by:	Name (printed):	<u>Dwight Okawa, S.E.</u>	Title: <u>V.P.</u>
	Signature:	<u></u>	
	Phone Number:	<u>808.536.2626</u>	

STATE OF HAWAII DEPARTMENT OF TRANSPORTATION
PONTIS BRIDGE INSPECTION REPORT

r10/8/07

Date of Inspection	2/18/10	Bridge Name	Piinaau Stream Bridge
Bridge Number	009003600501662	Route No.	360
Number of Spans	1	Highway	Hana Highway
Location: Island	Maui	Feature Intersected	Piinaau Stream

ELEM NO.	ELEMENT DESCRIPTION	ENV. (Note 1)	TOTAL QUANT.	UNIT	ST 1	ST 2	ST 3	ST 4	ST 5
13	DECK OR SLAB (Note 2)	2	560	SF.	560				
110	GIRDERS	2	196	LFT.		196			
215	ABUTMENTS	2	48	LFT.	45	3			
*	COLUMNS			EA.					
*	PIER WALL			LFT.					
*	PIER CAPS			LFT.					
301	JOINTS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)	2	40	LFT.		40			
331	BRIDGE RAILING	2	56	LFT.	55	1			
*	APPROACH SLABS			EA.					
*	BEARINGS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)			EA.					
*	CULVERT			LFT.					
*	SMART FLAG: STEEL FATIGUE			EA.					
*	SMART FLAG: PACK RUST			EA.					
*	SMART FLAG: DECK CRACKING (ON TOP OF DECK ONLY)			EA.					
359	SMART FLAG: SOFFIT OF CONC. DECK OR SLAB (THIS SMART FLAG IS MANDATORY IF DECK OR SLAB HAS AN A.C. OVERLAY).	2	1	EA.		1			
*	SMART FLAG: SETTLEMENT			EA.					
*	SMART FLAG: SCOUR			EA.					
*	SMART FLAG: TRAFFIC IMPACT (TRAFFIC IMPACT TO SUPERSTRUCTURE ONLY)			EA.					
*	SMART FLAG: SECTION LOSS			EA.					
OTHERS									

COMMENTS:

Note 1: For each element, the inspector shall code the type of environment from the following key:

Env 1: Benign & Low Env: Little or no env. conditions affecting deterioration. Past bridge inspections show that env. has caused little or no deterioration.

Env 2: Moderate: Moderate level of environmental influence or deterioration. Past bridge inspections show that environment has caused some deterioration.

Env 3: Severe: Severe level of environmental influence or deterioration. Past bridge inspections show that environment has caused significant.

Note 2: For DECKS ONLY: All quantity in one ST only. Deck/slab is rated from top of deck/slab only. Use soffit smart flag (elem 359) to rate soffit.

Use these revised Condition States for rating Concrete Decks/Slabs

CS1	No patched areas, no potholes, no spalls and delams, etc.
CS2	Distressed areas are less than 2% of the total deck area.
CS3	Distressed areas are more than 2% but 10% or less of the total deck area.
CS4	Distressed areas are more than 10% but 25% or less of the total deck area.
CS5	Distressed areas are 25% or more of the total deck area.

Inspector's Name (printed):

Garrett Nago & Robin Okawa

Title: Cert. Bridge Inspector

Inspector's Name (signature):

Garrett Nago *R. Okawa*

Inspector's phone number:

808.536.2626

Supervisor's Name (printed):

Dwight Okawa, S.E.

Title: V.P.

Supervisor's Name (signature):

Dwight Okawa

Geographic and Route Data

(1) State Hawaii
(2) District 20
(3) County Maui
(4) Place 99999
(6) Feature Under PIINAAU STRM
(7) Facility on HANA HWY
(9) Location 0.04MI E/KEANAE HMSTD RD
(16) Latitude 20° 51' 42.00"
(17) Longitude 156° 09' 00.00"
(98) Border Bridge
(99) Border Bridge Str No
(103) Temporary Str

On and Under Record Data

Route On
(5) Inventory Route 121003602
(10) Min Vert Clr 99.99 M
(11) Kilometerpoint 0026.714
(19) Detour Length 199 km
(20) Toll 3
(26) Func Class 07
(28) Lanes on/under 0200
(29) ADT 1515
(30) Year of ADT 2007
(47) Total Horz Clearance 05.9 M
(100) Defense Hwy 0
(101) Parallel Str N
(102) Direction of Traffic 2
(104) Hwy System 0
(109) Truck Traffic 00%
(110) Natl Truck Network No

General Data

(21) Maintenance Responsibility 01
(22) Owner 01
(31) Design Load 0
(33) Bridge Median 0
(34) Skew 00 deg
(35) Str Flared No
(37) Hist Significance 3
(38) Navigation Control 0
(42) Type of Service 15
(43) Structure Type Main 104
(44) Structure Type Approach 000
(45) No of Span Main 001
(46) No of Approach Spans 0000
(27) Year Built 1916
(106) Year Reconstructed 1940
(107) Deck Str Type 1
(108) Wear Surf/Protv Sys 000
(111) Nav Pier/Abut Protection

Dimensional Data

(32) Approach Rdwy Width 6.1 M
(39) Navigation Vert Clr 000.0 M
(40) Navigation Horz clr 0000.0 M
(48) Max Span Length 0008.2 M
(49) Str Length 00008.5 M
(50) Curb/Sidewalk Width Left 00.0 M
Right 00.0 M
(51) Brg Rdwy Width, curb-curb 005.9 M
(52) Deck Width out-out 006.2 M
(53) Min Vert Clr over 99.99 M
(54) Min Vert Clr under N 00.00 M
(55) Min Lat Underclr R N 00.0 M
(56) Min Lat Underclr L 99.9 M
(112) NBIS Bridge Length Y
(116) Navigation Min Vert Clr M

Proposed Improvements

(75) Type of Work 311
(76) Improvement Length 000149 M
(94) Bridge Improv Cost 1000
(95) Rdwy Improv Cost 0
(96) Total Proj Cost 1575
(97) Year of Cost Est 1999
(114) Future ADT 2150
(115) Year of Future ADT 2027

Condition Rating

(58) Deck 6
(59) Superstructure 5 - 6
(60) Substructure 7 - 6
(61) Channel & Channel Protect 7
(62) Culverts N

Appraisal Rating

(67) Structure Evaluation 6
(68) Deck Geometry 2
(69) Underclrn Vert & Horz N
(71) Waterway Adequacy 7
(72) Approach Rdwy Alignment 3
(36) Traffic Safety Features 0000

Scour Data

(113) Scour Critical Bridges 8
(202) Foundation Type
(220) Foundation Embedment 0.0 M
(221) Scour Countermeasures

Load Rate and Post

(41) Str Open/Post/Close Posted
(64) Operating Rating 30.8 ton
(66) Inventory Rating 22.7 ton
(70) Bridge Posting 4
(211) Posted Limit

(209) Str Name:

Princ Rte: 360 Milepost: 0.000

Proposed Maintenance

(212) Repair Priority
(213) Proposed Maint Type
(215) Maintn Date Completed / /
(216) Actual Maint Cost 0


Inspection Data

(90) Inspection Date (MoYr) ~~0100~~ 0210
(91) Inspection Frequency 24 Mo
(92) Critical Feature Insp (93) Date
Frac Crit Insp: N /
Underwater Insp: N /
Other Spec Insp: N /
(207) Inspection Quarter 4
(208) Inspection Number
(210) Date of Inspection ~~12/15/1996~~ 02/18/2010

Over 200 Items

(200) Princ Route Location
(201) Wear Surface Thickness 0.0 mm
(203) District Maint Org
(204) Original Proj #
(205) Station Princ Rte 0.000
(206) Bridge Rail Type
(217) Culvert Bbl Height 0.0 M
(218) Culvert Bbl Length 0.0 M
(219) Culvert Fill Height 0.0 M
(222) Date of Load Rating / /
(223) Tracs No
(224) Bridge Crew Region
(225) Total Deck Area (M^2) 0.0
(226) Superstr Unit Cost 0.00
(227) Substr Unit Cost 0.00
(228) Next Insp Due Date (QuartYr) 498
(229) Agency
(230) Principal Route Number 360
(231) Principal Route Letter
(232) Principal Route Milepost 0.000
(300) Comments:

Sufficiency Rating = 044.2
Functionly Obsolete




BRIDGE PLAN

PIINAAU STREAM BRIDGE
BRIDGE NO. 009003600501662


DOWNSTREAM
←

UPSTREAM
→



SECTION LOOKING TOWARD HANA

PIINAAU STREAM BRIDGE
BRIDGE NO. 009003600501662



UPSTREAM ELEVATION

PIINAAU STREAM BRIDGE
BRIDGE NO. 009003600501662

PIINAAU STREAM BRIDGE
PHOTO LOG
 Bridge No. 009003600501662

PHOTO NO.	DESCRIPTION
1	APPROACH TO BRIDGE LOOKING TOWARD KAHULUI
2	ARRPOACH TO BRIDGE LOOKING TOWARD HANA
3	UPSTREAM HANA CRM WALL
4	UPSTREAM BRIDGE RAILING LOOKING TOWARD KAHULUI
5	DAMAGE TO END OF DOWNSTREAM KAHULUI CRM WALL
6	DOWNSTREAM BRIDGE RAILING LOOKING TOWARD KAHULUI
7	OPENING IN DOWNSTREAM HANA CRM WALL
8	BACK SIDE VIEW OF DOWNSTREAM END WITH UTILITIES
9	OVERALL VIEW OF AC PAVEMENT
10	UPSTREAM BRIDGE ELEVATION
11	DOWNSTREAM BRIDGE ELEVATION
12	OVERALL SOFFIT LOOKING DOWNSTREAM
13	UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS. DELAMINATION IN GIRDER G4 NEAR HANA ABUTMENT AND VERTICAL CRACKS.
14	JOINT LEAKAGE IN SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS
15	DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS. DELAMINATION IN GIRDER G6 DOWNSTREAM FACE NEAR KAHULUI ABUTMENT.
16	HONEYCOMBING IN CANTELEIVERED SOFFIT UPSTREAM END
17	UPSTREAM KAHULUI CRM WINGWALL
18	KAHULUI ABUTMENT
19	SOLID ROCK STREAM CHANNEL FRONTING KAHULUI ABUTMENT
20	DOWNSTREAM HANA CRM WINGWALL ABD UTILITY PIPE
21	HANA ABUTMENT
22	SOLID ROCK STREAM CHANNEL FRONTING HANA ABUTMENT
23	UPSTREAM VIEW OF STREAM CHANNEL
24	DOWNSTREAM VIEW OF STREAM CHANNEL

PIINAAU STREAM BRIDGE
PHOTO LOG
Bridge No. 009003600501662

PHOTO NO.	DESCRIPTION
25	EROSION 2'x3' AT BASE OF KAHULUI CRM WALL



PHOTO 1 APPROACH TO BRIDGE LOOKING TOWARD KAHULUI



PHOTO 2 APPROACH TO BRIDGE LOOKING TOWARD HANA



PHOTO 3 UPSTREAM HANA CRM WALL



PHOTO 4 UPSTREAM BRIDGE RAILING LOOKING TOWARD KAHULUI



PHOTO 5 DAMAGE TO END OF DOWNSTREAM KAHULUI CRM WALL



PHOTO 6 DOWNSTREAM BRIDGE RAILING LOOKING TOWARD KAHULUI



PHOTO 7 OPENING IN DOWNSTREAM HANA CRM WALL



PHOTO 8 BACK SIDE VIEW OF DOWNSTREAM END WITH UTILITIES



PHOTO 9 OVERALL VIEW OF AC PAVEMENT



PHOTO 10 UPSTREAM BRIDGE ELEVATION



PHOTO 11 DOWNSTREAM BRIDGE ELEVATION



PHOTO 12 OVERALL SOFFIT LOOKING DOWNSTREAM



PHOTO 13 UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS. DELAMINATION IN GIRDER G4 NEAR HANA ABUTMENT AND VERTICAL CRACKS.



PHOTO 14 JOINT LEAKAGE IN SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS



PHOTO 15 DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI WITH EFFLORESCENCE AND MOSS. DELAMINATION IN GIRDER G6 DOWNSTREAM FACE NEAR KAHULUI ABUTMENT.



PHOTO 16 HONEYCOMBING IN CANTELEIVERED SOFFIT UPSTREAM END



PHOTO 17 UPSTREAM KAHULUI CRM WINGWALL



PHOTO 18 KAHULUI ABUTMENT



PHOTO 19 SOLID ROCK STREAM CHANNEL FRONTING KAHULUI ABUTMENT



PHOTO 20 DOWNSTREAM HANA CRM WINGWALL AND UTILITY PIPE



PHOTO 21 HANA ABUTMENT



PHOTO 22 SOLID ROCK STREAM CHANNEL FRONTING HANA ABUTMENT



PHOTO 23 UPSTREAM VIEW OF STREAM CHANNEL




PHOTO 24 DOWNSTREAM VIEW OF STREAM CHANNEL



PHOTO 25 EROSION 2'x3' AT BASE OF KAHULUI CRM WALL

ROUTINE (PERIODIC) BRIDGE INSPECTION REPORT

PALAUHULU STREAM BRIDGE

BRIDGE NO. 009003600501679

MAUI, HAWAII



For

State of Hawaii
Department of Transportation
Highways Division

Prepared by

Nagamine Okawa Engineers Inc.
1003 Bishop Street
Suite 2025
Honolulu, Hawaii 96813
Telephone: (808) 536-2626

FEBRUARY 2010

STATE OF HAWAII
DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

NBI BRIDGE INSPECTION REPORT

Date of Inspection	<u>2/18/10</u>	Bridge Name	<u>Palauhulu Stream Bridge</u>
Bridge Number	<u>009003600501679</u>	Highway	<u>Hana Highway</u>
Number of Spans	<u>1</u>	Milepost	<u>16.77</u>
Location: Island	<u>Maui</u>	Route No.	<u>360</u>
Feature Intersected	<u>Palauhulu Stream</u>	Substructure	<u>Reinforced Concrete</u>
Bridge Material:	Superstructure <u>Reinforced Concrete</u>		

Condition Rating		Remarks
36	TRAFFIC SAFETY FEATURES	Indicate if feature meets currently acceptable standards. 0 - No 1 - Yes N - Not Applicable
1.	Bridge Railings	0
2.	Transitions	0
3.	Approach Guardrail	0
4.	Approach Guardrail Ends	0

58	DECK	
1.	Wearing Surface	7
2.	Decks - Structural Condition	6
3.	Curbs	N
4.	Median	N
5.	Sidewalks	N
6.	Parapet	N
7.	Railing	7
8.	Paint	N
9.	Drains	0
10.	Lighting Standards	N
11.	Utilities	6
12.	Joint Leakage	6
13.	Expansion Joints or Devices	N
	Inspector's Condition Rating	6

59	SUPERSTRUCTURE	
1.	Bearing Devices	N
2.	Stringers	N
3.	Girders, Beams, or Arches	5
4.	Floor Beams and Diaphragms	N
5.	Trusses -General	N
	-Portals	N
	-Bracing	N
6.	Paint	N
7.	Machinery (Moveable Spans)	N
8.	Rivets and/or Bolts	N
9.	Welds - Cracks	N
10.	Rust	N
11.	Timber Decay	N
12.	Concrete Cracking and/or Spalling	5
13.	Collision Damage	7
14.	Deflection Under Load	7
15.	Alignment of Members	7
16.	Vibrations Under Load	7
17.	Flat Slab	N
	Inspector's Condition Rating	5

Date of Inspection 2/18/10
 Bridge Number 009003600501679

Bridge name Palauhulu Stream Bridge

		Condition Rating	Remarks
60	SUBSTRUCTURE		
1.	Abutment -Wings	6	1b. Minor hairline cracks in both Hana and Kahului abutments. 1c. Abutment bears directly on bedrock.
	-Backwall/Breastwall	6	
	-Footing	N	
	-Piles	N	
	-Erosion	7	
	-Settlement	7	
2.	Piers or Bents -Caps	N	
	-Column/Wall	N	
	-Footing	N	
	-Piles	N	
	-Scour	N	
	-Settlement	N	
3.	Pile bents	N	
4.	Concrete Cracking and/or Spalling	6	4. See Item 60.1.
5.	Steel Corrosion	N	
6.	Timber Decay, etc.	N	
7.	Debris on Seats	7	
8.	Paint	N	
9.	Collision Damage	7	
	Inspector's Condition Rating	6	

61	CHANNEL & CHANNEL PROTECTION		
1.	Channel Scour	7	4. Vegetation along embankments upstream and downstream of bridge.
2.	Embankment Erosion	7	
3.	Drift	7	
4.	Vegetation	6	
5.	Channel Change	7	
6.	Fender System	N	
7.	Spur Dikes & Jetties	N	
8.	Rip Rap	N	
9.	Adequacy of Opening	7	
	Inspector's Condition Rating	7	

62	CULVERT & RETAINING WALLS		
1.	Barrel -Concrete	N	
	-Steel	N	
	-Timber	N	
2.	Headwall	N	
3.	Cutoff Wall	N	
4.	Adequacy	N	
5.	Debris	N	
	Inspector's Condition Rating	N	

Date of Inspection 2/18/10 Bridge Name Palauhulu Stream Bridge
Bridge Number 009003600501679

93	CRITICAL FEATURE INSPECTION DATE	Provide date if applicable. If not applicable, indicate with N.
1.	Fracture Critical Details	<u>N</u>
2.	Underwater Inspection	<u>N</u>
3.	Other Special Inspection	<u>N</u>

[If applicable, submit Underwater Inspection Report]




OTHER FEATURES		Y - Yes	N - No	Remarks
1.	Bridge Posted?	<u>Y</u>		Posted Limit = <u>10 Ton weight limit</u>
2.	Signage for Posting Legible/Visible?	<u>N</u>		Load posting sign is located near mile post 0.0 Route 360,
3.	Riding Surface (Roughness) Rating	<u>2</u>		and is used as a notice for all Hana bridges. 3 - Smooth, 2 - Average, 1 - Poor

REPAIRS AND IMPROVEMENTS

- List all work done to this bridge since the last inspection including cost.
- Indicate proposed and/or recommended improvements including estimated cost.
 - Replace missing RM-4 markers at both Hana and Kahului ends of bridge(Maintenance Item).
 - Repair spall and delamination in deck soffit (Est. Cost = \$19,000).
 - Install guardrail transitions, approach guardrails, and end treatments to meet current acceptable standards (Cost Est. = \$50,000)
 - Upgrade railings to meet current acceptable standards (Cost Est. = \$118,000).
- List any existing temporary conditions.

REMARKS AND RECOMMENDATIONS

- Does this bridge require inspection by Bridge Design Section? Yes - No -
[This should only be addressed by in-house inspectors who are not structural engineers.]
- Remarks: Describe defects. Use sketches, diagrams and/or photographs where possible.

Inspected by:	Name (printed):	Erik-Jon Cabbab / Cody Aihara	Certified
	Signature:		
	Phone Number:	808.536.2626	
Supervised by:	Name (printed):	Dwight M. Okawa, S.E.	Title: V.P./Team Leader
	Signature:		
	Phone Number:	808.536.2626	

**STATE OF HAWAII DEPARTMENT OF TRANSPORTATION
PONTIS BRIDGE INSPECTION REPORT**

r10/8/07

Date of Inspection <u>2/18/10</u>	Bridge Name <u>Palauhulu Stream Bridge</u>
Bridge Number <u>009003600501679</u>	Route No. <u>360</u>
Number of Spans <u>1</u>	Highway <u>Hana Highway</u>
Location: Island <u>Maui</u>	Feature Intersected <u>Palauhulu Stream</u>

ELEM NO.	ELEMENT DESCRIPTION	ENV. (Note 1)	TOTAL QUANT.	UNIT	ST 1	ST 2	ST 3	ST 4	ST 5
13	DECK OR SLAB (Note 2)	2	620	SF.	620				
110	GIRDERS	2	124	LFT.	106	18			
215	ABUTMENTS	2	50	LFT.	50				
*	COLUMNS			EA.					
*	PIER WALL			LFT.					
*	PIER CAPS			LFT.					
301	JOINTS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)	2	40	LFT.		40			
331	BRIDGE RAILING	2	69	LFT.	69				
*	APPROACH SLABS			EA.					
*	BEARINGS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)			EA.					
*	CULVERT			LFT.					
*	SMART FLAG: STEEL FATIGUE			EA.					
*	SMART FLAG: PACK RUST			EA.					
*	SMART FLAG: DECK CRACKING (ON TOP OF DECK ONLY)			EA.					
359	SMART FLAG: SOFFIT OF CONC. DECK OR SLAB (THIS SMART FLAG IS MANDATORY IF DECK OR SLAB HAS AN A.C. OVERLAY)	2	1	EA.	1				
*	SMART FLAG: SETTLEMENT			EA.					
*	SMART FLAG: SCOUR			EA.					
*	SMART FLAG: TRAFFIC IMPACT (TRAFFIC IMPACT TO SUPERSTRUCTURE ONLY)			EA.					
*	SMART FLAG: SECTION LOSS			EA.					
OTHERS:									

COMMENTS:

Note 1: For each element, the inspector shall code the type of environment from the following key:

Env 1: Benign & Low Env: Little or no env. conditions affecting deterioration. Past bridge inspections show that env. has caused little or no deterioration.

Env 2: Moderate: Moderate level of environmental influence or deterioration. Past bridge inspections show that environment has caused some deterioration.

Env 3: Severe: Severe level of environmental influence or deterioration. Past bridge inspections show that environment has caused significant.

Note 2: For DECKS ONLY: All quantity in one ST only. Deck/slab is rated from top of deck/slab only. Use soffit smart flag (elem 359) to rate soffit.

Use these revised Condition States for rating Concrete Decks/Slabs	
CS1	No patched areas, no potholes, no spalls and delams, etc.
CS2	Distressed areas are less than 2% of the total deck area.
CS3	Distressed areas are more than 2% but 10% or less of the total deck area.
CS4	Distressed areas are more than 10% but 25% or less of the total deck area.
CS5	Distressed areas are 25% or more of the total deck area.

Inspector's Name (printed):

Erik-Jon Cabbab / Cody Aihara

Inspector's Name (signature):

Erik-Jon Cabbab *Cody Aihara*

Inspector's phone number:

808.536.2626

Title: Certified Bridge Inspector

Supervisor's Name (printed):

Dwight M. Okawa, S.E.

Supervisor's Name (signature):

Dwight M. Okawa

Title: V.P. / Team Leader

Geographic and Route Data

(1) State Hawaii
(2) District 20
(3) County Maui
(4) Place 99999
(6) Feature Under PALAUHULU STRM
(7) Facility on HANA HWY
(9) Location 0.21MI E/KEANAE HMSTD RD
(16) Latitude 20° 51' 36.00"
(17) Longitude 156° 08' 54.00"
(98) Border Bridge
(99) Border Bridge Str No
(103) Temporary Str

On and Under Record Data

(5) Inventory Route 121003602
(10) Min Vert Clr 99.99 M
(11) Kilometerpoint 0026.988
(19) Detour Length 199 km
(20) Toll 3
(26) Func Class 07
(28) Lanes on/under 0200
(29) ADT 1515
(30) Year of ADT 2007
(47) Total Horz Clearance 06.2 M
(100) Defense Hwy 0
(101) Parallel Str N
(102) Direction of Traffic 2
(104) Hwy System 0
(109) Truck Traffic 00%
(110) Natl Truck Network No

General Data

(21) Maintenance Responsibility 01
(22) Owner 01
(31) Design Load 0
(33) Bridge Median 0
(34) Skew 00 deg
(35) Str Flared No
(37) Hist Significance 3
(38) Navigation Control 0
(42) Type of Service 15
(43) Structure Type Main 104
(44) Structure Type Approach 000
(45) No of Span Main 001
(46) No of Approach Spans 0000
(27) Year Built 1916
(106) Year Reconstructed 0000
(107) Deck Str Type 1
(108) Wear Surf/Protv Sys 600
(111) Nav Pier/Abut Protection

Dimensional Data

(32) Approach Rdwy Width 7.6 M
(39) Navigation Vert Clr 000.0 M
(40) Navigation Horz clr 0000.0 M
(48) Max Span Length 0009.1 M
(49) Str Length 00009.4 M
(50) Curb/Sidewalk Width Left 00.0 M
Right 00.0 M
(51) Brg Rdwy Width, curb-curb 006.2 M
(52) Deck Width out-out 006.6 M
(53) Min Vert Clr over 99.99 M
(54) Min Vert Clr under N 00.00 M
(55) Min Lat Underclr R N 00.0 M
(56) Min Lat Underclr L 99.9 M
(112) NBIS Bridge Length Y
(116) Navigation Min Vert Clr M

Proposed Improvements

(75) Type of Work 311
(76) Improvement Length 000158 M
(94) Bridge Improv Cost 1061
(95) Rdwy Improv Cost 0
(96) Total Proj Cost 1672
(97) Year of Cost Est 1999
(114) Future ADT 2150
(115) Year of Future ADT 2027

Condition Rating

(58) Deck 6
(59) Superstructure 5-6
(60) Substructure 6
(61) Channel & Channel Protect 7-6
(62) Culverts N

Appraisal Rating

(67) Structure Evaluation 5
(68) Deck Geometry 2
(69) Underclrn Vert & Horz N
(71) Waterway Adequacy 6
(72) Approach Rdwy Alignment 3
(36) Traffic Safety Features 0000

Scour Data

(113) Scour Critical Bridges 8
(202) Foundation Type
(220) Foundation Embedment 0.0 M
(221) Scour Countermeasures

Load Rate and Post

(41) Str Open/Post/Close Posted
(64) Operating Rating 29.0 ton
(66) Inventory Rating 20.9 ton
(70) Bridge Posting 4
(211) Posted Limit

(209) Str Name:

Princ Rte: 360 Milepost: 0.000

Proposed Maintenance

(212) Repair Priority
(213) Proposed Maint Type
(215) Maintn Date Completed / /
(216) Actual Maint Cost 0


Inspection Data

(90) Inspection Date (MoYr) 02/10
0108
(91) Inspection Frequency 24 Mo
(92) Critical Feature Insp (93) Date
Frac Crit Insp: N /
Underwater Insp: N /
Other Spec Insp: N /
(207) Inspection Quarter 4
(208) Inspection Number
(210) Date of Inspection 12/15/1996
02/18/2010

Over 200 Items


(200) Princ Route Location
(201) Wear Surface Thickness 0.0 mm
(203) District Maint Org
(204) Original Proj #
(205) Station Princ Rte 0.000
(206) Bridge Rail Type
(217) Culvert Bbl Height 0.0 M
(218) Culvert Bbl Length 0.0 M
(219) Culvert Fill Height 0.0 M
(222) Date of Load Rating / /
(223) Tracs No
(224) Bridge Crew Region
(225) Total Deck Area (M^2) 0.0
(226) Superstr Unit Cost 0.00
(227) Substr Unit Cost 0.00
(228) Next Insp Due Date (QuartYr) 498
(229) Agency
(230) Principal Route Number 360
(231) Principal Route Letter
(232) Principal Route Milepost 0.000
(300) Comments:

Sufficiency Rating = 048.3
Functionly Obsolete




BRIDGE PLAN

PALAUHULU STREAM BRIDGE
BRIDGE NO. 009003600501679



SECTION LOOKING TOWARD HANA

PALAUHULU STREAM BRIDGE
BRIDGE NO. 009003600501679



UPSTREAM ELEVATION

PALAUHULU STREAM BRIDGE
BRIDGE NO. 009003600501679

PALAUHULU STREAM BRIDGE**PHOTO LOG**

Bridge No. 009003600501679

PHOTO NO.	DESCRIPTION
1	KAHULUI APPROACH TO BRIDGE LOOKING TOWARD HANA
2	HANA APPROACH TO BRIDGE LOOKING TOWARD KAHULUI
3	UPSTREAM / KAHULUI CRM WALL
4	DOWNSTREAM / KAHULUI GUARDRAIL END TREATMENT AND CRM WALL. NOTE: GUARDRAIL END TREATMENT HT = 36"
5	UPSTREAM / HANA CRM WALL
6	DOWNSTREAM / HANA CRM WALL
7	UPSTREAM BRIDGE RAILING. NOTE: RAILING HT = 24"
8	BACKSIDE UPSTREAM / KAHULUI BRIDGE RAILING ELEVATION
9	BACKSIDE UPSTREAM / HANA BRIDGE RAILING
10	DOWNSTREAM BRIDGE RAILING. NOTE: RAILING HT = 33"
11	OVERALL A.C. PAVEMENT LOOKING TOWARD HANA
12	UPSTREAM BRIDGE ELEVATION
13	DOWNSTREAM BRIDGE ELEVATION, BACKSIDE OF DOWNSTREAM BRIDGE RAILING AND CRM WALLS, AND UTILITY LINES ATTACHED TO SIDE OF BRIDGE
14	SUPPORTS FOR PVC PIPELINE ARE CORRODED ON THE DOWNSTREAM SIDE OF BRIDGE (SEE PHOTO 13)
15	OVERALL DECK SOFFIT VIEW LOOKING DOWNSTREAM
16	DELAMINATION IN DECK SOFFIT BETWEEN GIRDERS G3 AND G4 NEAR MID-SPAN
17	HAIRLINE LONGITUDINAL CRACK ALONG BOTTOM OF GIRDER G1
18	SMALL SPALL WITH EXPOSED REBAR IN BOTTOM OF GIRDER G1 NEAR HANA ABUTMENT
19	KAHULUI ABUTMENT
20	HANA ABUTMENT
21	UPSTREAM VIEW OF STREAM CHANNEL
22	DOWNSTREAM VIEW OF STREAM CHANNEL



PHOTO 1 KAHULUI APPROACH TO BRIDGE LOOKING TOWARD HANA



PHOTO 2 HANA APPROACH TO BRIDGE LOOKING TOWARD KAHULUI



PHOTO 3 UPSTREAM / KAHULUI CRM WALL



**PHOTO 4 DOWNSTREAM / KAHULUI GUARDRAIL END TREATMENT AND CRM WALL.
NOTE: GUARDRAIL END TREATMENT HT = 36"**



PHOTO 5 **UPSTREAM / HANA CRM WALL**



PHOTO 6 **DOWNSTREAM / HANA CRM WALL**



PHOTO 7 UPSTREAM BRIDGE RAILING. NOTE: RAILING HT = 24"



PHOTO 8 BACKSIDE UPSTREAM / KAHULUI BRIDGE RAILING ELEVATION



PHOTO 9 BACKSIDE UPSTREAM / HANA BRIDGE RAILING



PHOTO 10 DOWNSTREAM BRIDGE RAILING. NOTE: RAILING HT = 33"



PHOTO 11 OVERALL A.C. PAVEMENT LOOKING TOWARD HANA



PHOTO 12 UPSTREAM BRIDGE ELEVATION



PHOTO 13 DOWNSTREAM BRIDGE ELEVATION, BACKSIDE OF DOWNSTREAM BRIDGE RAILING AND CRM WALLS, AND UTILITY LINES ATTACHED TO SIDE OF BRIDGE



PHOTO 14 SUPPORTS FOR PVC PIPELINE ARE CORRODED ON THE DOWNSTREAM SIDE OF BRIDGE (SEE PHOTO 13)



PHOTO 15 OVERALL DECK SOFFIT VIEW LOOKING DOWNSTREAM



PHOTO 16 DELAMINATION IN DECK SOFFIT BETWEEN GIRDERS G3 AND G4 NEAR MID-SPAN



PHOTO 17 HAIRLINE LONGITUDINAL CRACK ALONG BOTTOM OF GIRDER G1



PHOTO 18 SMALL SPALL WITH EXPOSED REBAR IN BOTTOM OF GIRDER G1 NEAR HANA ABUTMENT



PHOTO 19 KAHULUI ABUTMENT



PHOTO 20 HANA ABUTMENT




PHOTO 21 UPSTREAM VIEW OF STREAM CHANNEL



PHOTO 22 DOWNSTREAM VIEW OF STREAM CHANNEL

ROUTINE (PERIODIC) BRIDGE INSPECTION REPORT

WAIKANI STREAM BRIDGE
BRIDGE NO. 009003600501942
MAUI, HAWAII



For

State of Hawaii
Department of Transportation
Highways Division

Prepared by

Nagamine Okawa Engineers Inc.
1003 Bishop Street
Suite 2025
Honolulu, Hawaii 96813
Telephone: (808) 536-2626

FEBRUARY 2010

STATE OF HAWAII
DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

NBI BRIDGE INSPECTION REPORT

Date of Inspection	<u>2/18/10</u>	Bridge Name	<u>Waikani Stream Bridge</u>
Bridge Number	<u>009003600501942</u>		
Number of Spans	<u>1</u>		
Location: Island	<u>Maui</u>	Route No.	<u>360</u>
Feature Intersected	<u>Waikani Stream</u>	Highway	<u>Hana Highway</u>
Bridge Material:		Milepost	<u>19.39</u>
	Superstructure <u>Reinforced Concrete</u>	Substructure	<u>Reinforced Concrete</u>

	Condition Rating	Remarks
36 TRAFFIC SAFETY FEATURES		Indicate if feature meets currently acceptable standards. 0 - No 1 - Yes N - Not Applicable

1. Bridge Railings	0
2. Transitions	0
3. Approach Guardrail	0
4. Approach Guardrail Ends	0

58 DECK		
----------------	--	--

1. Wearing Surface	6	1. Potholes and wear occurring in A.C. overlay.
2. Decks - Structural Condition	6	2. Patches observed in several soffit spans.
3. Curbs	N	
4. Median	N	
5. Sidewalks	N	
6. Parapet	4	6. Collision damage with exposed rebar at the upstream / Hana parapet. Collision damage at upstream / Kahului parapet with CRM parapet built in front of damage.
7. Railing	6	7. Delamination and spalls in pickets and railing cap.
8. Paint	5	8. Paint is faded and weathered on railings.
9. Drains	6	9. Most deck drains clear. Vegetation growth in some drains.
10. Lighting Standards	N	
11. Utilities	3	
12. Joint Leakage	N	
13. Expansion Joints or Devices	N	11. Utility line along the upstream face of the bridge has corroded and damaged supports.
Inspector's Condition Rating	6	

59 SUPERSTRUCTURE		
--------------------------	--	--

1. Bearing Devices	N	
2. Stringers	N	
3. Girders, Beams, or Arches	6	3. Delamination in downstream face of arch under first downstream / Hana column. Dark water stains on arch members.
4. Floor Beams and Diaphragms	6	4. Patches observed on several floor beams.
5. Trusses -General	N	
-Portals	N	
-Bracing	N	
6. Paint	N	
7. Machinery (Moveable Spans)	N	
8. Rivets and/or Bolts	N	
9. Welds - Cracks	N	
10. Rust	N	
11. Timber Decay	N	
12. Concrete Cracking and/or Spalling	6	
13. Collision Damage	7	
14. Deflection Under Load	7	
15. Alignment of Members	7	
16. Vibrations Under Load	7	
17. Flat Slab	N	
Inspector's Condition Rating	6	

Date of Inspection 2/18/10 Bridge name Waikani Stream Bridge
 Bridge Number 009003600501942

		Condition Rating	Remarks
60	SUBSTRUCTURE		
1.	Abutment -Wings	6	
	-Backwall/Breastwall	6/6	1b. Hairline cracks and water stains on abutments.
	-Footing	7	1c. Abutments bear directly on bedrock.
	-Piles	N	
	-Erosion	7	
	-Settlement	7	
2.	Piers or Bents -Caps	N	
	-Column/Wall	6	2b. Small spalls with exposed rebar in first upstream / Hana column.
	-Footing	N	Delaminated patches on columns.
	-Piles	N	
	-Scour	N	
	-Settlement	N	
3.	Pile bents	N	
4.	Concrete Cracking and/or Spalling	7	
5.	Steel Corrosion	N	
6.	Timber Decay, etc.	N	
7.	Debris on Seats	N	
8.	Paint	N	
9.	Collision Damage	8	
	Inspector's Condition Rating	6	

61	CHANNEL & CHANNEL PROTECTION		
1.	Channel Scour	7	
2.	Embankment Erosion	6	
3.	Drift	6	
4.	Vegetation	6	4. Heavy vegetation growth along channel embankments.
5.	Channel Change	7	
6.	Fender System	N	
7.	Spur Dikes & Jetties	N	
8.	Rip Rap	N	
9.	Adequacy of Opening	7	
	Inspector's Condition Rating	7	

62	CULVERT & RETAINING WALLS		
1.	Barrel -Concrete	N	
	-Steel	N	
	-Timber	N	
2.	Headwall	N	
3.	Cutoff Wall	N	
4.	Adequacy	N	
5.	Debris	N	
	Inspector's Condition Rating	N	

Date of Inspection 2/18/10 Bridge Name Waikani Stream Bridge
Bridge Number 009003600501942

93	CRITICAL FEATURE INSPECTION DATE	Provide date if applicable. If not applicable, indicate with N.
1.	Fracture Critical Details	<u>N</u>
2.	Underwater Inspection	<u>N</u>
3.	Other Special Inspection	<u>N</u>

[If applicable, submit Underwater Inspection Report]




OTHER FEATURES		Y - Yes	N - No	Remarks
1.	Bridge Posted?	<u>Y</u>		Posted Limit = <u>10 Ton weight limit</u>
2.	Signage for Posting Legible/Visible?	<u>N</u>		Load posting sign is located near mile post 0.0 Route 360,
3.	Riding Surface (Roughness) Rating	<u>2</u>		and is used as a notice for all Hana bridges. 3 - Smooth, 2 - Average, 1 - Poor

REPAIRS AND IMPROVEMENTS

- List all work done to this bridge since the last inspection including cost.
- Indicate proposed and/or recommended improvements including estimated cost.
 - Install guardrail transitions, approach guardrails, and end treatments to meet current acceptable standards (Cost Est. = \$50,000).
 - Upgrade railings to meet current acceptable standards (Cost Est. = \$376,000).
 - Repair collision damage to upstream / Hana parapet (Cost Est. = \$8,000).
 - Repair cracks, delaminations, and spalls in railings, arch, and columns (Cost Est. = \$50,000).
 - Replace corroded and damaged pipe supports (Maintenance Item).
 - Repair potholes in A.C. overlay (Cost Est. = \$50,000).
- List any existing temporary conditions.

REMARKS AND RECOMMENDATIONS

- Does this bridge require inspection by Bridge Design Section? Yes - No -
[This should only be addressed by in-house inspectors who are not structural engineers.]
- Remarks: Describe defects. Use sketches, diagrams and/or photographs where possible.

Inspected by:	Name (printed):	Erik-Jon Cabbab / Cody Aihara	Title:	Certified Bridge Inspectors
	Signature:			
	Phone Number:	808.536.2626		
Supervised by:	Name (printed):	Dwight M. Okawa, S.E.	Title:	V.P./Team Leader
	Signature:			
	Phone Number:	808.536.2626		

STATE OF HAWAII DEPARTMENT OF TRANSPORTATION
PONTIS BRIDGE INSPECTION REPORT

r10/8/07

Date of Inspection <u>2/18/10</u>	Bridge Name <u>Waikani Stream Bridge</u>
Bridge Number <u>009003600501942</u>	Route No. <u>360</u>
Number of Spans <u>1</u>	Highway <u>Hana Highway</u>
Location: Island <u>Maui</u>	Feature Intersected <u>Waikani Stream</u>

ELEM NO.	ELEMENT DESCRIPTION	ENV. (Note 1)	TOTAL QUANT.	UNIT	ST 1	ST 2	ST 3	ST 4	ST 5
013	DECK OR SLAB (Note 2): UNPROTECTED DECK W/ A.C. OVERLAY	2	1836	SF.		1836			
155	FLOOR BEAM: REINF CONC	2	180	LFT.	180				
215	ABUTMENTS: REINF CONC	2	58	LFT.	58				
205	COLUMNS: REINF CONC	2	18	EA.	16	2			
*	PIER WALL			LFT.					
*	PIER CAPS			LFT.					
144	ARCH: REINF CONC	2	152	LFT.	149	3			
301	JOINTS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.): POURABLE JOINT SEAL	2	34	LFT.		34			
331	BRIDGE RAILING: REINF CONC	2	221	LFT.	171	50			
*	APPROACH SLABS			EA.					
*	BEARINGS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)			EA.					
*	CULVERT			LFT.					
*	SMART FLAG: STEEL FATIGUE			EA.					
*	SMART FLAG: PACK RUST			EA.					
*	SMART FLAG: DECK CRACKING (ON TOP OF DECK ONLY)			EA.					
359	SMART FLAG: SOFFIT OF CONC. DECK OR SLAB (THIS SMART FLAG IS MANDATORY IF DECK OR SLAB HAS AN A.C. OVERLAY).	2	1	EA.	1				
*	SMART FLAG: SETTLEMENT			EA.					
*	SMART FLAG: SCOUR			EA.					
*	SMART FLAG: TRAFFIC IMPACT (TRAFFIC IMPACT TO SUPERSTRUCTURE ONLY)			EA.					
*	SMART FLAG: SECTION LOSS			EA.					
OTHERS:									

COMMENTS:

Note 1: For each element, the inspector shall code the type of environment from the following key:

Env 1: Benign & Low Env: Little or no env. conditions affecting deterioration. Past bridge inspections show that env. has caused little or no deterioration.

Env 2: Moderate: Moderate level of environmental influence or deterioration. Past bridge inspections show that environment has caused some deterioration.


Env 3: Severe: Severe level of environmental influence or deterioration. Past bridge inspections show that environment has caused significant.

Note 2: For DECKS ONLY: All quantity in one ST only. Deck/slab is rated from top of deck/slab only. Use soffit smart flag (elem 359) to rate soffit.

Use these revised Condition States for rating Concrete Decks/Slabs	
CS1	No patched areas, no potholes, no spalls and delams, etc.
CS2	Distressed areas are less than 2% of the total deck area.
CS3	Distressed areas are more than 2% but 10% or less of the total deck area.
CS4	Distressed areas are more than 10% but 25% or less of the total deck area.
CS5	Distressed areas are 25% or more of the total deck area.

Inspector's Name (printed): Erik-Jon Cabbab / Cody Aihara
 Inspector's Name (signature):  
 Inspector's phone number: 808.536.2626

Title: Certified Bridge Inspectors

Supervisor's Name (printed): Dwight M. Okawa, S.E.
 Supervisor's Name (signature): 

Title: V.P. / Team Leader

Geographic and Route Data

(1) State Hawaii
(2) District 20
(3) County Maui
(4) Place 11350
(6) Feature Under WAIKANI STRM
(7) Facility on HANA HWY
(9) Location 0.33MI E/WAILUA VLLY LO R
(16) Latitude 20° 50' 06.00"
(17) Longitude 156° 08' 30.00"
(98) Border Bridge
(99) Border Bridge Str No
(103) Temporary Str

On and Under Record Data

(5) Inventory Route 121003602
(10) Min Vert Clr 99.99 M
(11) Kilometerpoint 0031.204
(19) Detour Length 199 km
(20) Toll 3
(26) Func Class 07
(28) Lanes on/under 0100
(29) ADT 1515
(30) Year of ADT 2007
(47) Total Horz Clearance 05.2 M
(100) Defense Hwy 0
(101) Parallel Str N
(102) Direction of Traffic 3
(104) Hwy System 0
(109) Truck Traffic 008
(110) Natl Truck Network No

General Data

(21) Maintenance Responsibility 01
(22) Owner 01
(31) Design Load 0
(33) Bridge Median 0
(34) Skew 00 deg
(35) Str Flared Yes
(37) Hist Significance 5
(38) Navigation Control 0
(42) Type of Service 15
(43) Structure Type Main 211
(44) Structure Type Approach 000
(45) No of Span Main 001
(46) No of Approach Spans 0000
(27) Year Built 1926
(106) Year Reconstructed 0000
(107) Deck Str Type 1
(108) Wear Surf/Protv Sys 600
(111) Nav Pier/Abut Protection

Dimensional Data

(32) Approach Rdwy Width 8.2 M
(39) Navigation Vert Clr 000.0 M
(40) Navigation Horz clr 0000.0 M
(48) Max Span Length 0025.3 M
(49) Str Length 00032.9 M
(50) Curb/Sidewalk Width Left 00.0 M
Right 00.0 M
(51) Brg Rdwy Width, curb-curb 005.2 M
(52) Deck Width out-out 006.1 M
(53) Min Vert Clr over 99.99 M
(54) Min Vert Clr under N 00.00 M
(55) Min Lat Underclr R N 00.0 M
(56) Min Lat Underclr L 99.9 M
(112) NBIS Bridge Length Y
(116) Navigation Min Vert Clr M

Proposed Improvements

(75) Type of Work 311
(76) Improvement Length 000399 M
(94) Bridge Improv Cost 2774
(95) Rdwy Improv Cost 0
(96) Total Proj Cost 4732
(97) Year of Cost Est 1999
(114) Future ADT 2150
(115) Year of Future ADT 2027

Condition Rating

(58) Deck 6
(59) Superstructure 6
(60) Substructure 6
(61) Channel & Channel Protect 7
(62) Culverts N

Appraisal Rating

(67) Structure Evaluation 4
(68) Deck Geometry 2
(69) Underclrn Vert & Horz N
(71) Waterway Adequacy 5
(72) Approach Rdwy Alignment 2
(36) Traffic Safety Features 0000

Scour Data

(113) Scour Critical Bridges 8
(202) Foundation Type
(220) Foundation Embedment 0.0 M
(221) Scour Countermeasures

Load Rate and Post

(41) Str Open/Post/Close Posted
(64) Operating Rating 29.0 ton
(66) Inventory Rating 17.2 ton
(70) Bridge Posting 4
(211) Posted Limit

(209) Str Name:

Princ Rte: 360 Milepost: 0.000

Proposed Maintenance

(212) Repair Priority
(213) Proposed Maint Type
(215) Maintn Date Completed / /
(216) Actual Maint Cost 0


Inspection Data

(90) Inspection Date (MoYr) 02/10
(91) Inspection Frequency 24 Mo
(92) Critical Feature Insp (93) Date
Frac Crit Insp : N /
Underwater Insp: N /
Other Spec Insp: N /
(207) Inspection Quarter 4
(208) Inspection Number
(210) Date of Inspection 12/15/1996
02/18/2010


Over 200 Items

(200) Princ Route Location
(201) Wear Surface Thickness 0.0 mm
(203) District Maint Org
(204) Original Proj #
(205) Station Princ Rte 0.000
(206) Bridge Rail Type
(217) Culvert Bbl Height 0.0 M
(218) Culvert Bbl Length 0.0 M
(219) Culvert Fill Height 0.0 M
(222) Date of Load Rating / /
(223) Tracs No
(224) Bridge Crew Region
(225) Total Deck Area (M^2) 0.0
(226) Superstr Unit Cost 0.00
(227) Substr Unit Cost 0.00
(228) Next Insp Due Date (QuartYr) 498
(229) Agency
(230) Principal Route Number 360
(231) Principal Route Letter
(232) Principal Route Milepost 0.000
(300) Comments:

Sufficiency Rating = 046.0
Functionly Obsolete



WAIKANI STREAM BRIDGE
 BRIDGE NO. 009003600501942




TYPICAL BRIDGE SECTION

WAIKANI STREAM BRIDGE
BRIDGE NO. 009003600501942

TO KAHULUI

TO HANA



UPSTREAM ELEVATION

WAIKANI STREAM BRIDGE
BRIDGE NO. 009003600501942

WAIKANI STREAM BRIDGE
PHOTO LOG
 Bridge No. 009003600501942

PHOTO NO.	DESCRIPTION*
1	KAHULUI APPROACH LOOKING TOWARD HANA
2	HANA APPROACH LOOKING TOWARD KAHULUI
3	UPSTREAM / KAHULUI CRM WALL
4	COLLISION DAMAGE WITH EXPOSED REBAR AT FORMER CONCRETE BRIDGE RAILING AT UPSTREAM / KAHULUI SIDE
5	DOWNSTREAM / KAHULUI GUARDRAIL TRANSITION AND CRM WALL. NOTE: GUARDRAIL TRANSITION HT = 34"
6	UPSTREAM / HANA CONCRETE PARAPET WITH COLLISION DAMAGE AND EXPOSED REBAR. NOTE: PARAPET HEIGHT VARIES DUE TO COLLISION DAMAGE
7	CLOSE UP OF COLLISION DAMAGE AT UPSTREAM / HANA CONCRETE PARAPET
8	DOWNSTREAM / HANA GUARDRAIL AND CRM WALL. NOTE: GUARDRAIL HT = 27"
9	UPSTREAM RAILING ELEVATION. NOTE: RAILING HT = 29"
10	PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION NEAR KAHULUI. NOTE: RAILING HT = 33"
11	PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION LOOKING TOWARD HANA
12	PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION NEAR HANA
13	CLOSE UP OF SPALL WITH EXPOSED REBAR IN DOWNSTREAM RAILING CAP
14	DELAMINATION ON SECOND PICKET AT DOWNSTREAM / KAHULUI RAILING
15	OVERALL A.C. PAVEMENT LOOKING TOWARD HANA
16	DECK DRAIN ALONG DOWNSTREAM RAILING
17	UPSTREAM ELEVATION AND UTILITY LINE ALONG BASE OF RAILING
18	DOWNSTREAM ELEVATION
19	DELAMINATION (1' (H) X 3' (W)) IN DOWNSTREAM FACE OF ARCH RIB UNDER DOWNSTREAM / HANA SPANDREL COLUMN
20	OVERALL SOFFIT VIEW LOOKING TOWARD KAHULUI
21	SOFFIT VIEW NEAR KAHULUI END OF BRIDGE
22	SOFFIT VIEW OF CENTER OF BRIDGE

WAIKANI STREAM BRIDGE**PHOTO LOG**

Bridge No. 009003600501942

PHOTO NO.	DESCRIPTION*
23	SOFFIT VIEW NEAR HANA END OF BRIDGE
24	PATCHES IN SOFFIT NEAR HANA END
25	PATCHES IN SOFFIT BETWEEN SPANDREL BENT 1 AND 2. NOTE: SPANDREL COUNT STARTS FROM HANA ABUTMENT.
26	KAHULUI ABUTMENT
27	HANA ABUTMENT
28	SMALL SPALL WITH EXPOSED REBAR ON HANA FACE OF UPSTREAM SPANDREL COLUMN IN SPANDREL BENT 1.
29	UPSTREAM VIEW FROM TOP OF BRIDGE
30	UPSTREAM VIEW FROM UNDER BRIDGE
31	DOWNSTREAM VIEW FROM TOP OF BRIDGE
32	DOWNSTREAM VIEW FROM UNDER BRIDGE

NOTE: * (H) = HEIGHT; (W) = WIDTH



PHOTO 1 KAHULUI APPROACH LOOKING TOWARD HANA



PHOTO 2 HANA APPROACH LOOKING TOWARD KAHULUI



PHOTO 3 UPSTREAM / KAHULUI CRM WALL



PHOTO 4 COLLISION DAMAGE WITH EXPOSED REBAR AT FORMER CONCRETE BRIDGE RAILING AT UPSTREAM / KAHULUI SIDE



PHOTO 5 DOWNSTREAM / KAHULUI GUARDRAIL TRANSITION AND CRM WALL. NOTE: GUARDRAIL TRANSITION HT = 34"



PHOTO 6 UPSTREAM / HANA CONCRETE PARAPET WITH COLLISION DAMAGE AND EXPOSED REBAR. NOTE: PARAPET HEIGHT VARIES DUE TO COLLISION DAMAGE



PHOTO 7 CLOSE UP OF COLLISION DAMAGE AT UPSTREAM / HANA CONCRETE PARAPET



PHOTO 8 DOWNSTREAM / HANA GUARDRAIL AND CRM WALL. NOTE: GUARDRAIL HT = 27"



PHOTO 9 UPSTREAM RAILING ELEVATION. NOTE: RAILING HT = 29"



PHOTO 10 PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION NEAR KAHULUI.
NOTE: RAILING HT = 33"



PHOTO 11 PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION LOOKING TOWARD HANA



PHOTO 12 PARTIAL VIEW OF DOWNSTREAM RAILING ELEVATION NEAR HANA



PHOTO 13 CLOSE UP OF SPALL WITH EXPOSED REBAR IN DOWNSTREAM RAILING CAP



PHOTO 14 DELAMINATION ON SECOND PICKET AT DOWNSTREAM / KAHULUI RAILING



PHOTO 15 OVERALL A.C. PAVEMENT LOOKING TOWARD HANA



PHOTO 16 DECK DRAIN ALONG DOWNSTREAM RAILING



PHOTO 17 UPSTREAM ELEVATION AND UTILITY LINE ALONG BASE OF RAILING



PHOTO 18 DOWNSTREAM ELEVATION



**PHOTO 19 DELAMINATION (1' (H) X 3' (W)) IN DOWNSTREAM FACE OF ARCH RIB UNDER
DOWNSTREAM / HANA SPANDREL COLUMN**



PHOTO 20 OVERALL SOFFIT VIEW LOOKING TOWARD KAHULUI



PHOTO 21 SOFFIT VIEW NEAR KAHULUI END OF BRIDGE



PHOTO 22 SOFFIT VIEW OF CENTER OF BRIDGE



PHOTO 23 SOFFIT VIEW NEAR HANA END OF BRIDGE



PHOTO 24 PATCHES IN SOFFIT NEAR HANA END



PHOTO 25 PATCHES IN SOFFIT BETWEEN SPANDREL BENT 1 AND 2. NOTE: SPANDREL COUNT STARTS FROM HANA ABUTMENT.



PHOTO 26 KAHULUI ABUTMENT



PHOTO 27 HANA ABUTMENT



PHOTO 28 SMALL SPALL WITH EXPOSED REBAR ON HANA FACE OF UPSTREAM SPANDREL COLUMN IN SPANDREL BENT 1.



PHOTO 29 UPSTREAM VIEW FROM TOP OF BRIDGE



PHOTO 30 UPSTREAM VIEW FROM UNDER BRIDGE



PHOTO 31 DOWNSTREAM VIEW FROM TOP OF BRIDGE



PHOTO 32 DOWNSTREAM VIEW FROM UNDER BRIDGE

ROUTINE (PERIODIC) BRIDGE INSPECTION REPORT

WAIOKAMILO STREAM BRIDGE

BRIDGE NO. 009003600501811

MAUI, HAWAII



For

State of Hawaii
Department of Transportation
Highways Division

Prepared by

Nagamine Okawa Engineers Inc.
1003 Bishop Street
Suite 2025
Honolulu, Hawaii 96813
Telephone: (808) 536-2626

FEBRUARY 2010

STATE OF HAWAII
DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

NBI BRIDGE INSPECTION REPORT

Date of Inspection	<u>2/18/10</u>	Bridge Name	<u>Waiokamilo Stream Bridge</u>
Bridge Number	<u>009003600501811</u>	Route No.	<u>360</u>
Number of Spans	<u>1</u>	Highway	<u>Hana Highway</u>
Location: Island	<u>Maui</u>	Milepost	<u>18.07</u>
Feature Intersected	<u>Waiokamilo Stream</u>	Substructure	<u>Reinf Conc / CRM</u>
Bridge Material:	Superstructure <u>Reinforced Concrete</u>		

Condition Rating		Remarks
36	TRAFFIC SAFETY FEATURES	Indicate if feature meets currently acceptable standards. 0 - No 1 - Yes N - Not Applicable
1.	Bridge Railings	0
2.	Transitions	0
3.	Approach Guardrail	0
4.	Approach Guardrail Ends	0
		1. Bridge railing does not meet acceptable standards.
		3. No approach guardrails Wailuku end of bridge.

58	DECK	
1.	Wearing Surface	7
2.	Decks - Structural Condition	7
3.	Curbs	N
4.	Median	N
5.	Sidewalks	N
6.	Parapet	N
7.	Railing	7
8.	Paint	4
9.	Drains	N
10.	Lighting Standards	N
11.	Utilities	7
12.	Joint Leakage	N
13.	Expansion Joints or Devices	N
	Inspector's Condition Rating	7
		8. This rating is for paint on railings.

59	SUPERSTRUCTURE	
1.	Bearing Devices	N
2.	Stringers	N
3.	Girders, Beams, or Arches	5
4.	Floor Beams and Diaphragms	N
5.	Trusses -General	N
	-Portals	N
	-Bracing	N
6.	Paint	N
7.	Machinery (Moveable Spans)	N
8.	Rivets and/or Bolts	N
9.	Welds - Cracks	N
10.	Rust	N
11.	Timber Decay	N
12.	Concrete Cracking and/or Spalling	5
13.	Collision Damage	8
14.	Deflection Under Load	7
15.	Alignment of Members	8
16.	Vibrations Under Load	7
17.	Flat Slab	N
	Inspector's Condition Rating	5
		3. Delaminations, spalls with exposed rebar, water stains, and vegetation growing from girders.
		12. See Item 59.3

Date of Inspection 2/18/10 Bridge name Waiokamilo Stream Bridge
 Bridge Number 009003600501811

		Condition Rating	Remarks
60	SUBSTRUCTURE		
1.	Abutment		
	-Wings	6	Minor cracks in abutment wingwalls.
	-Backwall/Breastwall	7	
	-Footing	N	Abutment bears on solid rock base.
	-Piles	N	
	-Erosion	6	Roadway run-off has undermined upstream Hana wingwall.
	-Settlement	7	
2.	Piers or Bents		
	-Caps	N	
	-Column/Wall	N	
	-Footing	N	
	-Piles	N	
	-Scour	N	
	-Settlement	N	
3.	Pile bents	N	
4.	Concrete Cracking and/or Spalling	6	4. See Item 60.1
5.	Steel Corrosion	N	
6.	Timber Decay, etc.	N	
7.	Debris on Seats	7	
8.	Paint	N	
9.	Collision Damage	8	
	Inspector's Condition Rating	7	

61 CHANNEL & CHANNEL PROTECTION

1.	Channel Scour	7
2.	Embankment Erosion	7
3.	Drift	7
4.	Vegetation	7
5.	Channel Change	7
6.	Fender System	N
7.	Spur Dikes & Jetties	N
8.	Rip Rap	N
9.	Adequacy of Opening	7
	Inspector's Condition Rating	7

62 CULVERT & RETAINING WALLS

1.	Barrel	
	-Concrete	N
	-Steel	N
	-Timber	N
2.	Headwall	N
3.	Cutoff Wall	N
4.	Adequacy	N
5.	Debris	N
	Inspector's Condition Rating	N

Date of Inspection 2/18/10 Bridge Name Waiokamilo Stream Bridge
Bridge Number 009003600501811

93	CRITICAL FEATURE INSPECTION DATE	Provide date if applicable. If not applicable, indicate with N.
1.	Fracture Critical Details	<u>N</u>
2.	Underwater Inspection	<u>N</u>
3.	Other Special Inspection	<u>N</u>

[If applicable, submit Underwater Inspection Report]

OTHER FEATURES	Y - Yes	N - No	Remarks
1. Bridge Posted?	<u>Y</u>		Posted Limit = <u>10 Tons</u> (See comment below)
2. Signage for Posting Legible/Visible?	<u>N</u>		
3. Riding Surface (Roughness) Rating	<u>N</u>		3 - Smooth, 2 - Average, 1 - Poor



1. 10-ton posted load limit on Hana Bridges at both ends of Hana Hwy. No posting at the bridge.

REPAIRS AND IMPROVEMENTS

- List all work done to this bridge since the last inspection including cost.
None.
- Indicate proposed and/or recommended improvements including estimated cost.
 - Remove vegetation from bridge and shoulder (Maintenance Item)
 - Upgrade bridge railing and provide guardrails (Est. cost = \$11,000)
 - Repair delamination and spalls on girders (Est. cost = \$9,000)
 - Repair honeycombing in abutment walls (Est. cost = \$4,000)
 - Repair undermined CRM wall footing and divert roadway run-off away from CRM wingwall footing (Est. cost = \$11,000)
 - Seal crack in girder (Est. cost = \$6,000)
- List any existing temporary conditions.
None.

REMARKS AND RECOMMENDATIONS

- Does this bridge require inspection by Bridge Design Section? Yes _____ No X
[This should only be addressed by in-house inspectors who are not structural engineers.]
- Remarks: Describe defects. Use sketches, diagrams and/or photographs where possible.

Inspected by:	Name (printed):	<u>Garrett Nago & Robin Okawa</u>	Certified
	Signature:	<u></u>	Bridge Inspector
	Phone Number:	<u>808.536.2626</u>	
Supervised by:	Name (printed):	<u>Dwight Okawa, S.E.</u>	Title: <u>V.P.</u>
	Signature:	<u></u>	
	Phone Number:	<u>808.536.2626</u>	

STATE OF HAWAII DEPARTMENT OF TRANSPORTATION
PONTIS BRIDGE INSPECTION REPORT

r10/8/07

Date of Inspection <u>2/18/10</u>	Bridge Name <u>Waiokamilo Stream Bridge</u>
Bridge Number <u>009003600501811</u>	Route No. <u>360</u>
Number of Spans <u>1</u>	Highway <u>Hana Highway</u>
Location: Island <u>Maui</u>	Feature Intersected <u>Waiokamilo Stream</u>

ELEM NO.	ELEMENT DESCRIPTION	ENV. (Note 1)	TOTAL QUANT.	UNIT	ST 1	ST 2	ST 3	ST 4	ST 5
13	DECK OR SLAB (Note 2)	2	864	SF.	864				
110	GIRDERS	2	192	LFT.	152	25	15		
215	ABUTMENTS	2	72	LFT.	62	10			
*	COLUMNS			EA.					
*	PIER WALL			LFT.					
*	PIER CAPS			LFT.					
301	JOINTS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)	2	72	LFT.		72			
331	BRIDGE RAILING	2	48	LFT.	48				
*	APPROACH SLABS			EA.					
*	BEARINGS (INSPECTOR NEEDS TO INPUT ELEM NO. & QTY.)			EA.					
*	CULVERT			LFT.					
*	SMART FLAG: STEEL FATIGUE			EA.					
*	SMART FLAG: PACK RUST			EA.					
*	SMART FLAG: DECK CRACKING (ON TOP OF DECK ONLY)			EA.					
359	SMART FLAG: SOFFIT OF CONC. DECK OR SLAB (THIS SMART FLAG IS MANDATORY IF DECK OR SLAB HAS AN A.C. OVERLAY).	2	1	EA.	1				
*	SMART FLAG: SETTLEMENT			EA.					
361	SMART FLAG: SCOUR	2	1	EA.	1				
*	SMART FLAG: TRAFFIC IMPACT (TRAFFIC IMPACT TO SUPERSTRUCTURE ONLY)			EA.					
*	SMART FLAG: SECTION LOSS			EA.					
OTHERS									

COMMENTS:

Note 1: For each element, the inspector shall code the type of environment from the following key:

Env 1: Benign & Low Env: Little or no env. conditions affecting deterioration. Past bridge inspections show that env. has caused little or no deterioration.

Env 2: Moderate: Moderate level of environmental influence or deterioration. Past bridge inspections show that environment has caused some deterioration.

Env 3: Severe: Severe level of environmental influence or deterioration. Past bridge inspections show that environment has caused significant.

Note 2: For DECKS ONLY: All quantity in one ST only. Deck/slab is rated from top of deck/slab only. Use soffit smart flag (elem 359) to rate soffit.

Use these revised Condition States for rating Concrete Decks/Slabs	
CS1	No patched areas, no potholes, no spalls and delams, etc.
CS2	Distressed areas are less than 2% of the total deck area.
CS3	Distressed areas are more than 2% but 10% or less of the total deck area.
CS4	Distressed areas are more than 10% but 25% or less of the total deck area.
CS5	Distressed areas are 25% or more of the total deck area.

Inspector's Name (printed): Garrett Nago & Robin Okawa
 Inspector's Name (signature): *Garrett Nago*
 Inspector's phone number: 808.536.2626

Title: Cert. Bridge Inspector

Supervisor's Name (printed): Dwight Okawa, S.E.
 Supervisor's Name (signature): *Dwight Okawa*

Title: V.P.

Geographic and Route Data

(1) State Hawaii
(2) District 20
(3) County Maui
(4) Place 99999
(6) Feature Under WAIOKAMILO STRM
(7) Facility on HANA HWY
(9) Location 0.02MI W/WAILUA HMSTD RD
(16) Latitude 20° 51' 06.00"
(17) Longitude 156° 08' 18.00"
(98) Border Bridge
(99) Border Bridge Str No
(103) Temporary Str

On and Under Record Data

(5) Inventory Route Route On
121003602
(10) Min Vert Clr 99.99 M
(11) Kilometerpoint 0029.080
(19) Detour Length 199 km
(20) Toll 3
(26) Func Class 07
(28) Lanes on/under 0200
(29) ADT 1515
(30) Year of ADT 2007
(47) Total Horz Clearance 06.8 M
(100) Defense Hwy 0
(101) Parallel Str N
(102) Direction of Traffic 2
(104) Hwy System 0
(109) Truck Traffic 00%
(110) Natl Truck Network No

General Data

(21) Maintenance Responsibility 01
(22) Owner 01
(31) Design Load 0
(33) Bridge Median 0
(34) Skew 00 deg
(35) Str Flared No
(37) Hist Significance 3
(38) Navigation Control 0
(42) Type of Service 15
(43) Structure Type Main 104
(44) Structure Type Approach 000
(45) No of Span Main 001
(46) No of Approach Spans 0000
(27) Year Built 1921
(106) Year Reconstructed 0000
(107) Deck Str Type 1
(108) Wear Surf/Protv Sys 600
(111) Nav Pier/Abut Protection

Dimensional Data

(32) Approach Rdwy Width 8.2 M
(39) Navigation Vert Clr 000.0 M
(40) Navigation Horz clr 0000.0 M
(48) Max Span Length 0006.1 M
(49) Str Length 00007.3 M
(50) Curb/Sidewalk Width Left 00.0 M
Right 00.0 M
(51) Brg Rdwy Width, curb-curb 010.4 M
(52) Deck Width out-out 011.0 M
(53) Min Vert Clr over 99.99 M
(54) Min Vert Clr under N 00.00 M
(55) Min Lat Underclr R N 00.0 M
(56) Min Lat Underclr L 99.9 M
(112) NBIS Bridge Length Y
(116) Navigation Min Vert Clr M

Proposed Improvements

(75) Type of Work 311
(76) Improvement Length 000134 M
(94) Bridge Improv Cost 898
(95) Rdwy Improv Cost 0
(96) Total Proj Cost 1415
(97) Year of Cost Est 1999
(114) Future ADT 2150
(115) Year of Future ADT 2027

Condition Rating

(58) Deck 7-6
(59) Superstructure 5-6
(60) Substructure 7
(61) Channel & Channel Protect 7
(62) Culverts N

Appraisal Rating

(67) Structure Evaluation 6
(68) Deck Geometry 6
(69) Underclrn Vert & Horz N
(71) Waterway Adequacy 5
(72) Approach Rdwy Alignment 4
(36) Traffic Safety Features 0000

Scour Data

(113) Scour Critical Bridges 8
(202) Foundation Type
(220) Foundation Embedment 0.0 M
(221) Scour Countermeasures

Load Rate and Post

(41) Str Open/Post/Close Posted
(64) Operating Rating 53.5 ton
(66) Inventory Rating 27.2 ton
(70) Bridge Posting 4
(211) Posted Limit

(209) Str Name:

Princ Rte: 360 Milepost: 0.000

Proposed Maintenance

(212) Repair Priority
(213) Proposed Maint Type
(215) Maintn Date Completed / /
(216) Actual Maint Cost 0


Inspection Data

(90) Inspection Date (MoYr) 02/10
-0200
(91) Inspection Frequency 24 Mo
(92) Critical Feature Insp (93) Date
Frac Crit Insp : N /
Underwater Insp: N /
Other Spec Insp: N /
(207) Inspection Quarter 4
(208) Inspection Number
(210) Date of Inspection 12/15/1996
02/18/2010

Over 200 Items


(200) Princ Route Location
(201) Wear Surface Thickness 0.0 mm
(203) District Maint Org
(204) Original Proj #
(205) Station Princ Rte 0.000
(206) Bridge Rail Type
(217) Culvert Bbl Height 0.0 M
(218) Culvert Bbl Length 0.0 M
(219) Culvert Fill Height 0.0 M
(222) Date of Load Rating / /
(223) Tracs No
(224) Bridge Crew Region
(225) Total Deck Area (M^2) 0.0
(226) Superstr Unit Cost 0.00
(227) Substr Unit Cost 0.00
(228) Next Insp Due Date (QuartYr) 498
(229) Agency
(230) Principal Route Number 360
(231) Principal Route Letter
(232) Principal Route Milepost 0.000
(300) Comments:

Sufficiency Rating = 070.1




BRIDGE DECK PLAN

WAIOKAMILO STREAM BRIDGE
 BRIDGE NO. 009003600501811




BRIDGE SOFFIT PLAN

WAIOKAMILO STREAM BRIDGE
BRIDGE NO. 009003600501811



BRIDGE SECTION
LOOKING TOWARD HANA

WAIOKAMILO STREAM BRIDGE
BRIDGE NO. 009003600501811



UPSTREAM ELEVATION

WAIOKAMILO STREAM BRIDGE
BRIDGE NO. 009003600501811

WAIOKAMILO STREAM BRIDGE**PHOTO LOG**

Bridge No. 009003600501811

PHOTO NO.	DESCRIPTION
1	APPROACH TO BRIDGE LOOKING TOWARD KAHULUI
2	APPROACH TO BRIDGE LOOKING TOWARD HANA
3	UPSTREAM HANA CRM WALL
4	UPSTREAM BRIDGE RAILING LOOKING TOWARD HANA
5	UPSTREAM KAHULUI CRM WALL
6	DOWNSTREAM KAHULUI CRM WALL
7	DOWNSTREAM BRIDGE RAILING LOOKING TOWARD HANA
8	DOWNSTREAM HANA CRM WALL
9	OVERALL VIEW OF AC PAVEMENT OVER BRIDGE
10	BACKSIDE OF UPSTREAM RAILING AND UTILITY PIPE
11	CLOSE UP OF UTILITY PIPE AND HANGERS ON UPSTREAM SIDE OF BRIDGE
12	UPSTREAM BRIDGE ELEVATION
13	DOWNSTREAM BRIDGE ELEVATION
14	DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD HANA
15	JOINT IN SOFFIT
16	UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI
17	6' DELAMINATION IN GIRDER G8
18	DELAMINATION AND UNSOUND PATCH IN GIRDERS G5 AND G6 NEAR KAHULUI ABUTMENT
19	SPALL WITH EXPOSED REBAR AND UNSOUND PATCH IN GRIDER G4
20	DELAMINATION AND VEGETATION GORWING IN GIRDERS G4 AND G5
21	DOWNSTREAM HALF OF KAHULUI ABUTMENT GIRDER SEAT
22	DOWNSTREAM HALF OF HANA ABUTMENT
23	UPSTREAM HALF OF HANA ABUTMENT
24	UNDERMINING AT UPSTREAM HANA CRM WALL
25	UPSTREAM HANA ABUTMENT GIRDER SEAT
26	LOOSE ROCKS IN UPSTREAM KAHULUI CRM WALL

WAIOKAMILO STREAM BRIDGE

PHOTO LOG

Bridge No. 009003600501811

PHOTO NO.	DESCRIPTION
27	UPSTREAM HALF OF KAHULUI ABUTMENT
28	DOWNSSTREAM HALF OF KAHULUI ABUTMENT
29	MINOR UNDERMINING AT DOWNSSTREAM END OF KAHULUI ABUTMENT
30	SPALL IN KAHULUI ABUTMENT UNDER GIRDERS G4 AND G5
31	UPSTREAM VIEW OF STREAM CHANNEL
32	DOWNSSTREAM VIEW OF STREAM CHANNEL



PHOTO 1 APPROACH TO BRIDGE LOOKING TOWARD KAHULUI



PHOTO 2 APPROACH TO BRIDGE LOOKING TOWARD HANA



PHOTO 3 UPSTREAM HANA CRM WALL



PHOTO 4 UPSTREAM BRIDGE RAILING LOOKING TOWARD HANA



PHOTO 5 UPSTREAM KAHULUI CRM WALL



PHOTO 6 DOWNSTREAM KAHULUI CRM WALL



PHOTO 7 DOWNSTREAM BRIDGE RAILING LOOKING TOWARD HANA



PHOTO 8 DOWNSTREAM HANA CRM WALL



PHOTO 9 OVERALL VIEW OF AC PAVEMENT OVER BRIDGE



PHOTO 10 BACKSIDE OF UPSTREAM RAILING AND UTILITY PIPE



PHOTO 11 CLOSE UP OF UTILITY PIPE AND HANGERS ON UPSTREAM SIDE OF BRIDGE



PHOTO 12 UPSTREAM BRIDGE ELEVATION



PHOTO 13 DOWNSTREAM BRIDGE ELEVATION



PHOTO 14 DOWNSTREAM HALF OF SOFFIT LOOKING TOWARD HANA



PHOTO 15 JOINT IN SOFFIT



PHOTO 16 UPSTREAM HALF OF SOFFIT LOOKING TOWARD KAHULUI



PHOTO 17 6' DELAMINATION IN GIRDER G8



PHOTO 18 DELAMINATION AND UNSOUND PATCH IN GIRDERS G5 AND G6 NEAR KAHULUI ABUTMENT



PHOTO 19 SPALL WITH EXPOSED REBAR AND UNSOUND PATCH IN GIRDER G4



PHOTO 20 DELAMINATION AND VEGETATION GROWING IN GIRDERS G4 AND G5



PHOTO 21 DOWNSTREAM HALF OF KAHULUI ABUTMENT GIRDER SEAT



PHOTO 22 DOWNSTREAM HALF OF HANA ABUTMENT



PHOTO 23 UPSTREAM HALF OF HANA ABUTMENT



PHOTO 24 UNDERMINING AT UPSTREAM HANA CRM WALL



PHOTO 25 UPSTREAM HANA ABUTMENT GIRDER SEAT



PHOTO 26 LOOSE ROCKS IN UPSTREAM KAHULUI CRM WALL



PHOTO 27 UPSTREAM HALF OF KAHULUI ABUTMENT



PHOTO 28 DOWNSTREAM HALF OF KAHULUI ABUTMENT



PHOTO 29 MINOR UNDERMINING AT DOWNSTREAM END OF KAHULUI ABUTMENT



PHOTO 30 SPALL IN KAHULUI ABUTMENT UNDER GIRDERS G4 AND G5



PHOTO 31 UPSTREAM VIEW OF STREAM CHANNEL




PHOTO 32 DOWNSTREAM VIEW OF STREAM CHANNEL