



(80 Mils Min. Thickness)

<sup>-</sup>2" HDPE Tunnel



DETAIL OF PANNING VERTICAL EDGE BATTENS Not to Scale



### Panning Installation Notes:

STATE

FED. ROAD DIST. NO.

- 1. Contractor shall thoroughly clean all surfaces where HDPE Panning will be installed.
- 2. Calcium Carbonate deposits (Stalagmites and Stalactites) shall be removed and cracks/leaks properly cleaned as directed by the Engineer. Cracks/leaks that are not panned off shall be sealed as directed by the Engineer.

FED. AID PROJ. NO.

HAW. | STP-063-1(22) | 2003


FISCAL YEAR

SHEET NO.

SHEETS

- 3. Bolt spacing across the panning panel width should begin approximately 4" from the panel edge or approximately 1/2 way within the panel overlap area.
- 4. Bolt spacing along the panning height width should begin approximately 4" from the top of the panel and extend downward with a bolt installed a maximum of 4" from the panel bottom.
- 5. 6" min. vertical overlap between sheets. Horizontal overlaps are not permitted. Overlapping sheets shall be sealed with adhesive sealant compatible with panning material.
- 6. Contractor shall verify and protect all plumbing, electrical, and mechanical items prior to applying waterproof membrane.
- 7. Exposed reinforcing bars should be cleaned to remove all traces of rust.


### AIR PLENUM DRAINAGE TROUGH




TUNNEL DRAIN DEMOLITION Scale: Not to Scale

1/4"ø Stainless Steel Anchor Bolts (Grade 316) 2-1/4" Long Spaced 18" Maximum Both Ways (See Notes 3 & 4)

> PANNING DETAIL Not to Scale





THIS WORK WAS PREPARED BY ME OR UNDER MY SUPERVISION AND CONSTRUCTION OF THIS PROJECT


EXPIRATION DATE OF THE LICENSE

DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION AIR PLENUM DRAINAGE DETAILS

LIKELIKE HIGHWAY

Wilson Tunnel Improvements Leak and Crack Remediation F. A. Project No. STP-063-1(22) Scale: As Shown


Date: April 24, 2003 SHEET No. C-16 OF 30 SHEETS



C/C

Limit of HDPE-

Panning Sheet




SIDEWALK DRAINAGE TROUGH

ORIGINAL SURVEY
PLAN DRAWN 1
NOTE BOOK DESIGNE
QUANTITY
No. CHECKEI


2. Cut-out and remove concrete 1 1/2"

3. Cut reinforcing bars as necessary.

deep by 4" wide for drainage trough.




#### **ELEVATION**



C-17

## POLYURETHANE GROUT LEAK SEALING


**SECTION** 



### PATCH FAILURE/SPALL REPAIR ALONG TUNNEL WALLS/PLENUM CEILING

Not To Scale

# **GRAPHIC SCALES:**



OR UNDER MY SUPERVISION AND CONSTRUCTION OF THIS PROJECT WILL BE UNDER MY OBSERVATION

\_\_\_\_ April 30, 2004 EXPIRATION DATE OF THE LICENSE

### DEPARTMENT OF TRANSPORTATION HIGHWAYS DIVISION

TUNNEL DRAINAGE DETAILS

LIKELIKE HIGHWAY Wilson Tunnel Improvements Leak and Crack Remediation F. A. Project No. STP-063-1(22) Scale: As Shown

Date: April 24, 2003 SHEET No. C-17 OF 30 SHEETS

FED. ROAD

clean and hard surface.

possible to the planned hole.

concrete surface.

recommendation.

DIST. NO.

STATE

Polyurethane Grout Leak Sealing Notes:

crack at an angle intersecting the crack

Clean crack, remove debris and efflorescence to

Drill 1/2" (max.) holes, 12" o.c. directly into the

approximately 6 inches behind the face of the

concrete. Drilled holes shall be alternating left

and right of the crack in a "stitching" pattern.

Flush drilled holes with water to clean hole and

verify adequacy of the connection between the

Inject grout into the lowest positioned hole first.

Grout drilled holes with Polyurethane grout until

If cracks are difficult to fill due to excessive

width, stop grouting and allow grout to set.

After grout sets, resume grouting procedure.

Inflow of water from cracks that were previously

dry shall be grouted with a waterproof grout if

inflow is determined to be unacceptable by the

Engineer. Contractor shall prepare surface and

install waterproof grout per manufacturers

Spall greater than 1/2" in depth shall be

sandblasted to provide clean surface and coat

matching the finish on the adjacent concrete.

Re-drill new holes as required.

Patch Failure/Spall Repair Notes:

with epoxy bonding compound.

2. Fill prepared area with low-shrink mortar

return is seen in the crack or the adjacent hole.

holes and return through the crack to the

If rebar is encountered, re-drill hole as close as

FISCAL YEAR

SHEETS

FED. AID

PROJ. NO.

HAW. | STP-063-1(22) | 2003

