ATTACHMENT A



August 6, 2021

State of Hawaii Department of Transportation Highways Division, Maui District 650 Palapala Drive, Kahului, Hawaii 96732

Attention: Mr. Ty Fukuroku

Subject: Limited Hazardous Materials Survey

State of Hawaii Department of Transportation Highways Division, Maui District Office

The following comprehensive report documents the limited hazardous materials activities performed at Department of Transportation Maui District Office, Kahului, Maui, Hawaii on July 23, 2021. ETC inspected the Subject Site for suspected asbestos-containing materials (ACM), lead-containing and lead-based paint (LCP & LBP), and arsenic-containing materials (AsM) as part of the State of Hawaii Department of Transportation, Highways Division Maui District Office renovations.

Laboratory analysis indicated the following to be asbestos-containing material:

- White joint compound on interior drywall walls contained 2% chrysotile.
- Grey caulking on interior window frames contained 20% chrysotile.
- Off-white skim coat on interior CMU walls contained 2% chrysotile.
- White joint compound on interior drywall ceiling of restroom ceilings contained 2% chrysotile.

Laboratory analysis indicated the following to be lead-containing paint:

- Purple paint on east drywall wall of the general office area was lead-containing.
- Light yellow paint in the of the shared gender restroom and throughout various offices was lead-containing.
- Navy blue paint on east drywall wall of the survey crew area was lead-containing.
- Grey paint on exterior textured concrete walls was lead-containing.
- White paint on exterior fascia was lead-containing.

Laboratory analysis indicated no arsenic-containing materials present at the time of the survey.

If you have any questions or desire further information, please feel free to contact me at 808-839-7222.



Respectfully,

EnviroServices & Training Center, LLC

Brian Carroll

Environmental Scientist

LIMITED HAZARDOUS MATERIALS SURVEY REPORT

State of Hawaii Department of Transportation Maui District Office 650 Palapala Drive Kahului, Maui, Hawaii 96732

Prepared for:

State of Hawaii Department of Transportation Highways Division, Maui District

650 Palapala Drive Kahului, Maui, Hawaii 96732

Prepared by:

ENVIROSERVICES & TRAINING CENTER, LLC

505 Ward Avenue, Suite 202 Honolulu, Hawaii 96814 tel: (808) 839-7222

ETC Project No. 19-3501

August 6, 2021

TABLE OF CONTENTS

1.0	CERTIFICATIONS AND LIMITATIONS	1
2.0	EXECUTIVE SUMMARY	2
2.1 2.2 2.3	SUMMARY OF ASBESTOS CONTAINING BUILDING MATERIALS SURVEY	2
3.0	INTRODUCTION/PURPOSE	4
4.0	METHODOLOGY	5
4.1 4.2 4.3	ASBESTOSLEAD PAINTARSENIC	5
5.0	RESULTS	6
5.1 5.2 5.3	ASBESTOSLEAD PAINTARSENIC	6
6.0	DISCUSSION AND RECOMMENDATIONS	8
APPE APPE	NDICES INDIX I: T INDIX II: LABORATORY ANALYTICAL RESULTS AND CHAIN-OI	F-CUSTODY FORMS
APPE	NDIX III: HOMOGE	ENEOUS AREA MAP

1.0 CERTIFICATIONS AND LIMITATIONS

EnviroServices & Training Center, LLC (ETC) has completed this Limited Hazardous Materials Survey (Survey) of the State of Hawaii Department of Transportation, Highways Division, Maui District (DOT), District Office, located at 650 Palapala Drive, Kahului, Maui, Hawaii (Subject Site). ETC's findings and recommendations contained herein are based on site observations, government regulations and laboratory data, which were gathered at the time and location of the study. Opinions stated in this report do not apply to changes that may have occurred after the services were performed.

ETC has performed specified services for this project with the degree of care, skill and diligence ordinarily exercised by professional consultants performing the same or similar services. No other warranty, guarantee, or representation, expressed or implied, is included or intended, unless otherwise specifically agreed to in writing by both ETC and ETC's Client.

This report is intended for the sole use of the DOT (Client), exclusively for the Subject Site. Client may use and release this report, including making and retaining copies, provided such use is limited to the Subject Site and project for which this report is provided. However, the services performed may not be appropriate for satisfying the needs of other users. Release of this report to third-parties will be at the sole risk of ETC's Client and/or said user, and ETC shall not be liable for any claims or damages resulting from or connected with such release or any third party's use or reuse of this report.

Surveyed By:

Dakota Holliman

State of Hawaii Asbestos Building Inspector #HIASB-5099 State of Hawaii Lead Based Paint Inspector #PB-1237

Surveyed and Prepared By:

Brian Carroll

State of Hawaii Asbestos Building Inspector # HIASB-4663 State of Hawaii Lead Based Paint Inspector # PB-1124

2.0 EXECUTIVE SUMMARY

ETC has conducted a Survey and compiled this report for the State of Hawaii Department of Transportation, Highways Division, Maui District (DOT) Office located at 650 Palapala Drive, Kahului, Hawaii, the Subject Site. The scope of services was limited to all interior and exterior building materials which could potentially be affected by future renovations as specified by Mr. Ty Fukuroku of the DOT Maui District Office. The following summarizes the results of ETC's survey on July 23, 2021.

2.1 Summary of Asbestos Containing Building Materials Survey

Four (4) materials sampled contained a non-regulated asbestos below the regulatory limit of 1% but above the laboratory's detection limit. The following table summarizes these findings.

Asbestos-Containing Materials

Homogeneous Area	Material	Asbestos Content	Estimated Quantity
Walls	Joint compound on drywall	2% Chrysotile	15,000 sq. ft.
Interior window frames	Grey caulking	20% Chrysotile	150 l.f.
Walls	Skim coat on CMU	2% Chrysotile	10,000 sq.ft.
Restroom ceilings	Joint compound on drywall	2% Chrysotile	400 sq.ft.

2.2 Summary of Lead Paint Survey

None of the sampled paint was found to contain lead in excess of the Environmental Protection Agency (EPA)/United States Department of Housing and Urban Development (HUD) guideline of 0.5 percent lead by weight, defining Lead-Based Paint (LBP).

Five (5) paints sampled were found to contain lead above the laboratory detection limit, but below the EPA/HUD guideline, classifying it as Lead-Containing Paint (LCP). The following table summarizes these findings.

Lead-Containing Paints

Location	Color	Substrate	Description	Estimated Quantity
General office E. wall	Purple	Drywall	Intact	400 sq. ft.
Throughout	Light yellow	Drywall/concrete	Intact	250 sq. ft.

Location	Color	Substrate	Description	Estimated Quantity
Survey crew area E. wall	Navy blue	Drywall	Intact	400 sq. ft.
Exterior walls	Grey	Concrete/CMU	Fair	15,000 sq. ft.
Roof - Fascia	White	Wood	Poor	3,000 sq. ft.

The remaining eleven (11) sampled paints did not contain detectable amounts of lead, classifying them as non-lead containing.

2.3 Summary of Arsenic Survey

ETC personnel identified, and sampled materials suspected of being treated with arsenic, from the Subject Site. None (0) of the sampled materials were found to contain levels of arsenic above the laboratory reporting limit of thirteen milligrams per kilogram (13 mg/kg), classifying them as non-arsenic containing.

3.0 INTRODUCTION/PURPOSE

The purpose of this Survey was to inspect the Subject Site for the presence of hazardous materials on the interior and exterior of the Maui District Office. Specifically, ETC completed the following tasks:

- Mobilized a State of Hawaii Department of Health (DOH)/ Environmental Protection Agency (EPA) certified asbestos building inspector and lead risk assessor to the Subject Site;
- Collected one hundred twenty (120) samples of forty (40) suspected asbestoscontaining materials (ACM) from the Subject Site and recorded the location of each material;
- Submitted the 120 samples of suspected ACM to Hawaii Analytical Laboratory (HAL) for asbestos analysis via Polarized Light Microscopy (PLM) in accordance with the National Institute for Occupational Safety and Health (NIOSH) Method 600/R -93/116;
- Collected sixteen (16) paint chip samples from the Subject Site;
- Submitted the 16 paint chip samples HAL for analysis by flame atomic absorption spectroscopy (FAAS) via EPA SW-846 Method 7420 for total lead content;
- Collected one (1) samples of suspected arsenic containing materials (AsCM) from the Subject Site;
- Submitted (1) samples of suspected AsCM to NVL Laboratories, Inc. (NVL) for analysis of total arsenic content via EPA Method 6010; and
- Prepared this report documenting the field activities and the results of the investigation including analytical results, conclusions, and recommendations.

4.0 METHODOLOGY

4.1 Asbestos

ETC personnel collected a total of one hundred twenty (120) samples of forty (40) suspected ACM for asbestos analysis. Samples were collected in accordance with EPA guidelines and recommendations.

The suspected ACM was wetted before sample collection. A small piece was then carefully cut out and placed into a labeled, re-sealable plastic bag. The sampling equipment was cleaned between each sample collection to avoid cross-contamination between samples. Sample locations were randomly selected in accordance with EPA protocols and recommendations.

Samples were properly logged and recorded following strict chain-of-custody procedure and submitted to HAL located in Honolulu, Hawaii for analysis by PLM in accordance with EPA Method 600/R-93/116. HAL is accredited for bulk asbestos analysis through successful participation in the National Voluntary Lab Accreditation Program (NVLAP).

4.2 Lead Paint

ETC personnel collected and had analyzed sixteen (16) paint chip sample from the Subject Site in accordance with the EPA guidelines and recommendations.

The suspected lead-containing paints were wetted with amended water before sample collection. Paint was carefully scraped and placed into a labeled re-sealable plastic bag. The sampling equipment was cleaned between each sample collection to avoid cross-contamination between samples.

Samples were properly logged and recorded following strict chain-of-custody procedure and submitted to HAL located in Honolulu, Hawaii for analysis by FAAS, in accordance with EPA Method 7420. HAL is an Environmental Lead Laboratory Accreditation Program (ELLAP)-accredited laboratory.

4.3 Arsenic

ETC personnel collected one (1) sample of materials suspected of being treated with arsenic, from the Subject Site. The suspected AsCM samples were collected in accordance with EPA guidelines and recommendations.

The suspected AsCM was wetted before sample collection. Small pieces were then carefully cut out and placed into a labeled, re-sealable plastic bag. The samples were logged and recorded following strict chain-of-custody procedure and submitted to NVL in Seattle, Washington for analysis by EPA Method 6010.

5.1 Asbestos

A total of one hundred twenty (120) suspect asbestos samples were collected from forty (40) suspected materials and submitted for analysis via PLM. Four (4) of the sampled materials were found to contain levels of asbestos above the regulatory limit of 1%. A detailed list of sampled materials and results can be found in Table 1 included in Appendix I.

In accordance with federal and state regulations, and industry standard practice, ETC determined homogeneous areas of each suspect material and collected multiple representative samples of the material from each homogeneous area by building and floor. Typically, all samples for a suspect material will have similar laboratory results. When the results differ, a single result above the regulatory limit is sufficient to determine that the material within the homogeneous area is ACBM and the entirety of the homogeneous area should be treated as ACBM. Thus, ETC may request that the laboratory stops analyzing when the first sample in the set is determined to have an asbestos content above one percent.

In addition, three (3) materials were found to contain fibrous glass at a concentration. It is ETC's recommendation to handle materials containing such fibers with appropriate protective equipment.

A detailed list of sampled asbestos and results can be found in Table 1 included in Appendix I.

Asbestos laboratory analytical results are included in Appendix II.

5.2 Lead Paint

None (0) of the paint samples were determined to contain lead in excess of the Environmental Protection Agency (EPA)/United States Department of Housing and Urban Development (HUD) guideline of 0.5% lead by weight defining Lead-Based Paint (LBP).

Five (5) of the sampled paints were found to contain detectable levels of lead less than the EPA/HUD guideline but greater than or equal to the reporting limit for the laboratory of 0.01% lead by weight, classifying them as Lead-Containing Paint (LCP).

The eleven (11) remaining sampled paint was not found to contain any detectable amounts of lead, classifying them as non-lead containing.

A detailed list of sampled paints and results can be found in Table 2 included in Appendix I.

Lead laboratory analytical results are included in Appendix II.

5.3 Arsenic

None (0) of the suspect arsenic-containing materials (AsCM) identified and sampled by ETC were found to contain arsenic.

A detailed list of sampled materials and results can be found in Table 3 included in Appendix I. Arsenic laboratory analytical results are included in Appendix II.

6.0 DISCUSSION AND RECOMMENDATIONS

The findings and recommendations of ETC's limited hazardous material survey extended only to those areas that were accessible at the time of the site reconnaissance. ETC collected samples from inconspicuous areas when possible. Any areas that were inaccessible either due to physical restraints (i.e. areas within walls, behind locked doors, beneath flooring materials, hidden materials, etc.) or occupancy are not covered under the scope of this survey and should be evaluated for hazardous materials separately prior to any disturbance.

Based on ETC's visual inspection of the Subject Site and laboratory data, ETC recommends the following:

- Any materials at the Subject Site that are suspected to contain a hazardous contaminant but was not tested as part of this survey should be tested prior to disturbance.
- Manage and/or remove and dispose of hazardous and regulated materials in accordance with applicable federal, state, and local regulations, prior to renovation and/or demolition activities that may disturb these materials.
- Handle materials containing Wollastonite and/or glass fibers with appropriate protective equipment to prevent inhalation or ingestion of fibers and contact with skin and mucous membranes.
- Remove and dispose of all loose and flaking (poor condition) LCP that may be disturbed during renovation/demolition activities in accordance with applicable federal, state, and local regulations. Note that conditions of paint may have changed since the time of this survey.
- All waste and debris generated from the removal of LCP must either be recycled in accordance with applicable regulatory requirements, where available (e.g. metal components), or undergo Toxicity Characteristic Leaching Procedure (TCLP)-Lead analysis prior to disposal.
- Retain the services of a qualified consultant to monitor and inspect the removal activities to ensure compliance with specifications and applicable EPA, OSHA, and HIOSH regulations pertaining to the handling of asbestos-containing materials and lead-containing paint.
- Conduct air monitoring for asbestos fibers and lead dust by qualified personnel during abatement and general renovation/demolition activities of areas that were determined to contain these contaminants.
- Handle materials containing <1% asbestos with the same care and appropriate protective equipment as regulated asbestos containing materials to prevent inhalation or ingestion of fibers and contact with skin and mucous membranes.

Appendix I

TABLES OF RESULTS

Table 1 Maui District Office Asbestos Survey Results

Sample ID	Homogeneous Area	Material	Condition	Category	Friability	Asbestos Content	Estimated Quantity	
1901-M-A01						ND	<u></u>	
1901-M-A02	Floor	1x1' speckled	Damaged	Misc	N/A	ND	10,000 sq. ft.	
1901-M-A03	throughout	grey VFT	8			ND	1	
1901-M-A04		4" grey cove				ND*		
1901-M-A05	Base of walls	base with	Damaged	Misc	N/A	ND*	500 l.f	
1901-M-A06		mastic	C			ND*		
1901-M-A07		Joint				< 1 to 2% Chrysotile		
1901-M-A08	Walls	compound on	Good	Misc	NF1	NA	15,000 sq ft	
1901-M-A09		drywall			NA			
1901-M-A10						ND		
1901-M-A11	Walls	Concrete	Good	Misc N	N/A	ND	10,000 sq ft	
1901-M-A12					ND	, 1		
1901-M-A13						ND		
1901-M-A14	Door frames	White caulking	Good	Misc	N/A	ND	700 l.f.	
1901-M-A15	1	_				ND		
1901-M-A16	Interior					20% Chysotile		
1901-M-A17	window frames	Grey caulking	Good	Misc	NF1	NA	150 l.f.	
1901-M-A18	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					NA		
1901-M-A19		Skim coat on				2% Chrysotile	10,000 sq. ft.	
1901-M-A20	Walls	CMU	Good	Misc	NF1	NA		
1901-M-A21		Civio				NA		
1901-M-A22]	2'x4' acoustic			N/A	ND*	10,000 sq. ft.	
1901-M-A23	Drop ceiling	tile	Good	Misc		ND*		
1901-M-A24		tiic				ND*		
1901-M-A25]					ND*		
1901-M-A26	Plennum	Duct insulation	Fair	TSI	N/A	ND*	20 l.f.	
1901-M-A27						ND*		
1901-M-A28	Various offices -	4" brown cove				ND		
1901-M-A29	Base of walls	base with	Damaged	Misc	N/A	ND	500 l.f.	
1901-M-A30	Base of walls	mastic				ND		
1901-M-A31						ND		
1901-M-A32	Floor	Concrete	Damaged	Misc	N/A	ND	2,000 sq. ft.	
1901-M-A33						ND		
1901-M-A34	Men's Restroom					ND		
1901-M-A35		Misc	N/A	ND	100 sq. ft.			
1901-M-A36	hallway					ND		
1901-M-A37	Men's Restroom	4x4" white				ND		
1901-M-A38	S. entrance	CWT	Good	Misc	N/A	ND	100 sq. ft.	
1901-M-A39	hallway	C VV I				ND		

Table 1 Maui District Office Asbestos Survey Results

Sample ID	Homogeneous Area	Material	Condition	Category	Friability	Asbestos Content	Estimated Quantity		
1901-M-A40	S. Hallway					ND			
1901-M-A41	Restrooms	White caulking	Damaged	Misc	N/A	ND	50 l.f.		
1901-M-A42	Restrooms					ND			
1901-M-A43	S. Hallway					ND			
1901-M-A44	Restrooms	White caulking	Damaged	Misc	N/A	ND	50 l.f.		
1901-M-A45	Restrooms					ND			
1901-M-A46	Shared gender	Joint				< 1 to 2% Chrysotile			
1901-M-A47	restroom -	compound on	Good	Misc	NF1	NA NA	400 sq. ft.		
1901-M-A48	Ceiling	drywall				NA			
1901-M-A49	Lab/survey/					ND			
1901-M-A50	break area -	Beige caulking	Damaged	Misc	N/A	ND	50 l.f.		
1901-M-A51	Countertop					ND			
1901-M-A52								ND	
1901-M-A53	Ext. Walkway	Concrete	Damaged	Misc	N/A	ND	1,000 sq. ft.		
1901-M-A54						ND	_		
1901-M-A55	Ext. Ctm. etc					ND			
1901-M-A56	Ext. Structural	pillars Concrete Damaged Misc	N/A	ND	750 sq. ft.				
1901-M-A57	piliais	pinars		Ī	ND				
1901-M-A58		Ext. Walls Textured concrete				ND	2,000 sq. ft.		
1901-M-A59	Ext. Walls		Damaged	Damaged Misc	Isc N/A	ND			
1901-M-A60		Concrete				ND			
1901-M-A61	Ext. Extruding					ND			
1901-M-A62	window sections	Concrete	Damaged	Misc	N/A	ND	300 sq. ft.		
1901-M-A63	willdow sections					ND			
1901-M-A64	Ext. Mechanical	Decorative				ND			
1901-M-A65	enclosure	CMU	Good	Misc	N/A	ND	500 sq. ft.		
1901-M-A66	Chelosure	CIVIO				ND			
1901-M-A67	Ext. Roof				l	ND			
1901-M-A68	overhang	Plaster	Damaged	Misc	N/A	ND	400 sq. ft.		
1901-M-A69	overnang					ND			
1901-M-A70	Women's					ND			
1901-M-A71	restroom - Floor	1x1" grey CFT	Good	Misc	N/A	ND	100 sq. ft.		
1901-M-A72	restroom ricor					ND			
1901-M-A73	Women's	4x4" white			[ND			
1901-M-A74	restroom - Wall	CWT	Good	Misc	N/A	ND	100 sq. ft.		
1901-M-A75	TOTAL TOTAL					ND			
1901-M-A76		O-ring spacer				ND	_		
1901-M-A77	Roof - Bolts	with	Damaged	Misc	N/A	ND	5 sq. ft.		
1901-M-A78		waterproofing				ND			

Table 1 Maui District Office Asbestos Survey Results

Sample ID	Homogeneous Area	Material	Condition	Category	Friability	Asbestos Content	Estimated Quantity	
1901-M-A79						ND	2	
1901-M-A80	Roof - Fall	White caulking	Damaged	Misc	N/A	ND	10 sq. ft.	
1901-M-A81	protection latch		J			ND	1	
1901-M-A82						ND		
1901-M-A83	Roof - Weather	Black caulking	Damaged	Misc	N/A	ND	50 l.f.	
1901-M-A84	station					ND		
1901-M-A85	D 0 D1 1					ND		
1901-M-A86	Roof - Black	White caulking	Damaged	Misc	N/A	ND	100 l.f.	
1901-M-A87	solar panel		C			ND		
1901-M-A88					1	ND		
1901-M-A89	Roof - Vent	Black caulking	Damaged	Misc	N/A	ND	50 l.f.	
1901-M-A90						ND		
1901-M-A91	D C D1 1					ND		
1901-M-A92	Roof - Black	Foam insulation	Damaged	TSI	N/A	ND	5 sq. ft.	
1901-M-A93	solar panel pipes					ND		
1901-M-A94	D 0 D:				1	ND		
1901-M-A95	Roof - Pipe	Black caulking	Damaged	Misc	N/A	ND	50 l.f.	
1901-M-A96	penetrations	_			1	ND		
1901-M-A97	D C C :					ND		
1901-M-A98	Roof - Spine	White caulking	Damaged	Misc	N/A	ND	100 l.f.	
1901-M-A99	flashing					ND		
1901-M-A100	E . M 1 1 1					ND		
1901-M-A101	Ext. Mechanical	Grout Damaged	aged Misc	N/A	ND	20 1.f.		
1901-M-A102	area - Beams		_			ND		
1901-M-A103	E-4 M - 1 1		Damaged Misc			ND		
1901-M-A104	Ext. Mechanical enclosure	Concrete		N/A	ND	50 sq. ft.		
1901-M-A105	enciosure				1	ND		
1901-M-A106	E-4 Madaalaa					ND		
1901-M-A107	Ext. Mechanical	Foam insulation	Damaged	TSI	N/A	ND	20 sq. ft.	
1901-M-A108	enclosure					ND		
1901-M-A109	E-4 M - 1 1					ND		
1901-M-A110	Ext. Mechanical enclosure	Grey caulking	Damaged	Misc	N/A	ND	20 l.f.	
1901-M-A111	enciosure					ND		
1901-M-A112		4" grey cove				ND		
1901-M-A113	Lobby area	base with	Good	Misc	N/A	ND	50 sq. ft.	
1901-M-A114		mastic				ND	<u>] </u>	
1901-M-A115	Shared					ND		
1901-M-A116	Restroom	1x1" grey CFT	Good	Misc	N/A	ND	50 sq. ft.	
1901-M-A117	Kesitooiii	100111			<u> </u>	ND		
1901-M-A118	Shared	2"x/4" cmax				ND		
1901-M-A119	Restroom	2"x4" grey CWT	Good	Misc	N/A	ND	25 l.f.	
1901-M-A120	Keshoom	C VV I				ND	<u></u>	

Table 2 Maui District Office Lead Survey Results

Sample ID	Int/Ext	Homogeneous Areas	Color	Substrate	Condition	Laboratory Reporting Limit (mg/kg)	Results (mg/kg)
1901-M-L01	Int	Throughout - Walls	Light pink	Drywall	Intact	44	BRL
1901-M-L02	Int	Throughout - Doors	Pink	Wood/Drywall	Intact	120	BRL
1901-M-L03	Int	General office E. wall	Purple	Drywall	Intact	40	440*
1901-M-L04	Int	Lobby area	White	Drywall	Intact	40	BRL
1901-M-L05	Int	Throughout	Light yellow	Drywall/Concrete	Intact	44	210*
1901-M-L06	Int	Throughout	Tan	Drywall/Concrete/CMU	Intact	40	BRL
1901-M-L07	Int	Throughout	Off-white	Drywall/Concrete/CMU	Intact	43	BRL
1901-M-L08	Int	Throughout - Walls	Light blue	Drywall/Concrete/CMU/wood	Intact	40	BRL
1901-M-L09	Int	Throughout - Doors	Blue	Wood/Drywall	Intact	56	BRL
1901-M-L10	Int	Survey area E. wall	Navy blue	Drywall	Intact	46	290*
1901-M-L11	Int	Manager's office E. wall	Brown	Drywall	Intact	40	BRL
1901-M-L12	Int	Manager's office walls	Salmon	Drywall	Intact	40	BRL
1901-M-L13	Ext	Walls	Grey	Concrete/CMU	Fair	40	74*
1901-M-L14	Ext	Structural pillars	Dark brown	Concrete	Fair	40	BRL
1901-M-L15	Ext	Roof - Fascia	White	Wood	Poor	40	450*
1901-M-L16	Ext	Roof - Vent	Faded white	Metal	Poor	40	BRL

Table 3 Maui District Office Arsenic Survey Results

Sample ID	Homogeneous Area	Material	Condition	Arsenic Content (mg/kg)	Estimated Quantity
1091-M-AS01	Drop ceiling	Canec tile	Good	BRL	10000 sq.ft.

Appendix II

LABORATORY ANALYTICAL RESULTS AND CHAIN-OF-CUSTODY FORMS



Hawaii Analytical Laboratory ANALYTICAL REPORT

Wednesday, July 28, 2021

EnviroServices & Training Center, LLC 505 Ward Avenue, Suite 202 Honolulu HI 96814

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	tion		
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v Matrix	Date Analyzed
202143099	1901-M-A01		NONE DETECTED		None detected	Tar + vinyl	7/27/2021
<u>Layer</u>	Black mastic (limited)						
Comments							
202143099	1901-M-A01		NONE DETECTED		None detected	Vinyl	7/27/2021
<u>Layer</u>	Gray vinyl floor tile						
Comments							
202143100	1901-M-A02		NONE DETECTED		None detected	Vinyl + other	7/27/2021
<u>Layer</u>	Gray cove base						
Comments							
202143100	1901-M-A02		NONE DETECTED		None detected	Binder + other	7/27/2021
<u>Layer</u>	Yellow mastic						
Comments							
202143101	1901-M-A03		NONE DETECTED		None detected	Vinyl	7/27/2021
<u>Layer</u>	Gray vinyl floor tile						
Comments							
202143102	1901-M-A04		NONE DETECTED		None detected	Vinyl + other	7/27/2021
<u>Layer</u>	Gray cove base						
Comments							

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bulk	Asbes	tos Dete	rmina	tion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143102	1901-M-A04		NONE DETECTED		Wollastonite (+/- optical	5	Binder + other	7/27/2021
<u>Layer</u> Comments	Yellow mastic				sign)			
202143103	1901-M-A05		NONE DETECTED		None detected		Vinyl + other	7/27/2021
<u>Layer</u> Comments	Gray cove base							
202143103	1901-M-A05		NONE DETECTED		Wollastonite (+/- optical	5	Binder + other	7/27/2021
<u>Layer</u> Comments	Yellow mastic				sign)			
202143104	1901-M-A06		NONE DETECTED		None detected		Vinyl + other	7/27/2021
<u>Layer</u> Comments	Gray cove base							
202143104	1901-M-A06		NONE DETECTED		Wollastonite (+/- optical	5	Binder + other	7/27/2021
<u>Layer</u> Comments	Yellow / brown mastic				sign)			
202143105	1901-M-A07		NONE DETECTED		Cellulose (undulose) +	15	Gypsum	7/27/2021
<u>Layer</u>	White drywall				fibrous glass (amorphous)			
Comments								
202143105	1901-M-A07	Yes	Chrysotile	< 1	None detected		Calcite + paint	7/27/2021
<u>Layer</u> Comments	White joint compound / beige paint						1	
202143105	1901-M-A07	Yes	Chrysotile	< 1	Cellulose	5	Calcite	7/27/2021
<u>Layer</u>	White joint compound / paper	163	Only young	• •	(undulose)	3	Calono	1/21/2021
Comments	TTIME JOINT COMPOUND 7 PUPCI							

Facsimile: (808) 839-4455

(808)839-7222

Email: -

Phone Number:

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bulk	Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143106	1901-M-A08		NONE DETECTED		Cellulose (undulose) +	15	Gypsum	7/27/2021
<u>Layer</u>	White drywall				fibrous glass (amorphous)			
Comments								
202143106	1901-M-A08	Yes	Chrysotile	2	None		Calcite +	7/27/2021
<u>Layer</u>	White joint compound / beige paint				detected		paint	
Comments								
202143107 <u>Layer</u>	1901-M-A09 NOT ANALYZED DUE TO STOP ANALYSIS							
Comments								
202143108	1901-M-A10		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143108	1901-M-A10		NONE DETECTED		None detected		Gypsum + calcite +	7/27/2021
<u>Layer</u>	White texture / white paint						quartz + paint	
Comments								
202143109	1901-M-A11		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143109	1901-M-A11		NONE DETECTED		None detected		Gypsum + calcite +	7/27/2021
<u>Layer</u>	White texture / white paint						quartz + paint	
Comments								
202143110	1901-M-A12		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u>	<u>Gray concrete</u>							
Comments								

EnviroServices & Training Center, LLC 505 Ward Avenue, Suite 202

Honolulu HI 96814

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bulk	Asbes	tos Dete	rmina	tion		
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v Matrix	Date Analyzed
202143110	1901-M-A12		NONE DETECTED		None detected	Gypsum + calcite +	7/27/2021
<u>Layer</u>	White texture / white paint					quartz + paint	
Comments							
202143111	1901-M-A13		NONE DETECTED		None detected	Binder + paint	7/27/2021
<u>Layer</u>	White caulking / off-white paint						
Comments							
202143112	1901-M-A14		NONE DETECTED		None detected	Binder + paint	7/27/2021
<u>Layer</u>	White caulking / off-white paint						
Comments							
202143113	1901-M-A15		NONE DETECTED		None detected	Binder + paint	7/27/2021
<u>Layer</u>	White caulking / off-white paint						
Comments							
202143114	1901-M-A16	Yes	Chrysotile	20	None detected	Binder + other	7/27/2021
<u>Layer</u>	Gray caulking / off-white paint				detected	otner	
Comments							
202143115	1901-M-A17						
<u>Layer</u>	NOT ANALYZED DUE TO STOP ANALYSIS						
Comments							
202143116	1901-M-A18						
<u>Layer</u>	NOT ANALYZED DUE TO STOP ANALYSIS						
Comments							
202143117	1901-M-A19		NONE DETECTED		None detected	Cementitious	7/27/2021
<u>Layer</u>	Gray concrete						
Comments							

EnviroServices & Training Center, LLC 505 Ward Avenue, Suite 202

Honolulu HI 96814

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bulk	Asbes	tos Dete	rminat	tion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143117	1901-M-A19	Yes	Chrysotile	2	None detected		Calcite + paint + other	7/27/2021
<u>Layer</u>	Off-white skim coat / beige paint				detected		pairit + other	
Comments								
202143118	1901-M-A20							
<u>Layer</u>	NOT ANALYZED DUE TO STOP ANALYSIS							
Comments								
202143119	1901-M-A21							
<u>Layer</u>	NOT ANALYZED DUE TO STOP ANALYSIS							
Comments								
202143120	1901-M-A22		NONE DETECTED		Cellulose (undulose) +	70	Perlite + glass + other	7/27/2021
<u>Layer</u>	Gray / white ceiling tile				fibrous glass (amorphous)			
Comments								
202143121	1901-M-A23		NONE DETECTED		Cellulose (undulose) + fibrous glass	70	Perlite + glass + other	7/27/2021
<u>Layer</u>	Gray / white ceiling tile				(amorphous)			
Comments								
202143122	1901-M-A24		NONE DETECTED		Cellulose (undulose) +	70	Perlite + glass + other	7/27/2021
<u>Layer</u>	Gray / white ceiling tile				fibrous glass (amorphous)			
Comments								
202143123	1901-M-A25		NONE DETECTED		Cellulose (undulose) + fibrous glass	20	Aluminum	7/27/2021
<u>Layer</u>	Silver wrap				(amorphous)			
Comments								
202143123	1901-M-A25		NONE DETECTED		Fibrous glass (amorphous)	> 99	None detected	7/27/2021
<u>Layer</u> Comments	Yellow insulation							

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Sample No.	Your Sample ID / Description	Asbestos	Туре	%v/v	Other	0/. 1/1/1	Matrix	Date
Sample No.	Tour Sample ID / Description	Present?	туре	/0 V/V	Fibrous	/0 V / V	Wattix	Analyzed
202143124	1901-M-A26		NONE DETECTED		Cellulose (undulose) +	20	Aluminum	7/27/2021
<u>Layer</u>	Silver wrap				fibrous glass (amorphous)			
Comments								
202143124	1901-M-A26		NONE DETECTED		Fibrous glass (amorphous)	> 99	None detected	7/27/2021
<u>Layer</u>	Yellow insulation							
Comments								
202143125	1901-M-A27		NONE DETECTED		Cellulose (undulose) +	20	Aluminum	7/27/2021
<u>Layer</u>	Silver wrap				fibrous glass (amorphous)			
Comments								
202143125	1901-M-A27		NONE DETECTED		Fibrous glass (amorphous)	> 99	None detected	7/27/2021
<u>Layer</u>	Yellow insulation							
Comments								
202143126	1901-M-A28		NONE DETECTED		None detected		Vinyl + other	7/27/2021
<u>Layer</u>	Green cove base							
Comments								
202143126	1901-M-A28		NONE DETECTED		None detected		Binder + other	7/27/2021
<u>Layer</u>	Yellow mastic							
Comments								
202143127	1901-M-A29		NONE DETECTED		None detected		Vinyl + other	7/27/2021
<u>Layer</u>	Green cove base							
Comments								
202143127	1901-M-A29		NONE DETECTED		None detected	_	Binder + other	7/27/2021
<u>Layer</u> Comments	Yellow mastic							

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143128	1901-M-A30		NONE DETECTED		None detected		Vinyl + other	7/27/2021
<u>Layer</u>	Green cove base							
Comments								
202143128	1901-M-A30		NONE DETECTED		None detected		Binder + other	7/27/2021
<u>Layer</u>	Yellow mastic							
Comments								
202143129	1901-M-A31		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143130	1901-M-A32		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143131	1901-M-A33		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143132	1901-M-A34		NONE DETECTED		None detected		Ceramic	7/27/2021
<u>Layer</u>	Gray ceramic tile							
Comments								
202143132	1901-M-A34		NONE DETECTED		None detected		Glass +	7/27/2021
<u>Layer</u>	Gray grout							
Comments								
202143132	1901-M-A34		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u>	Gray mortar							
Comments								

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion		
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v Matrix	Date Analyzed
202143132	1901-M-A34		NONE DETECTED		None detected	Binder	7/27/2021
<u>Layer</u>	Off-white mastic						
Comments							
202143133	1901-M-A35		NONE DETECTED		None detected	Ceramic	7/27/2021
<u>Layer</u>	Gray ceramic tile						
Comments							
202143133	1901-M-A35		NONE DETECTED		None detected	Glass +	7/27/2021
<u>Layer</u>	Gray grout						
Comments							
202143134	1901-M-A36		NONE DETECTED		None detected	Ceramic	7/27/2021
<u>Layer</u>	Gray ceramic tile						
Comments							
202143134	1901-M-A36		NONE DETECTED		None detected	Glass +	7/27/2021
<u>Layer</u>	Gray grout						
Comments							
202143135	1901-M-A37		NONE DETECTED		None detected	Glass +	7/27/2021
<u>Layer</u>	Gray grout						
Comments							
202143135	1901-M-A37		NONE DETECTED		None detected	Ceramic	7/27/2021
<u>Layer</u>	White ceramic tile						
Comments							
202143136	1901-M-A38		NONE DETECTED		None detected	Glass +	7/27/2021
<u>Layer</u> Comments	Gray grout						

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143136	1901-M-A38		NONE DETECTED		None detected		Ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								
202143137	1901-M-A39		NONE DETECTED		None detected		Glass +	7/27/2021
<u>Layer</u>	Gray grout							
Comments								
202143137	1901-M-A39		NONE DETECTED		None detected		Ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								
202143138	1901-M-A40		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White sealant material							
Comments								
202143139	1901-M-A41		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White sealant material							
Comments								
202143140	1901-M-A42		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White sealant material							
Comments								
202143141	1901-M-A43		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White caulking							
Comments								
202143142	1901-M-A44		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White caulking							
Comments								

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bulk	Asbes	tos Dete	rminat	tion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143143	1901-M-A45		NONE DETECTED		None detected		Binder	7/27/2021
<u>Layer</u>	White caulking							
Comments								
202143144	1901-M-A46		NONE DETECTED		Cellulose (undulose) +	15	Gypsum	7/27/2021
<u>Layer</u>	Tan drywall				fibrous glass (amorphous)			
Comments								
202143144	1901-M-A46	Yes	Chrysotile	2	None		Calcite +	7/27/2021
<u>Layer</u>	White joint compound (1) / paint				detected		binder + paint	
Comments								
202143144	1901-M-A46	Yes	Chrysotile	< 1	Cellulose	20	Calcite +	7/27/2021
<u>Layer</u>	White joint compound (2) / paper				(undulose)		binder	
Comments								
202143145	1901-M-A47							
<u>Layer</u>	NOT ANALYZED DUE TO STOP ANALYSIS							
Comments								
202143146	1901-M-A48							
Layer	NOT ANALYZED DUE TO STOP ANALYSIS							
Comments								
202143147	1901-M-A49		NONE DETECTED		None detected		Binder + paint	7/27/2021
<u>Layer</u>	White caulking / paint							
Comments								
202143148	1901-M-A50		NONE DETECTED		None detected	_	Binder + paint	7/27/2021
<u>Layer</u>	White caulking / paint							
Comments								

(808)839-7222 Phone Number: Facsimile: (808) 839-4455

Email:

Lab Job No: 202107064 Date Submitted: 7/26/2021

19-3501, Maui Highways SWMP, 7/23/21 **Your Project:**

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143149	1901-M-A51		NONE DETECTED		None detected		Binder + paint	7/27/2021
<u>Layer</u> Comments	White caulking / paint							
202143150	1901-M-A52		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u> Comments	Gray concrete							
202143151	1901-M-A53		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u> Comments	Gray concrete							
202143152	1901-M-A54		NONE DETECTED		None detected		Cementitious + other	7/27/2021
<u>Layer</u> Comments	Gray concrete							
202143153	1901-M-A55		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u> Comments	Gray concrete / brown paint						other	
202143154	1901-M-A56		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u> Comments	Gray concrete / brown paint						other	
202143155	1901-M-A57		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u>	Gray concrete / brown paint						other	
202143156	1901-M-A58		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u>	Gray cementitious material / pain	<u>t</u>			30.00.04		other	
Comments								

(808)839-7222 **Phone Number:** (808) 839-4455 Facsimile:

Email:

Lab Job No: 202107064 Date Submitted: 7/26/2021

19-3501, Maui Highways SWMP, 7/23/21 **Your Project:**

	Bulk	Asbes	tos Dete	rminati	on			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143157	1901-M-A59		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u>	Gray cementitious material / paint						other	
Comments								
202143158	1901-M-A60		NONE DETECTED		None detected		Cementitious + paint +	7/27/2021
<u>Layer</u>	Gray cementitious material / paint						other	
Comments								
202143159	1901-M-A61		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u>	Gray concrete / paint						otner	
Comments								
202143160	1901-M-A62		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u>	Gray concrete / paint						otriei	
Comments								
202143161	1901-M-A63		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u>	Gray concrete / paint						otriei	
Comments								
202143162	1901-M-A64		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u>	Gray cementitious material / paint						otner	
Comments								
202143163	1901-M-A65		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u>	Gray cementitious material / paint						oulei	
Comments								
202143164	1901-M-A66		NONE DETECTED		None detected		Cementitious + paint + other	7/27/2021
<u>Layer</u> Comments	Gray cementitious material / paint						ou lei	

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Sample No.	Your Sample ID / Description	Asbestos	Туре	%v/v	Other	%v/v	Matrix	Date
		Present?			Fibrous			Analyzed
202143165	1901-M-A67		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	<u>Gray plaster</u>							
Comments								
202143166	1901-M-A68		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray plaster							
Comments								
202143167	1901-M-A69		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray plaster							
Comments								
202143168	1901-M-A70		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Tan grout							
Comments								
202143168	1901-M-A70		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								
202143168	1901-M-A70		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	White mortar							
Comments								
202143169	1901-M-A71		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Tan grout							
Comments								
202143169	1901-M-A71		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143169	1901-M-A71		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	White mortar							
Comments								
202143170	1901-M-A72		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Tan grout							
Comments								
202143170	1901-M-A72		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								
202143170	1901-M-A72		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	White mortar							
Comments								
202143171	1901-M-A73		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Tan grout							
Comments								
202143171	1901-M-A73		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	White ceramic tile							
Comments								
202143172	1901-M-A74		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Tan grout							
Comments								
202143172	1901-M-A74		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u> Comments	White ceramic tile							

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143173	1901-M-A75		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u> Comments	Tan grout							
202143173	1901-M-A75		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u> Comments	White ceramic tile							
202143174	1901-M-A76		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u> Comments	White/black caulks							
202143175	1901-M-A77		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u> Comments	White/black caulks							
202143176	1901-M-A78		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u> Comments	White/black caulks							
202143177	1901-M-A79		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u> Comments	Tan/white caulks							
202143178	1901-M-A80		NONE DETECTED		None detected		Binder + other	7/27/2021
<u>Layer</u> Comments	<u>Tan caulk</u>							
202143179	1901-M-A81		NONE DETECTED		None detected		Binder + other	7/27/2021
<u>Layer</u> Comments	<u>Tan caulk</u>							

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Bulk Asbestos Determination										
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed		
202143180	1901-M-A82		NONE DETECTED		None detected		Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143181	1901-M-A83		NONE DETECTED		None detected		Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143182	1901-M-A84		NONE DETECTED		None detected		Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143183	1901-M-A85		NONE DETECTED		None detected		Binder + other	7/27/2021		
<u>Layer</u> Comments	White caulk									
202143184	1901-M-A86		NONE DETECTED		None detected		Binder + other	7/27/2021		
<u>Layer</u> Comments	White caulk									
202143185	1901-M-A87		NONE DETECTED		None detected		Binder + other	7/27/2021		
<u>Layer</u> Comments	White caulk									
202143186	1901-M-A88		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143187	1901-M-A89		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Bulk Asbestos Determination										
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed		
202143188	1901-M-A90		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143189	1901-M-A91		NONE DETECTED		None detected		Foam	7/27/2021		
<u>Layer</u> Comments	Black foam insulation									
202143190	1901-M-A92		NONE DETECTED		None detected		Foam	7/27/2021		
<u>Layer</u> Comments	Black foam insulation									
202143191	1901-M-A93		NONE DETECTED		None detected		Foam	7/27/2021		
<u>Layer</u> Comments	Black foam insulation									
202143192	1901-M-A94		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143193	1901-M-A95		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143194	1901-M-A96		NONE DETECTED		Polypropylene (undulose)	5	Calcite + binder	7/27/2021		
<u>Layer</u> Comments	Black caulk									
202143195	1901-M-A97		NONE DETECTED		None detected		Calcite + binder	7/27/2021		
<u>Layer</u> Comments	White caulk									

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	ion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143196	1901-M-A98		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u>	White caulk							
Comments								
202143197	1901-M-A99		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u>	White caulk							
Comments								
202143198	1901-M-A100		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray plaster							
Comments								
202143199	1901-M-A101		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray plaster							
Comments								
202143200	1901-M-A102		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray plaster							
Comments								
202143201	1901-M-A103		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143202	1901-M-A104		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u>	Gray concrete							
Comments								
202143203	1901-M-A105		NONE DETECTED		None detected		Cementitious	7/27/2021
<u>Layer</u> Comments	Gray concrete							

Hawaii Analytical Laboratory is a NIST NVLAP accredited laboratory (NVLAP Lab Code 200655-0) and is accredited in accordance with the recognized ISO/ IEC 17025:2017. Controlled doc.: Asbestos Report, rev. 3 – 20200630

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	Bulk Asbestos Determination												
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v Matrix	Date Analyzed							
202143204	1901-M-A106		NONE DETECTED		None detected	Foam	7/27/2021							
<u>Layer</u>	Black foam insulation													
Comments														
202143205	1901-M-A107		NONE DETECTED		None detected	Foam	7/27/2021							
<u>Layer</u>	Black foam insulation													
Comments														
202143206	1901-M-A108		NONE DETECTED		None detected	Foam	7/27/2021							
<u>Layer</u>	Black foam insulation													
Comments														
202143207	1901-M-A109		NONE DETECTED		None detected	Binder + other	7/27/2021							
<u>Layer</u>	Gray caulk													
Comments														
202143208	1901-M-A110		NONE DETECTED		None detected	Binder + other	7/27/2021							
<u>Layer</u>	Gray caulk													
Comments														
202143209	1901-M-A111		NONE DETECTED		None detected	Binder + other	7/27/2021							
<u>Layer</u>	Gray caulk													
Comments														
202143210	1901-M-A112		NONE DETECTED		None detected	Calcite + vinyl	7/27/2021							
<u>Layer</u>	Gray covebase													
Comments														
202143210	1901-M-A112		NONE DETECTED		None detected	Calcite + binder	7/27/2021							
<u>Layer</u> Comments	Off-white mastic													

Hawaii Analytical Laboratory is a NIST NVLAP accredited laboratory (NVLAP Lab Code 200655-0) and is accredited in accordance with the recognized ISO/ IEC 17025:2017. Controlled doc.: Asbestos Report, rev. 3-20200630

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

	Bul	k Asbes	tos Dete	rminat	tion			
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v	Matrix	Date Analyzed
202143211	1901-M-A113		NONE DETECTED		None detected		Calcite + vinyl	7/27/2021
<u>Layer</u>	Gray covebase							
Comments								
202143211	1901-M-A113		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u>	Off-white mastic							
Comments								
202143212	1901-M-A114		NONE DETECTED		None detected		Calcite + vinyl	7/27/2021
<u>Layer</u>	Gray covebase							
Comments								
202143212	1901-M-A114		NONE DETECTED		None detected		Calcite + binder	7/27/2021
<u>Layer</u>	Off-white mastic							
Comments								
202143213	1901-M-A115		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	Gray ceramic tile							
Comments								
202143213	1901-M-A115		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
<u>Layer</u>	Gray grout							
Comments								
202143214	1901-M-A116		NONE DETECTED		None detected		Calcite + ceramic	7/27/2021
<u>Layer</u>	Gray ceramic tile							
Comments								
202143214	1901-M-A116		NONE DETECTED		None detected		Calcite + quartz	7/27/2021
Layer	Gray grout							
Comments								

Hawaii Analytical Laboratory is a NIST NVLAP accredited laboratory (NVLAP Lab Code 200655-0) and is accredited in accordance with the recognized ISO/ IEC 17025:2017. Controlled doc.: Asbestos Report, rev. 3 – 20200630

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Bulk Asbestos Determination												
Sample No.	Your Sample ID / Description	Asbestos Present?	Туре	%v/v	Other Fibrous	%v/v Matrix	Date Analyzed					
202143215	1901-M-A117		NONE DETECTED		None detected	Calcite + ceramic	7/27/2021					
<u>Layer</u> Comments	Gray ceramic tile											
202143215	1901-M-A117		NONE DETECTED		None detected	Calcite + quartz	7/27/2021					
<u>Layer</u>	Gray grout											
Comments												
202143216	1901-M-A118		NONE DETECTED		None detected	Calcite + ceramic	7/27/2021					
<u>Layer</u>	Gray ceramic tile											
Comments												
202143217	1901-M-A119		NONE DETECTED		None detected	Calcite + ceramic	7/27/2021					
<u>Layer</u>	Gray ceramic tile											
Comments												
202143218	1901-M-A120		NONE DETECTED		None detected	Calcite + ceramic	7/27/2021					
<u>Layer</u>	Gray ceramic tile											
Comments												

Phone Number: (808)839-7222 Facsimile: (808) 839-4455

Email: -

Lab Job No: 202107064 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

General Comments

The bulk sample[s] analysis subject of this analytical report were conducted in general accordance with the procedures outlined in the United States Environmental Protection Agency's "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" (EPA-600/M4-82-020, Dec. 1982) and / or "Method for Determination of Asbestos in bulk Building Materials" (EPA-600/R-93-116, July 1993). The analysis of each bulk sample relates only to the material examined, and may or may not represent the overall composition of its original source. Floor tile and other resinously bound materials, when analyzed by the EPA methods referenced above may yield false negative results because of limitations in separating closely bound fibers and in detecting fibers of small length and diameter. Alternative methods of identification, including Transmission Electron Microscopy (TEM) may or may not be applicable. We utilize calibrated visual area estimation on a routine basis and do not conduct point counting unless specifically requested to do so. Estimated error for the visual determinations presented are 75% relative (1 to 2%), 50% relative (3 to 5%); 25% relative (6 to 25%) and 20% (>26% v/v). We will not separate layers which in our opinion are not readily discernable. This report is not to be duplicated except in full without the expressed written permission of Hawaii Analytical Laboratory. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST or any agency of Federal Governement. Unless otherwise indicated, the sample condition at the time of receipt was acceptable.

Results and Symbols Definitions

- > This testing result is greater than the numerical value listed.
- < This testing result is less than the numerical value listed.

Verif the Lian

None Detected = asbestos was not observed in the sample. If trace amount of asbestos was detected below our quantifiable limits of 1.0%, <1% (trace) would be indicated and the asbestos type listed. Point counting, where applicable, are recommended to improve accuracy.

Jennifer Hsu Liao Laboratory Manager

		☐ New Client?							
HAWAII		Report To*	:Antone Gabri	el		Invoice To*		: Bianca Kim	
LABORATO	RY, LLC	Company	ENVIROSERV	ICES & TRAINING CE	ENTER, LLC	Company		ENVIROSERVICES	& TRAINING CENTER, LLC
	· .	Address*	505 Ward Ave.	. Suite #202		Address*		505 Ward Ave. Suite	#202
			Honolulu, HI 96	6814				Honolulu, HI 96814	
3615 Harding Avenue, Suite 3	200	Phone / Cell No.*	(808) 839-7222	2		Phone / Ce	l No.*	(808) 839-7222	
Honolulu, HI 96816		Report results to	: Antone Gabrie	1		Purchase C	rder No.		
Ph: 808-735-0422 - Fax: 808- www.analyzehawaii.com	735-0047	via email or fax	: agabriel@gotoetc.	.com, smarvin@gotoetc.com	m, bcarroll@gotoetc.com	Email Invoid	се То	:	
Need Results By*:	_								
5 Working Days (WD)									
3 WD		roject Name:			Client Project No.:			Sampled By:	
☑ 2 WD		ui Highways S			19-3501			B. Carroll	
24 hours 6 hours or less	Comm	ents / Special Instruct	tions:	verbal res	ults needed?	PLM POSIT	IVE STOP	Instructions:	LAB USE ONLY
4 hours or less						Positive stop			Lab Report No.:
1-2 hours Sample Identi	fication / [Description*	Date Sample	d* Collection	Comple Area	Positive stop	per LAYER	10.11	202107064
	of 30 Char		(mm/dd/yy)	Medium	Sample Area / Air Volume	Analysis Requ	ested*	Method Reference	Lab ID
1901-M	1-A01 to	A03	7/23/2021	l Bulk	2021430	99 PLM	201	2143100	202143101
1901-M	1-A04 to	A06	7/23/2021	Bulk2 ()	2143102	PLM	202	143103	202143104
1901-M	1-A07 to	A09	7/23/2021	Bulk 2.0	2143105	PLM	202	143106	202143107
1901-M	1-A10 to	A12	7/23/2021	Bulk 2	02143108	PLM	202	2143109	202143110
1901-M	1-A13 to	A15	7/23/2021	Bulk 2 (2143111	PLM	202	143112	202143113
1901-M	1-A16 to	A18	7/23/2021	Bulk 2 (2143114	PLM	202	143115	202143116
. 1901-M	1-A19 to	A21	7/23/2021	Bulk 20	2143117	PLM	202	143118	202143119
, 1901-M	1-A22 to	A24	7/23/2021	Bulk 2 (2143120	PLM	20	2143121	202143122
, 1901-M	1-A25 to	A27	7/23/2021	Bulk 20	2143123	PLM	201	2143124	202143125
1901-M	1-A28 to	A30	7/23/2021	l Bulk 2 0	2143126	PLM	20	2143127	202143128
1901-M	1-A31 to	A33	7/23/2021	10 0		PLM	202	143130	202143131
1901-M	1-A34 to	A36	7/23/2021	l Bulk 2 (2143132	PLM	202	143133.	202143134
Relinqu		(Print and Sign)	*3	Date/Time		Received E			Date/Time
	S.\Ma	arvin		7/26/2021			Corin For	rest	07-26-21 P01902-M
Samuel days in Co						Commence	-	1	1:13 pm -1
Sample description can be p	NAME OF TAXABLE PARTY.				☐ via F	FedEx 🔲 via US	ps □ v	ria	
All samples submitted are su	ibject to Ha	waii Analytical Laborator	y terms and condit	tions.	_	, , , , , , , , , , , , , , , , , , , 			
*Required fields, failure to co	implete the	se fields may result in a c	delay in your samp	les being processed.		4		1	Page: 1 of 4

	☐ New Client?						
HAWAII	Report To*	: Antone Gabriel			Invoice To*	: Bianca Kim	
LABORATORY	Company	ENVIROSERVICE	NVIROSERVICES & TRAINING CENTER, LLC			ENVIROSERVICE	ES & TRAINING CENTER, LLC
	Address*	505 Ward Ave. Su	ite #202		Address*	505 Ward Ave. Su	
		Honolulu, HI 9681	4			Honolulu, HI 9681	4
3615 Harding Avenue, Suite 308	Phone / Cell No.*	(808) 839-7222			Phone / Cell No.*	(808) 839-7222	
Honolulu, HI 96816	Report results to	: Antone Gabriel			Purchase Order N	lo. :	
Ph: 808-735-0422 - Fax: 808-73 www.analyzehawaii.com	via email or fax	agabriel@gotoetc.com	, smarvin@gotoetc.co	m, bcarroll@gotoetc.com	Email Invoice To		
Need Results By*:							
5 Working Days (WD) 4 WD							
☐ 3 WD	Site/Project Name:			Client Project No.:		Sampled By:	
☑ 2 WD	Maui Highways S			19-3501		B. Carroll	
24 hours 6 hours or less	Comments / Special Instruc	tions:	verbal res	sults needed?	PLM POSITIVE S		LAB USE ONLY
4 hours or less				ε	Positive stop per SAM		Lab Report No.:
1-2 hours	- 15 15	Data Carrata It	I 0 11 11		Positive stop per LAY		202107064
	ation / Description* f 30 Characters)	Date Sampled* (mm/dd/yy)	Collection Medium	Sample Area / Air Volume	Analysis Requested	Method Reference	Lab ID
1901-M-	A37 to A39	7/23/2021	Bulk 2	02143135	PLM 2	02143136	202143137
	A40 to A42	7/23/2021	Bulk 2 (2143138	PLM 2	02143139	202143140
1901-M-,	A43 to A45	7/23/2021	Bulk 20	2143141	PLM 2	02143142	202143143
1901-M-	A46 to A48	7/23/2021	Bulk 2 (2143144	- N	02143145	202143146
1901-M-	A49 to A51	7/23/2021	Bulk 20	2143147	PLM 2	02143148	202143149
1901-M-	A52 to A54	7/23/2021	Bulk 2 (PLM 2	02143151	202143152
1901-M-	A55 to A57	7/23/2021	Bulk 2 €		PLM 2(12143154	202143155
1901-M-	A58 to A60	7/23/2021	Bulk 20	2143156	PLM 20	2143157	202143158
1901-M-	A61 to A63	7/23/2021		2143159	PLM 20	2143160	202143161
1901-M-	A64 to A66	7/23/2021	Bulk 20	2143162	PLM 2		202143164
1901-M-	A67 to A69	7/23/2021	Bulk 2 (PLM 2	12143166	202143167
1901-M-	A70 to A72	7/23/2021	Bulk 20	2143168	PLM 2	02143169.	202143170
Relinquis	hed By (Print and Sign)		Date/Time		Received By (Pri	nt and Sign)	Date/Time
	S. Marvin		7/26/2021		Corin	Forrest	07-26-21 P01:13
					1.	The state of	
	வு-ளிற்க, concrete, specific sampl rif it is a FOREIGN SOIL SAMPLE			☐ via F	edEx 🔲 via USPS [via	
	ect to Hawaii Analytical Laborato			y 	<u> </u>		-
required fields, failure to com	plete these fields may result in a	delay in your samples t	peing processed				Page: 8- of 4

☐ New Client?							
HAWAII ANALYTICAL Report To*	: Antone Gabriel			Invoice To*	:	Bianca Kim	
LABORATORY, LLC Company	ENVIROSERVICE	S & TRAINING C	ENTER, LLC	Company	:	ENVIROSERVICES	S & TRAINING CENTER, LLC
Address*	505 Ward Ave. Sui	ite #202		Address*	:	505 Ward Ave. Suit	re #202
	Honolulu, HI 96814	4				Honolulu, HI 96814	8
Phone / Cell No.*	(808) 839-7222			Phone / Cell	No.*	(808) 839-7222	
Honolulu, HI 96816 Report results to	: Antone Gabriel			Purchase Or	der No.		
Ph: 808-735-0422 - Fax: 808-735-0047	: agabriel@gotoetc.com	, smarvin@gotoetc.co	m, bcarroll@gotoetc.com	Email Invoice	e To :		
Need Results By*:							
5 Working Days (WD)				-			
Site/Project Name:			Client Project No.:			Sampled By:	
Maui Highways S			19-3501			B. Carroll	
Comments / Special Instruc	tions:	verbal res	sults needed?	PLM POSITI		Instructions:	LAB USE ONLY
4 hours or less				Positive stop po			Lab Report No.:
1-2 hours	Data Campledt	O-U		Positive stop pe	er LAYER		202107064
Sample Identification / Description* (Maxmium of 30 Characters)	Date Sampled* (mm/dd/yy)	Collection Medium	Sample Area / Air Volume	Analysis Reque	ested*	Method Reference	Lab ID
1901-M-A73 to A75	7/23/2021	Bulk 2 (2143171	PLM	202	2143172	202143173
1901-M-A76 to A78	7/23/2021	Bulk 20	2143174	PLM	202	143175	2021/2176
1901-M-A79 to A81	7/23/2021	Bulk 2 (2143177	PLM	202	2143178	202143179
1901-M-A82 to A84	7/23/2021	Bulk 2 (2143180	PLM	202	143181	202143182
1901-M-A85 to A87	7/23/2021	Bulk 2 0	2143183	PLM	20	143184	202143185
1901-M-A88 to A90	7/23/2021	Bulk 20	2143186	PLM	202	2143187	202143188
1901-M-A91 to A93	7/23/2021	Bulk 2 (2143189	PLM	201	2143190	202143191
1901-M-A94 to A96	7/23/2021	Bulk 2 ()		PLM	20	143193	202143194
1901-M-A97 to A99	7/23/2021	Bulk 20	2143195	PLM	202	143196	202143197
1901-M-A100 to A102	7/23/2021	Bulk 2 ()	2143198	PLM	202	143199	202142200
1901-M-A103 to A105	7/23/2021	Bulk 2 (2143201	PLM	202	143202	$\frac{202143203}{202143203}$
1901-M-A106 to A108	7/23/2021	Bulk 20	2143204	PLM	201	143205	202143206
Relinquished By (Print and Sign)		Date/Time		Received By	y (Print ar	nd Sign)	Date/Time
S. Marvin		7/26/2021		Co	rin Forr	est	07-26-21 P01:13
				Constant of the second	- 1	and the same	
Sample description can be paint thips, concrete, specific sample If matrix is 'soil', please specify if it is a FOREIGN SOIL SAMPLE	(outside Hawaii) in the	comment section.	☐ via F	edEx 📜 via USP	s 🔲 v	ia	
All samples submitted are subject to Hawaii Analytical Laborator *Required fields, failure to complete these fields may result in a description.	y terms and conditions delay in your samples b	i. peing processed.		?		, "•	Page: 3 of 4

□ New (Client?					
HAWAII Report To	* Antone Gabriel			Invoice To*	: Bianca Kim	
LABORATORY, LLC Company		ES & TRAINING C	CENTER, LLC	Company	ENVIROSERVICES	& TRAINING CENTER, LLC
Address*	505 Ward Ave. S	Suite #202		Address*	505 Ward Ave. Suite	e #202
	Honolulu, HI 968	314			Honolulu, HI 96814	
Phone / C	Cell No.* : (808) 839-7222			Phone / Cell No.*	(808) 839-7222	
3615 Harding Avenue, Suite 308 Honolulu, HI 96816 Report res	sults to : Antone Gabriel			Purchase Order No.	. S	
Ph: 808-735-0422 - Fax: 808-735-0047 www.analyzehawaii.com via emai	il or fax : agabriel@gotoetc.co	om, smarvin@gotoetc.co	om, bcarroll@gotoetc.com	Email Invoice To	:	
Need Results By*:	9					
5 Working Days (WD)						
☐ 4 WD Site/Project Name	:		Client Project No.:		Sampled By:	
☑ ₂wɒ Maui Highv	vays SWMP		19-3501		B. Carroll	
Comments / Spec	ial Instructions:	☐ verbal re	sults needed?	PLM POSITIVE STO		LAB USE ONLY
6 hours or less 4 hours or less		verbarre	suits needed?	Positive stop per SAMPLI	E	Lab Report No.:
1-2 hours				Positive stop per LAYER	,	202107064
Sample Identification / Description* (Maxmium of 30 Characters)	Date Sampled* (mm/dd/yy)	Collection Medium	Sample Area / Air Volume	Analysis Requested*	Method Reference	Lab ID
1901-M-A109 to A111	7/23/2021	Bulk 2 (2143207	PLM 20	2143208	202143209
1901-M-A112 to A114	7/23/2021		2143210	PLM 20	143211	202143212
1901-M-A115 to A117	7/23/2021		2143213	PLM 20;		202143215
1901-M-A118 to A120	7/23/2021	Bulk 2 (2143216	PLM 202	2143217	202143218
j						
3						
5						
3					-	
Relinguished By (Print and S	Sian)			Received By (Print	and Sign)	Date/Time
S. Marvin		7/26/2021		Corin Fo		07-26-21 P01:13
				(Jan 1	
Sample description can be paint chips, concrete, son If matrix is 'soil', please specify if it is a FOREIGN SO	IL SAMPLE (outside Hawaii) in t	he comment section.	. uia F	edEx 🖸 via USPS 🔲	via	
All samples submitted are subject to Hawaii Analytica *Required fields, failure to complete these fields may				•	χ.	Page: 4 of 4



Hawaii Analytical Laboratory ANALYTICAL REPORT

Tuesday, July 27, 2021

EnviroServices & Training Center, LLC 505 Ward Avenue, Suite 202 Honolulu HI 96814

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107063 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Total Lead (paint chips)											
	NIOSH Method: 7082m LEAD by FAAS			Date							
Sample No.	Your Sample ID / Description	Results	Units	Analyzed							
202143083	1901-M-L01	< 44	mg/kg	7/27/2021							
Comments	MRL = 44 mg/kg										
202143084	1901-M-L02	< 120	mg/kg	7/27/2021							
Comments	MRL = 120 mg/kg										
202143085	1901-M-L03	440	mg/kg	7/27/2021							
Comments	MRL = 40 mg/kg			772172021							
202143086	1901-M-L04	< 40	mg/kg	7/27/2021							
Comments	MRL = 40 mg/kg			.,,_							
202143087	1901-M-L05	210	mg/kg	7/27/2021							
Comments	MRL = 44 mg/kg			772172021							
202143088	1901-M-L06	< 40	mg/kg	7/27/2021							
Comments	MRL = 40 mg/kg		9/9	772772021							
202143089	1901-M-L07	< 43	mg/kg	7/27/2021							
Comments	MRL = 43 mg/kg			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
202143090	1901-M-L08	< 40	mg/kg	7/27/2021							
Comments	MRL = 40 mg/kg	. 10	9/119	112112021							

Hawaii Analytical Laboratory (101812) is accredited by the AIHA LAP, LLC in the EMLAP, IHLAP, and ELLAP programs for the scope of work listed on www.aihaaccreditedlabs.org, in accordance with the recognized ISO/IEC 17025:2005. AIHA is a NLLAP recognized accrediting body. Controlled doc.: Lead Report, rev. 3 – 20181015

EnviroServices & Training Center, LLC 505 Ward Avenue, Suite 202

Honolulu HI 96814

Phone Number: (808)839-7222 **Facsimile:** (808) 839-4455

Email: -

Lab Job No: 202107063 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

Total Lead (paint chips)														
	NIOSH Method: 7082m LEAD by FAAS Date													
Sample No.	Your Sample ID / Description	Results	Units	Analyzed										
202143091	1901-M-L09	< 56	mg/kg	7/27/2021										
Comments	MRL = 56 mg/kg													
202143092	1901-M-L10	290	mg/kg	7/27/2021										
Comments	MRL = 46 mg/kg													
202143093	1901-M-L11	< 40	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg													
202143094	1901-M-L12	< 40	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg													
202143095	1901-M-L13	74	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg													
202143096	1901-M-L14	< 40	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg	- -												
202143097	1901-M-L15	450	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg													
202143098	1901-M-L16	< 40	mg/kg	7/27/2021										
Comments	MRL = 40 mg/kg													

EnviroServices & Training Center, LLC Phone Number: (808)839-7222 505 Ward Avenue, Suite 202 Facsimile: (808) 839-4455

Honolulu HI 96814 Email:

Lab Job No: 202107063 **Date Submitted:** 7/26/2021

Your Project: 19-3501, Maui Highways SWMP, 7/23/21

All Quality Control data are acceptable unless otherwise noted.

MRL for lead air is 5ug.
MRL for lead wipe is 10ug.

MRL for lead paint or soil is 40 mg/kg for a 0.25g sample.

General Comments

The sample[s] analysis subject of this analytical report were conducted in general accordance with the procedures associated with the "analytical method" referenced above. Modifications to this methodology may have been made based upon the analyst's professional judgment and / or sample matrix effects encountered. The analysis of sample relates only to the sample analyzed, and may or may not be representative of the original source of the material submitted for our analysis. All analysts participate in interlaboratory quality control testing to continuously document profiency. This report is not to be duplicated except in full without the expressed written permission of Hawaii Analytical Laboratory. This report should not be construed as an endorsement for a product or a service by the AIHA LAP, LLC or any affiliated organizations. Sample and associated sampling / collection data is reported as provided by client. TWA values have been calculated based on information supplied by the client that the laboratory has not independently verified. Results have not been corrected for blank determinations unless noted in remarks. Unless otherwise indicated the sample condition at the time of receipt was acceptable.

Results and Symbols Definitions

- > This testing result is greater than the numerical value listed.
- < This testing result is less than the numerical value listed.

Verif the Lian

= Analytical methods marked with an "#" are not within our AIHA LAP, LLC Scope of Accreditation. MRL = Method Reporting Limit.

Jennifer Hsu Liao Laboratory Manager

Hawaii Analytical Laboratory (101812) is accredited by the AIHA LAP, LLC in the EMLAP, IHLAP, and ELLAP programs for the scope of work listed on www.aihaaccreditedlabs.org, in accordance with the recognized ISO/ IEC 17025:2005. AIHA is a NLLAP recognized accrediting body. Controlled doc.: Lead Report, rev. 3 – 20181015

	■ New Client?							
HAWAII	Report To*	: Antone Gabriel			7 [Invoice To*	· Bianca Kim	
LABORATORY, LLC	Company	ENVIROSERVICE	S & TRAINING C	ENTER, LLC		Company	ENVIROSERVICES	R TRAINING CENTER, LLC
1,1,	Address*	505 Ward Ave. Su	ite #202			Address*	505 Ward Ave. Suite	
		Honolulu, HI 9681	Honolulu, HI 96814				Honolulu, HI 96814	
0045 Unit in A 0 it and	Phone / Cell No.*	(808) 839-7222				Phone / Cell No.*	(808) 839-7222	
3615 Harding Avenue, Suite 308 Honolulu, HI 96816	Report results to	: Antone Gabriel			_	Purchase Order No.	:	
Ph: 808-735-0422 - Fax: 808-735-0047 www.analyzehawaii.com	via email or fax	: agabriel@gotoetc.com	, smarvin@gotoetc.co	om, bcarroll@gotoetc.com		Email Invoice To	:	
Need Results By*:					-			
5 Working Days (WD)								
I I I 3 WD	Project Name:			Client Project No.:			Sampled By:	
☑ ₂wɒ Ma	ui Highways S	SWMP		19-3501			D. Hollimar	1
24 hours Com	ments / Special Instruc	tions:	☐ verbal res	sults needed?		PLM POSITIVE STOP	Instructions:	LAB USE ONLY
4 hours or less					1 2000	Positive stop per SAMPLE		Lab Report No.:
1-2 hours					L	Positive stop per LAYER		202107063
Sample Identification / (Maxmium of 30 Ch		Date Sampled* (mm/dd/yy)	Collection Medium	Sample Area / Air Volume	A	nalysis Requested*	Method Reference	Lab ID
1901-M-L	01	7/23/2021	Paint Chip			Lead		202143083
1901-M-L	02	7/23/2021	Paint Chip			Lead		202143083 202143084
1901-M-L		7/23/2021	Paint Chip		$oxed{oxed}$	Lead		202143085
1901-M-L	04	7/23/2021	Paint Chip			Lead		202143086
1901-M-L	05	7/23/2021	Paint Chip			Lead		202143087
1901-M-L	06	7/23/2021	Paint Chip			Lead		202143088
1901-M-L	07	7/23/2021	Paint Chip			Lead		202143089
1901-M-L	08	7/23/2021	Paint Chip			Lead		202143090
1901-M-L	09	7/23/2021	Paint Chip			Lead		202143091
1901-M-L	10	7/23/2021	Paint Chip			Lead		202143092
1901-M-L	11	7/23/2021	Paint Chip			Lead		202143093
1901-M-L	12	7/23/2021	Paint Chip			_. Lead		202143094
Rel/inquished B	y (Print and Sign)		Date/Time			Received By (Print a	nd Sign)	Date/Time
\ s/n	Marvin		7/26/2021			Corin For	rest	07-26-21 P01:12
						<i>j</i>	7	
Sample description can be paint chips If matrix is 'soil', please-specify if it is	a FOREIGN SOIL SAMPLE	(outside Hawaii) in the	comment section.	☐ via	FedEx	□ via USPS □ \	/ia	
All samples submitted are subject to I *Required fields, failure to complete to							•	Page: of _2

	☐ New Client?							
HAWAII	Report To*	: Antone Gabriel			7	Invoice To*	· Bianca Kim	
LABORATORY, LLC	Company	ENVIROSERVICE	S & TRAINING C	ENTER, LLC	-	Company	ENVIROSERVICE	S & TRAINING CENTER, LLC
	Address*	505 Ward Ave. Su	ite #202		-	Address*	505 Ward Ave. Sui	te #202
		Honolulu, HI 9681	4				Honolulu, HI 96814	
2045 Harding Average (2.14, 202)	Phone / Cell No.*	: (808) 839-7222				Phone / Cell No.*	(808) 839-7222	
3615 Harding Avenue, Suite 308 Honolulu, HI 96816	Report results to	: Antone Gabriel				Purchase Order No.		
Ph: 808-735-0422 - Fax: 808-735-0047 www.analyzehawaii.com	via email or fax	; agabriel@gotoetc.com	, smarvin@gotoetc.co	om, bcarroll@gotoetc.com		Email Invoice To	:	
Need Results By*:					-			
5 Working Days (WD)								
☐ 4 WD Site/F	Project Name:			Client Project No.:			Sampled By:	
☑ ₂ wb Ma	ui Highways S	SWMP		19-3501			D. Hollima	an l
24 hours Comr	ments / Special Instruct	ions:	☐ verbal res	sults needed?	T	PLM POSITIVE STOP		LAB USE ONLY
6 hours or less 4 hours or less			U verbaires	suits needed?		Positive stop per SAMPLE		Lab Report No.:
1-2 hours					E	Positive stop per LAYER		202107063
Sample Identification / (Maxmium of 30 Cha		Date Sampled* (mm/dd/yy)	Collection Medium	Sample Area / Air Volume	A	nalysis Requested*	Method Reference	Lab ID
1901-M-L		7/23/2021	Paint Chip			Lead		202143095
1901-M-L	14	7/23/2021	Paint Chip			Lead		202143096
1901-M-L	15	7/23/2021	Paint Chip			Lead		202143097
1901-M-L	16	7/23/2021	Paint Chip			Lead		202143098
					<u> </u>			
					-			
					-			
					\vdash			
Relinquished B	y (Print and Sign)		Date/Time			Received By (Print a	nd Sign)	Date/Time
(s) N	Maryin		7/26/2021			Corin For		07-26-21 P01:12
	~					COFIN POL	1 7	
Sample description can be paint chips If matrix is 'soil', please specify if it is All samples submitted are subject to h	a FOREIGN SOIL SAMPLE	(outside Hawaii) in the	comment section.	☐ via	FedEx	via USPS	/ia	
*Required fields, failure to complete th						: -)	χ.	Page: 2 of 2

July 28, 2021



Antone Gabriel

EnviroServices & Training Center, LLC
505 Ward Avenue, Suite 202

Honolulu, HI 96814

NVL Batch # 2113314.00

RE: Total Metal Analysis

Method: EPA 6010 (price per analyte) <paint>

Item Code: ICP-M2

Client Project: 19-3501 Location: Maui Highways

Dear Mr. Gabriel,

For recent regulation updates pertaining to current regulatory levels or permissible exposure levels, please call your local regulatory agencies for more detail.

At NVL Labs all analyses are performed under strict guidelines of the Quality Assurance Program. This report is considered highly confidential and will not be released without your approval. Samples are archived after two weeks from the analysis date. Please feel free to contact us at 206-547-0100, in case you have any questions or concerns.

Sincerely.

Shalini Patel, Lab Supervisor

Enc.: Sample results





Analysis Report

Total Metals

Client: EnviroServices & Training Center, LLC

Address: 505 Ward Avenue, Suite 202

Honolulu, HI 96814

Attention: Mr. Antone Gabriel

Project Location: Maui Highways



Batch #: 2113314.00

Matrix: Bulk

Method: EPA 3051/6010D

Client Project #: 19-3501

Date Received: 7/27/2021

Samples Received: 1

Samples Analyzed: 1

Lab ID	Client Sample #	Elements	Sample wt (g)	RL mg / kg	Results in mg / kg	Results in ppm	
21087264	1901-M-As01	Arsenic (As)	0.3075	13.0	< 13.0	< 13.0	

Sampled by: Client

ppm = Parts per million

Analyzed by: Yasuyuki Hida

Reviewed by: Shalini Patel

mg/ kg = Milligrams per kilogram

Date Analyzed: 07/28/2021 Date Issued: 07/28/2021

Shalini Patel, Lab Supervisor

RL = Reporting Limit
'<' = Below the reporting Limit

Note: Method QC results are acceptable unless stated otherwise.

Unless otherwise indicated, the condition of all samples was acceptable at time of receipt.

ICP-M2 Bench Run No: 2021-0728-01 page 2 of 4

METAL LABORATORY SERVICES



Company	EnviroServices & T	raining Center, LLC	NVL Batch Number 2'				
Address	505 Ward Avenue,	Suite 202	TAT 2 Days	/	AH No		
	Honolulu, HI 96814		Rush TAT				
Project Manager Mr. Antone Gabriel		Due Date 7/29/2021	Time 10:30):30 AM			
Phone	e (808) 839-7222		Email agabriel@gotoeto				
		Fax (808) 839-4455	x (808) 839-4455				
Project Name/	Number: 19-3501	Project Lo	cation: Maui Highways				
Subcategory In	ductively Coupled P	lasma (ICP) - Group Tes	ets				
Item Code IC	P-M2	EPA 6010 (price per ana	alyte) <paint></paint>				
Metals Ar	senic (As)						
Total Numl	ber of Samples	1		Rı	ush Samples		
Lab ID	Sample ID	Description			A/R		
1 21087264	1901-M-As01				Α		

	Print Name	Signature	Company	Date	Time
Sampled by	Client				
Relinquished by	Federal Express				
Office Use Only	Print Name	Signature	Company	Date	Time
Received by	Fatima Khan		NVL	7/27/21	1030
Analyzed by	Yasuyuki Hida		NVL	7/28/21	
Results Called by					
☐ Faxed ☐ Emailed					
Special Instructions:		'			

Date: 7/27/2021 Time: 11:03 AM Entered By: Fatima Khan



Turn Around Time q 2 Hour q 2 Days q 5 Days Please call fo

q4 Hours 20---

q 24 Hours n 4 Davs

2113314

METALS CHAIN OF CUSTODY INDUSTRIAL HYGIENE SERVICES

Address: 505 Ward Ave. Suite #202 Honolulu HI, 96814 Phone (808) 839- 7222			Email agabriel@gotoetc.com			
roject Na	me/Number 19-3501	Project Location Ma	ui Highways			
CLP	q Paint Chi qGFAA(ppb) q Drinking qCVAA(ppb) QOther E	ps (cm) q Dust Wipes Water q Waste Water	q Bar q Ars	ium q Chromium q S	Lead q Zinc	
Reporti Call	ng Instructions	Fax ()	ā.	q Email agabriel@gotoe bcarroll@gotoetc.com. d	etc.com_smarvin@got holliman@gotoetc.co	oetc.com_ m
otal N	Number of Samples	1 Descript	tion		Time	L/min
1	1901-M-As01		Ceiling tile			
2						
3						
5						
6						
7						
8						
9						
10						
11						
12						
	Print Name	Signature	¥	Company	_v Date	Time
	Plint Name	Signature)		7123/202	,
Sample	d by SCAJNIRum	, 11		ETC	7/23/200	1
Relinquis	h by S.M.RUW			ETC	41001000	l
Office U	Jse Only Print Park teived by Print Park	Signature/	2	Company (Chi	Date /27/2	Time / 10:3

Appendix III

HOMOGENEOUS AREA MAP



