

**PALI HIGHWAY RESURFACING
VINEYARD BOULEVARD TO WAOKANAKA STREET
PHOTOGRAPHS OF ROADWAY SURVEY**




Photo No. 1: Heavy rutting under bus wheel path.



Photo No. 2: Concrete pothole patching along longitudinal cracks.

**PALI HIGHWAY RESURFACING
VINEYARD BOULEVARD TO WAOKANAKA STREET
PHOTOGRAPHS OF ROADWAY SURVEY**



Photo No. 3: Heavy alligator cracking and asphalt concrete patches under vehicle wheel paths.



Photo No. 4: Alligator cracking, block cracking, asphalt and concrete pothole patches, and subgrade failure.

**PALI HIGHWAY RESURFACING
VINEYARD BOULEVARD TO WAOKANAKA STREET
PHOTOGRAPHS OF ROADWAY SURVEY**



Photo No. 5: Longitudinal cracking, large asphalt and concrete patches, and subgrade failure.



Photo No. 6: Heavy rutting, alligator cracking, and pothole patches under vehicle wheel path.

**PALI HIGHWAY RESURFACING
VINEYARD BOULEVARD TO WAOKANAKA STREET
PHOTOGRAPHS OF ROADWAY SURVEY**



Photo No. 7: Rutting, alligator cracking, and long asphalt patches under vehicle wheel paths.



Photo No. 8: Surface raveling, alligator cracking, and large asphalt and concrete patches.