



Boring No.






<u>Note:</u> Boring log data included for information only

SURFACE ELEV			3.5 ±		DROP				30 in. END DATE 2/2/21
REMARKS/ SAMPLE NO.	CORE RECOVERY (%)	RQD (%)	BLOWS PER FOOT	DRY DENSITY (pcf)	MOISTURE CONTENT (%)	DEPTH (ft)	GRAPHIC LOG	SAMPLE	MATERIAL DESCRIPTION
Lost Recovery			33 50/4"	103	20	- - <u>¥</u> -			Silty GRAVEL (GM) - Dark brown, moist, medium dense, with sand. (Fill) Covered by 2 inches of AC over 3.5 inches of base material. Metal shards at 1 foot.
		40	110	16	5	Cobble at 3 feet. Silty Coralline GRAVEL (GM) - Tan, medium dense to dense, with sand. Groundwater encountered at 3.2 feet on 2/2/21 at 11:00 am.			
			54	94	38	10-			End boring at 10.5 feet.
						- - 15— -			
						20-			
						25— -			
						-			Plate A4.

OJECT NAME <u>HDOT Kakoi an</u> ORK ORDER NO. <u>21-6595</u> RFACE ELEV. <u>4</u> ±			95	DRIVING WT				140 lb.					
REMARKS/ SAMPLE NO.	CORE RECOVERY (%)	RQD (%)	BLOWS PER FOOT	DRY DENSITY (pcf)	MOISTURE CONTENT (%)	DEPTH (ft)	GRAPHIC LOG	SAMPLE	MA	TERIAL DESCRIPTIOI	N		
			104/8"		14	-	20 \$ 00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		with sand. (Fill)	GC) - Dark brown, m nches of AC over 3 ir			
			23	105	21	<u>▼</u> 5 –			Groundwater encountered at 4.6 feet on 2/1/21 at 9:20 am.				
			24	100	25	- - 10-			Silty Coralline GRA with sand.	AVEL (GM) - Tan, me	edium dense		
						-	bold⊾obb,		End boring at 10.5	feet.			
						_							
						15-							
						-							
						20-							
						- - 25—							
						-							

Hirata & Associates, Inc.

GEOTECHNICAL ENGINEERING





STATE OF HAWAII DEPARTMENT OF TRANSPORTATION HIGHWAYS DIVISION

BORING LOGS

EROSION CONTROL AND BEST MANAGEMENT PRACTICES FOR STORM WATER PERMIT COMPLIANCE PHASE 2

Project No. HWY-0-02-21 Scale: None Date: April 2022

SHEET No. EC-14 OF 14 SHEETS