

APPENDIX A: PHOTOGRAPHS



PHOTO 1 EAST APPROACH LOOKING WEST



PHOTO 2 WEST APPROACH LOOKING EAST

Farrington Highway Bridge No.2 over Hunehune Stream
Bridge No. 924
Structure No. 003924001100001



PHOTO 3 UPSTREAM ELEVATION



PHOTO 4 DOWNSTREAM ELEVATION



PHOTO 5 LOAD POSTING SIGNS ON FARRINGTON HIGHWAY AT EAST APPROACH TO BRIDGE



PHOTO 6 LOAD POSTING SIGNS ON FARRINGTON HIGHWAY, WEST OF KOWELO AVENUE



PHOTO 7 UPSTREAM EAST APPROACH GUARDRAIL



PHOTO 8 UPSTREAM WEST APPROACH GUARDRAIL



PHOTO 9 DOWNSTREAM EAST APPROACH GUARDRAIL COVERED BY HEAVY VEGETATION



PHOTO 10 DOWNSTREAM WEST APPROACH GUARDRAIL COVERED BY HEAVY VEGETATION



PHOTO 11 METAL GUARDRAIL ATTACHED TO UPSTREAM
CONCRETE BRIDGE RAILING



PHOTO 12 METAL GUARDRAIL ATTACHED TO DOWNSTREAM
CONCRETE BRIDGE RAILING



PHOTO 13 2'X1' DELAMINATION ON CURB AT BASE OF
DOWNSTREAM CONCRETE BRIDGE RAILING, NEAR
WEST END OF BRIDGE



PHOTO 14 WEARING SURFACE



PHOTO 15 LONGITUDINAL CRACK WITH BUILT-UP EFFLORESCENCE (25SF 1120 CS3) ON SLAB SOFFIT, 28' FROM UPSTREAM SIDE



PHOTO 16 LONGITUDINAL CRACK WITH BUILT-UP EFFLORESCENCE (25SF 1120 CS3) ON SLAB SOFFIT, 30' FROM UPSTREAM SIDE



PHOTO 17 LONGITUDINAL CRACK WITH BUILT-UP EFFLORESCENCE (25SF 1120 CS3) ON SLAB SOFFIT, 32' FROM UPSTREAM SIDE



PHOTO 18 LONGITUDINAL CRACK WITH BUILT-UP EFFLORESCENCE (25SF 1120 CS3) ON SLAB SOFFIT, 45' FROM UPSTREAM SIDE



PHOTO 19 PROTRUDING ROOFING PAPER ALONG TOP OF ABUTMENT 1



PHOTO 20 TYPICAL MODERATE WIDTH CRACK (1130 CS2) ON BOTH ABUTMENTS



PHOTO 21 WIDE CRACK (1FT 1130 CS3) ON ABUTMENT 1, 25' FROM UPSTREAM END



PHOTO 22 WIDE CRACK (1FT 1130 CS3) ON ABUTMENT 1, 45' FROM UPSTREAM END



PHOTO 23 STREAM CHANNEL UNDER BRIDGE LOOKING
UPSTREAM, WITH UTILITY PIPE ALONG ABUTMENT 2



PHOTO 24 UPSTREAM CHANNEL WITH HEAVY VEGETATION AND
EXISTING ABANDONED BRIDGE



PHOTO 25 DOWNSTREAM CHANNEL WITH HEAVY VEGETATION