GENERAL NOTES:

REPAIR NOTES:

1 - All deteriorated, damaged, cracked, spalled, honeycombed concrete or concrete over rusted reinforcing bars shall be removed as shown and repaired with hand-placed mortar or shotcrete.

face of existing? concrete

Hatched area denotes approximate damaged area from which loose or unsound concrete has been partially removed.

Limits of concrete removal or concrete patch (see detail this sheet). Apply bonding agent immediately before placing mortar or concrete.

- a Provide min. 2" conc. over reinforcement or welded wire fabric. See specifications for welded wire fabric requirements.
- 3 Reinforcing bars that have rusted more than 25% of their original cross sectional area shall be strengthened as shown on the "Repair Splice Detail," this sheet.
- 4 Efflorescence shall be inspected and repaired as directed by the Engineer.
- 5 The Engineer shall determine all areas to be repaired and the limits of repair at each area.
- 6- Apply Hydrozo Clear 16 Waterproofing or equivalent to repaired areas as approved by the Engineer Application shall be according to the Manufacturer's recommendations.


GENERAL:

- 1 All reinforcing steel to be ASTM AGI5 Grade 40.
- e All welding shall be done in accordance with the current edition of the Reinforcing Steel Welding Code AWS DI.4.


INCIDENTAL ITEMS: The following items shall be considered incidental to the various pay items of repair and will not be paid for separately.

- 1 Bolts and other miscellaneous hardware including hot-dipped zine-coating and welded wire fabric.
- 2 Cleaning of all exposed, corroded reinforcing steel to sound metal.
- 3 Reinforcing bars of repair splice for strengthening corroded bars.
- 4- Furnishing and application of Hydrozo Clear 16 Waterproofing Material.

SYMBOLS:



Spall or unsound surface area.



FED. ROAD STATE

Approx. exist. surface spalls) or unsound concrete removal in sq. ft. areas. See General

Corner spalls or unsound concrete removal

FISCAL SHEET YEAR NO.


PROJ. NO.


HAWAII HAW. 50BC-01-92M 1932 3

TOTAL SHEETS

PLAN OR ELEVATION

Not to Scale






SQUARE

Exist. bar-

REINFORCING TYPICAL BAR


REPAIR SPLICE DETAIL


Not to Scale



Welded wire fabric, 2×2-W1.4×W1.4

and 1/4" of hooked expansion bolts





AT SURFACE

AT FILLET

TYPICAL REPAIRS CONCRETE 5PALLS

Not to Scale

DEPARTMENT OF TRANSPORTATION

STATE OF HAWAII

GENERAL NOTES AND DETAILS

KAUMUALII HIGHWAY REPAIR SPALLS Waimea, Hanapepe, and Lawai Bridges PROJECT NO. 50BC-01-92M Scale: None Date: April 1992

SHEET No. | OF | SHEETS

