

### GENERAL NOTES FOR SPALL REPAIR

- INCIDENTAL ITEMS:** *The following items shall be considered incidental to the various pay items for repairs and will not be paid for separately:*

- REPAIR NOTES:

- 
- Face of existing concrete
- Hatched area denotes approximate damaged area from which loose or unsound concrete has been partially removed.
- Limits of concrete removal or concrete patch (see detail this sheet).

- |                                  |                                    |
|----------------------------------|------------------------------------|
| ORIGINAL PLAN                    | SURVEY PLOTTED BY _____ DATE _____ |
| NOTE BOOK<br>162<br>44-24163-100 | DRAWN BY <u>X</u> _____            |
|                                  | TRACED BY _____                    |
|                                  | DESIGNED BY <u>X</u> _____         |
|                                  | QUANTITIES BY _____                |
|                                  | CHECKED BY _____                   |

SHEET No. 1 OF 2 SHEETS