

DOME SECTION

DETECTABLE WARNING DETAIL

Not to Scale

Edge of Concrete

ENLARGEMENT

SURVEY PLOT
DRAWN BY_
TRACED BY_
DESIGNED BY
QUANTITIES I

ORIGINAL PLAN NOTE BOOK Ke2.janil Skmukulp.dgn

STATE OF HAWAII DEPARTMENT OF TRANSPORTATION

SIDEWALK REPAIR DETAIL

KAUMUALII HIGHWAY Guardrail and Shoulder Improvements

the detectable warning and an adjoining surface, or the detectable warning

4. The material used to provide visual contrast shall be an integral part of the

5. Installation of Detectable warning shall be concidered incidental to sidewalk

shall be "safety yellow".

repair.

detectable warning surface.

FED. AID PROJ. NO.

HAW. | STP-050-1(27)

FISCAL SHEET TOTAL YEAR NO. SHEETS

2005

at Hanapepe Bridge Federal Aid Project No. STP-050-1(27)

Scale: As Noted Date: Nov. 2004

> OF 1 SHEETS SHEET No. 1

> > 18