

$$\begin{aligned} C &= 0 \\ F &= 0 \end{aligned}$$

Exc = 68 C.Y.
Emb = 27 C.Y.

Exc = 78 C.Y.
Emb = 31 C.Y.

$$\begin{aligned}Exc &= 0 \\Emb &= 12 CY.\end{aligned}$$

Exc = 59 C.Y.
Emb = 28 C.Y.

Exc = 77 CY.
Emb = 26 CY.

Exc = 2 C.Y.
Emb = 31 C.Y.

Exc = 35 C.Y.
Emb = 27 C.Y.

Exc = 66 C.Y.
Emb = 17 C.Y.

Exc = 11 C.Y.
Emb = 42 C.Y.

Exc = 10 C.Y.
Emb = 28 C.Y.

Exc = 55 C.Y.
Emb = 21 C.Y.

Exc = 75 C.Y.
Emb = 44 C.Y.

Exc = 5 C.Y.
Emb = 29 C.Y.

Exc = 56 C.Y.
Emb = 29 C.Y.

Exc = 47 CY
Emb = 38 CY