

11 Vapor Management Plan

None of the COCs identified or suspected to be present at the site contain significant volatile constituents that are anticipated to create a soil vapor hazard at the site during construction. Therefore, a vapor management plan is not needed for this C-EHMP. If new information indicates that hazardous soil vapors may be present, then this C-EHMP will be revised and re-submitted to the HEER Office for review and approval at least 90 days prior to conducting soil/groundwater disturbing activities or as soon as the change has been identified.