



TYPICAL SECTION - REPAIR OF WASHED OUT CRM WALL

SCALE: 1" = 2"



TYPICAL SECTION - REPAIR OF UNDERMINED/BROKEN CRM BASE

SCALE: 1" = 2"



DEPARTMENT OF TRANSPORTATION
HIGHWAYS DIVISION

DRAINAGE REPAIRS

ATMILE POST 34.0

(VICINITY AT END OF KEAWA PLACE)

HANA HIGHWAY

EMERGENCY FEDERAL-AID PROJECT

ROADWAY REPAIRS

AT VARIOUS LOCATIONS

FED. AID PROJ. NO. ER-12(5)

SCALE: AS NOTED

DATE: FEBRUARY 2001

SHEET No. 2 OF 2

SHEET No. 2 OF 2 SHEET