



D. MAPS



Map 1 – Culvert M.P. 6.70 (Pali Highway)



Map 2 – Culvert M.P. 1.30 (Kalanianaʻole Highway)



Map 3 – Culvert M.P. 2.40 (Kalanianaʻole Highway)



Legend	
✕	Soil Disturbance Location
☆	Discharge Point
—	Stream
▬	Culvert Repair Location
⊙	Culvert Location (Zoom-Out View)

- Notes**
1. Map projection: WGS 1984 UTM Zone 4N.
 2. Base Map: USGS 1-foot orthoimagery.






Figure 3B
 Discharge Location
 Culvert M.P. 2.40 (Kalanianaʻole Highway)
 State of Hawaii, Department of Transportation
 Culvert Repair at Various Locations
 Oahu, Hawaii


Map 4 – Culvert M.P. 19.06 (Kamehameha Highway)




Map 5 – Culvert M.P. 4.66 (Likelike Highway)




Map 6 – Culvert M.P. 12.56 (H-3 Highway)



Map 7 – Culvert M.P. 14.50 (H-3 Highway)





Map 8 – Culvert M.P. 14.60 (H-3 Highway)