


Appendix **IV**

PHOTOGRAPHIC DOCUMENTATION

Lead-Based Paint



Photograph 1: Yellow paint on fuel station parking bollards
Sample ID 1901-F-L02



Page 1 of 7

May 2022

**Photographic Documentation
Limited Hazardous Materials Survey
Maui Baseyard
Kahului, Maui**

Lead-Containing Paints



Photograph 2: Red paint on fuel tank motor and pipes
Sample ID 1901-F-L05

Lead-Containing Paints



Photograph 3: Brown paint on fuel station canopy pillars
Sample ID 1901-F-L07



Page 3 of 7

May 2022

Photographic Documentation
Limited Hazardous Materials Survey
Maui Baseyard
Kahului, Maui

Lead-Containing Paints



Photograph 4: Off-white paint on maintenance building interior conduit
Sample ID 1901-M-L03



Lead-Containing Paints



Photograph 5: Off-white paint on repair shop interior conduit
Sample ID 1901-R-L02

Lead-Containing Paints



Photograph 6: Grey paint on repair shop exterior conduit and junction box
Sample ID 1901-R-L03

Lead-Containing Paints



Photograph 7: Brown paint on repair shop exterior CMU walls
Sample ID 1901-R-L04