

GEOTECHNICAL ENGINEERING EXPLORATION
KEKAULIKE AVENUE
EMERGENCY REPAIRS AT MILEPOST 8.2
FEDERAL AID PROJECT NO. ER-25(001)
KULA, MAUI, HAWAII
W.O. 8424-00 MARCH 31, 2022

TABLE OF CONTENTS

	Page
SUMMARY OF FINDINGS AND RECOMMENDATIONS.....	iii
1. GENERAL.....	1
1.1 Project Considerations.....	1
1.2 Purpose and Scope	2
2. SITE CHARACTERIZATION.....	4
2.1 Regional Geology	4
2.2 Site Description.....	5
2.3 Subsurface Conditions.....	5
2.4 Seismic Design Considerations	6
2.4.1 Earthquake and Seismicity.....	7
2.4.2 Liquefaction Potential.....	8
2.4.3 Soil Profile Type for Seismic Design	9
3. DISCUSSION AND RECOMMENDATIONS	10
3.1 Segmental Retaining Walls.....	11
3.1.1 Segmental Retaining Wall Foundations	13
3.1.2 Lateral Earth Pressures	14
3.1.3 Reinforced Fill	14
3.1.4 Overall Slope Stability	15
3.2 Retaining Walls.....	15
3.3 Retaining Structure Foundations	16
3.3.1 Lateral Earth Pressures	16
3.3.2 Dynamic Lateral Earth Pressures.....	17
3.3.3 Drainage	17
3.4 Site Grading.....	18
3.4.1 Cut and Fill Slope Design.....	18
3.4.2 Site Preparation	19
3.4.3 Fills and Backfills.....	19
3.4.4 Fill Placement and Compaction Requirements	20
3.4.5 Excavations.....	21
3.5 Design Review.....	21
3.6 Post-Design Services/Services During Construction	21
4. LIMITATIONS.....	23

	Page
CLOSURE.....	25
PLATES	
Project Location Map.....	Plate 1
Site Plan	Plate 2
APPENDIX A	
Field Exploration.....	Pages A-1 and A-2
Soil Log Legend	Plate A-0.1
Soil Classification Log Key	Plate A-0.2
Rock Log Legend	Plate A-0.3
Logs of Borings	Plates A-1.1 thru A-2.2
APPENDIX B	
Laboratory Tests.....	Page B-1
Laboratory Test Data	Plates B-1 thru B-4
APPENDIX C	
Photographs of Core Samples.....	Plates C-1 and C-2