

GEOTECHNICAL ENGINEERING EXPLORATION
FREEWAY MANAGEMENT SYSTEM, PHASE 2
FEDERAL AID PROJECT NO. NH-0300(160)
DISTRICTS OF HONOLULU AND EWA, ISLAND OF OAHU
W.O. 6891-20(A) MARCH 9, 2018

TABLE OF CONTENTS

	Page
SUMMARY OF FINDINGS AND RECOMMENDATIONS.....	iii
1. GENERAL	1
1.1 Introduction	1
1.2 Project Considerations.....	1
1.3 Purpose and Scope	3
2. SITE CHARACTERIZATION.....	5
2.1 Regional Geology	5
2.2 Existing Site Conditions	5
2.2.1 Farrington VMS/Speed Reader Site.....	6
2.2.2 Palailai CCTV Site.....	6
2.2.3 Kualakai CCTV Site	6
2.2.4 H-2 VMS Site	6
2.2.5 Waipio CCTV Site	6
2.2.6 H-2 CCTV Site	7
2.2.7 Kualakai VMS Site	7
2.2.8 Kunia West CCTV Site.....	7
2.2.9 Speed Reader 4 Site.....	7
2.3 Subsurface Conditions.....	7
2.3.1 Farrington VMS/Speed Reader Site.....	8
2.3.2 Palailai CCTV Site.....	8
2.3.3 Kualakai CCTV Site	8
2.3.4 H-2 VMS Site	8
2.3.5 Waipio CCTV Site	8
2.3.6 H-2 CCTV Site	9
2.3.7 Kualakai VMS Site	9
2.3.8 Kunia West CCTV Site.....	9
2.3.9 Speed Reader 4 Site.....	9
3. DISCUSSION AND RECOMMENDATIONS	11
3.1 Drilled Shaft Foundations.....	11
3.1.1 Uplift Load Resistance	13
3.1.2 Lateral Load Resistance	14
3.1.3 Torsional Resistance.....	16
3.1.4 Foundation Settlement.....	16
3.1.5 Drilled Shaft Construction Considerations.....	16

	Page
3.2 Design Review	17
3.3 Construction Observation	18
4. LIMITATIONS.....	19
CLOSURE.....	21
PLATES	
Project Location Map	Plate 1
Site Plans	Plates 2.1 thru 2.9
APPENDIX A	
Field Exploration	Pages A-1 and A-2
Soil Log Legend	Plate A-0.1
Soil Classification Log Key	Plate A-0.2
Rock Log Legend	Plate A-0.3
Logs of Borings	Plates A-1 thru A-9
APPENDIX B	
Laboratory Tests	Page B-1
Laboratory Test Data	Plates B-1 thru B-14