

**GEOTECHNICAL ENGINEERING EXPLORATION
TRAFFIC SIGNAL MODERNIZATION PROJECT
KAHUAPAANI STREET & ULUNE STREET INTERSECTION
HALAWA, OAHU, HAWAII
W.O. 7328-00(A) AUGUST 6, 2019**

TABLE OF CONTENTS

	Page
SUMMARY OF FINDINGS AND RECOMMENDATIONS.....	iii
1. GENERAL	1
1.1 Project Considerations.....	1
1.2 Purpose and Scope	1
2. SITE CHARACTERIZATION.....	4
2.1 Regional Geology	4
2.2 Site Description.....	4
2.3 Subsurface Conditions.....	5
3. DISCUSSION AND RECOMMENDATIONS	7
3.1 Traffic Signal Pole Foundations	7
3.1.1 Lateral Load Resistance.....	10
3.1.2 Foundation Settlements	11
3.1.3 Drilled Shaft Construction Considerations.....	11
3.2 Utility Trench.....	12
3.3 Design Review.....	13
3.4 Post-Design Services/Services During Construction	14
4. LIMITATIONS.....	15
CLOSURE.....	17
PLATES	
Project Location Map.....	Plate 1
Site Plan	Plate 2
APPENDIX A	
Field Exploration.....	Pages A-1 and A-2
Soil Log Legend.....	Plate A-0.1
Soil Classification Log Key	Plate A-0.2
Rock Log Legend	Plate A-0.3
Log of Boring	Plate A-1

	Page
APPENDIX B	
Laboratory Tests.....	Page B-1
Laboratory Test Data.....	Plates B-1 thru B-3
APPENDIX C	
Photograph of Core Samples	Plate C-1