

**GEOTECHNICAL ENGINEERING EXPLORATION
REHABILITATION OF PALI HIGHWAY
WAOKANAKA STREET TO KAMEHAMEHA HIGHWAY
HONOLULU TO KANEOHE, OAHU, HAWAII
W.O. 6782-00(A) FEBRUARY 2, 2015**

TABLE OF CONTENTS

	Page
SUMMARY OF FINDINGS AND RECOMMENDATIONS.....	iii
1. GENERAL.....	1
1.1 Introduction	1
1.2 Project Considerations.....	1
1.3 Purpose and Scope	2
2. SITE CHARACTERIZATION.....	5
2.1 Regional Geology	5
2.2 Existing Site/Pavement Conditions	7
2.2.1 Areas with Minor Distresses.....	8
2.2.2 Areas with Moderate to Severe Distresses	8
2.3 Subsurface Conditions.....	9
2.4 Dynamic Cone Penetration Testing	12
3. DISCUSSION AND RECOMMENDATIONS	14
3.1 Methodology of Pavement Design	16
3.2 Design Traffic Loading Conditions/Traffic Index	16
3.3 Design Subgrade Conditions	17
3.4 Existing Pavement Sections	20
3.5 Rehabilitation of Existing Pavements.....	20
3.6 Rehabilitation of Bridge Deck Pavements.....	21
3.7 Pavement Reconstruction.....	21
3.8 Light Pole Foundations	22
3.9 Surface Drainage	24
3.10 Design Review.....	24
3.11 Construction Monitoring	24
4. LIMITATIONS.....	25
CLOSURE.....	27

TABLE OF CONTENTS

	Page
PLATES	
Project Location Map	Plate 1
General Site Plan	Plate 2
Site Plans	Plates 3.1 thru 3.12
Summary of Dynamic Cone Penetration Test Data	Plates 4.1 thru 4.3
Correlations of Penetration Index and California Bearing Ratio	Plates 5.1 thru 5.3
Summary of Pavement Design Recommendations	Plate 6
Soft Subgrade Stabilization Detail	Plate 7
APPENDIX A	
Field Exploration.....	Page A-1
Soil Log Legend.....	Plate A-0.1
Rock Log Legend	Plate A-0.2
Logs of Borings.....	Plates A-1 thru A-50
APPENDIX B	
Dynamic Cone Penetration Tests	Page B-1
Dynamic Cone Penetration Test Field Logs	Plates B-1 thru B-21
APPENDIX C	
Laboratory Tests.....	Page C-1
Laboratory Test Data.....	Plates C-1 thru C-22
APPENDIX D	
Pavement Design	
Pavement Calculations	Plates D-1 thru D-3
APPENDIX E	
Photographs of AC Cores.....	Plates E-1 thru E-25
APPENDIX F	
Photographs of Roadway Survey	Plates F-1 thru F-5